



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2107199

INV Date 18/10/2021

Reference CC4/LPC20013707/Qga3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SMC 2082E
Insured Veh. SKV 7129X
Claim No. 20/20/20/VP05/023993
Policy No. Z20VP05027548
Accident Date 08/12/2020
Inspection Date 11/12/2020

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555			Ref: CC4/LPC20013707/Qga3q2 Date: 18/10/2021 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKV 7129X	Veh. Inspected	SMC 2082E	
Policy No.	Z20VP05027548	Coverage (\$)	0.00	
Claim No.	20/20/20/VP05/023993	Excess (\$)	0.00	
Assign From	KENNY LIM	Assign Date	10/12/2020	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA HYBRID	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	NHP1707125763	Colour	SILVER	
Odometer	220187 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	WANLI	6 mm	
L/H Front Tyre	185/65 R15	WANLI	6 mm	
R/H Rear Tyre	185/65 R15	WANLI	6 mm	
L/H Rear Tyre	185/65 R15	WANLI	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/12/2020	Inspection Date	11/12/2020	
Survey held at	MY CAR CONSULTANT PTE LTD 53 UBI AVENUE 1 #01-33 PAYA UBI INDUSTRIAL PARK SINGAPORE 408934			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMC 2082E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
2	REAR NUMBER PLATE LAMP @\$65.00	SERVICEABLE	130.00	-
1	REAR NUMBER PLATE TOP GAR	SERVICEABLE	43.50	-
1	REAR BUMPER	TO REPAIR SEE LABOUR	498.20	-
2	REAR BUMPER SIDE RETAINER @\$52.30	SERVICEABLE	104.60	-
2	REAR BUMPER OUTER BRACKET @\$124.00	SERVICEABLE	248.00	-
2	REAR BUMPER INNER BRACKET @\$159.00	SERVICEABLE	318.00	-
1	REAR BUMPER CENTER CAR	CRUMPLED	190.00	190.00
2	REAR BUMPER SIDE GARNISH @\$159.10	SERVICEABLE	318.20	-
1	REAR BUMPER TOWING COVER	SCRATCHED	40.80	40.80
2	REAR BUMPER REFLECTOR @\$69.80	SERVICEABLE	139.60	-
1	TAILGATE	DENTED	1,131.90	1,076.00
2	TAILGATE HINGE @\$112.00	SERVICEABLE	224.00	-
1	TAILGATE LOCK	JAMMED	321.00	321.00
1	TAILGATE LOCK CATCH	SERVICEABLE	52.00	-
1	TAILGATE DETECTOR	SERVICEABLE	297.00	-
1	TAILGATE WEATHERSTRIP	SERVICEABLE	372.30	-
	TAILGATE INNER TRIM BOARD	SERVICEABLE	158.00	-
1	TAILGATE EMBLEM	NECESSARY	67.50	67.50
1	TAILGATE HYBRID LOGO	NECESSARY	65.60	65.60
2	TAILGATE LAMP @\$261.40	SERVICEABLE	522.80	-
1	REAR TAILGATE SWITCH OPENER	SERVICEABLE	212.00	-
1	REAR TAILGATE OPENING PANEL LH BTM	SERVICEABLE	237.00	-
1	REAR WINDSCREEN MOULDING TOP	NECESSARY	64.00	45.00
1	REAR WINDSCREEN MOULDING BTM	NECESSARY	64.00	45.00
1	REAR WINDSCREEN MOULDING LH	NECESSARY	57.00	40.00
1	REAR WINDSCREEN MOULDING RH	NECESSARY	57.00	40.00
1	REAR FENDER INNERSHIELD LH INNER	SERVICEABLE	621.00	-
1	REAR FENDER INNERSHIELD LH OUTER	SERVICEABLE	212.00	-
1	REAR END PANEL INNER	SERVICEABLE	391.00	-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR END PANEL OUTER	TO REPAIR SEE LABOUR	433.60	-
1	REAR END PANEL TOP GAR	SERVICEABLE	147.50	-
1	REAR SPARE TYRE PANEL BOARD	SERVICEABLE	446.70	-
1	REAR SPARE TYRE PANEL BOARD INNER COVER	SERVICEABLE	279.90	-
	LESS 25% DISCOUNT		-2,116.43	-482.73
			6,349.27	1,448.17
	<u>SPECIAL NETT ITEMS</u>			
1	REAR NUMPER PLATE (SN)	SERVICEABLE	50.00	-
10	REAR BUMPER CLIP (SN)	NECESSARY	50.00	30.00
10	TAILGATE INNERTRIM BOARD CLIP (SN)	SERVICEABLE	50.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
1	REAR FENDER INNERSHIELD CLIP (SN)	SERVICEABLE	50.00	-
1	END PANEL SEALANT (SN)	SERVICEABLE	150.00	-
1	REVERSE SENSOR (SN)	SHORTED	250.00	200.00
			680.00	270.00
	<u>LABOUR</u>			
	CHECK WIRING .		200.00	20.00
	R+R RR WINDSCREEN .		150.00	120.00
	R+R RR TAILGATE MECHANISM .		150.00	60.00
	R+R TRIM ,SEAT & UPHOLSTERY .	NOT NECESSARY	300.00	-
	RESET & DIAGNOSE FAULT CODE .	NOT NECESSARY	300.00	-
	KNOCK.INCLUSIVE OF THE REPAIR OF REAR END PANEL OUTER AND REAR BUMPER .		1,200.00	400.00
	SPRAY .		1,200.00	400.00
			3,500.00	1,000.00
GRAND TOTAL			10,529.27	2,718.17

RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			2,150.00
---	--	--	-----------------

Report Ref No. CC4/LPC20013707/Qga3q2

OI SUN PIN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SMC 2082E

INSPECTION





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

