

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013709/KGS3Q2
Date: 03/08/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800057508-01
Claimant Vehicle No :	SKT2583K	Insured Vehicle No :	SLZ8968B
Date of Loss:	09/12/2020	Nature of Claim:	TP
		Claim No:	9703507887SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT2583K		
Make & Model:	VOLVO S60, 1.6 D2 (A)	Engine No:	D4162T3069094
Reg. Date:	28/05/2015 (Man. Year: 2014)	Chassis No:	YV1FS84ABF2348199
Colour:	Metallic Red	Odometer:	46452 km
Engine Capacity:	1560 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/55 R16	Rear Tyre Size:	215/55 R16
Front Left Side:	Hankook 6 mm	Rear Left Side:	Hankook 6 mm
Front Right Side:	Hankook 6 mm	Rear Right Side:	Hankook 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,284.21	6,123.71	4,160.50	40.46
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,650.00	1,860.00	790.00	29.81
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	12,934.21	7,983.71	4,950.50	38.27
Approved Total (Overridden) (S\$)		6,350.00		

(S\$)	12,934.21	6,350.00	6,584.21	50.91
+ GST 7.00/7.00% (S\$)	905.39	444.50	460.89	50.91
Nett Amount (S\$)	13,839.60	6,794.50	7,045.10	50.91
+ Loss of Use (7.0 x S\$50.00/day) (S\$)		350.00		
+ Doc/Search Fee (S\$)		8.00		
Nett Liability (S\$)		7,152.50		

INSPECTION

Date of Assignment: 11/12/2020

Date Inspected: 16/12/2020

Estimated Period of Repair: 6.0 days

Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)
Blk 1019 #01-374/382, Yishun Industrial Park A
Singapore 768761

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR RH DOOR	Bent	2,931.72 FL	*2,931.72 FL
2	1		*REAR RH DOOR FRAME GARNISH	Serviceable	299.25 FL	*- FL
3	1		*REAR RH DOOR INNER RUBBER	Serviceable	289.90 FL	*- FL
4	1		*FRONT RH DOOR	Bent	2,998.10 FL	*2,998.10 FL
5	1		*FRONT RH DOOR FRAME GARNISH	Serviceable	301.20 FL	*- FL
6	1		*REAR RH DOOR INNER RUBBER	Serviceable	290.10 FL	*- FL
7	1		*RH SIDE SKIRT	Dented / Warped	516.19 FL	*516.19 FL
8	1		*REAR RH FENDER	Repair	2,851.02 FL	*- FL
9	1		*REAR WINDSCREEN GLASS MOULDING	Not Necessary	305.90 FL	*- FL
10	1		*REAR WINDSCREEN GLASS GUM	Not Necessary	40.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	10,823.38	6,446.01
- List Item Discount on L Items 5.00/5.00% (\$)	539.17	322.30
Total Parts (\$)	10,284.21	6,123.71

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,200.00	800.00
2	REMOVE & REFIX SEAT ,CARPET ,GARNISH ,ETC	New	120.00	80.00
3	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	0.00
4	PUTTY & RESPRAY ON REAR RH DOOR ,REAR RH FENDER ,RH SIDE SKIRT	New	1,000.00	800.00
5	REMOVE & REFIX REAR & FRT RH DOOR GLASS	New	120.00	120.00
6	RUSTPROOFING	New	90.00	60.00
Gross Labour Cost (S\$)			2,650.00	1,860.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >