

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013713/R1PA3Q2

Date: 28/01/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993844

Claimant
Vehicle No : GBE6905A **Insured Vehicle No :** SLH5772M

Date of Loss: 08/12/2020 Nature of Claim: TP Claim No: 9511721645SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBE6905A		
Make & Model:	FIAT DOBLO, 1.2 D 1.3M (M)	Engine No:	198A30007494202
Reg. Date:	03/03/2016 (Man. Year: 2015)	Chassis No:	ZFA26300006B46392
Colour:	White	Odometer:	117636 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/60 R16C	Rear Tyre Size:	195/60 R16C
Front Left Side:	Nexen 6 mm	Rear Left Side:	Nexen 6 mm
Front Right Side:	Nexen 6 mm	Rear Right Side:	Nexen 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,118.73	3,663.02	1,455.71	28.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,900.00	1,020.00	880.00	46.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,018.73	4,683.02	2,335.71	33.28
Approved Total (Overridden) (\$\$)		3,750.00		
Nett Amount (\$\$)	7,018.73	3,750.00	3,268.73	46.57
+ Loss of Use (4.0 x S\$80.00/day) (\$\$)		320.00		
Nett Liability (\$\$)		4,070.00		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 11/12/2020 Inspected At:

TJ Car Care Services (HQ)
Blk 1010, #01-115, Bukit Merah Lane
3
Singapore 159724

Estimated Period of Repair: 4.0 days

Adjuster: MOHD RASUL

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LH DOOR PANEL	Bent	1,472.00 FL	*1,472.00 FL
2	1		*LH DOOR BADGE -MAXI	Necessary	95.70 FL	*95.70 FL
3	1		*LH DOOR BADGE -DOBLO	Necessary	67.30 FL	*67.30 FL
4	1		*LH DOOR WEATHERSTRIP	Serviceable	286.00 FL	*- FL
5	2		*LH DOOR NUMBER PLATE LAMP	Serviceable	144.60 FL	*- FL
6	1		*LH DOOR LOWER LOCK	Serviceable	158.20 FL	*- FL
7	1		*RH DOOR PANEL	Bent	1,146.30 FL	*1,146.30 FL
8	1		*RH DOOR OUTER GARNISH	Serviceable	132.50 FL	*- FL
9	1		*RH DOOR BADGE -PROFESIONAL	Necessary	71.20 FL	*71.20 FL
10	1		*RH DOOR BADGE -MULTIET	Necessary	52.10 FL	*52.10 FL
11	1		*RH DOOR WEATHERSTRIP	Necessary	202.50 FL	*202.50 FL
12	1		*RH DOOR LOWER LOCK	Bent	158.20 FL	*158.20 FL
13	1		*REAR DOOR LOWER HINGE	Serviceable	97.20 FL	*- FL
14	1		*REAR BUMPER	Deformed	468.50 FL	*468.50 FL
15	1		*REAR BUMPER REINFORCEMENT	Bent	314.00 FL	*314.00 FL
16	2		*REAR BUMPER SIDE HOLDER	Serviceable	205.20 FL	*- FL
17	1		*REAR END GARNISH	Serviceable	268.20 FL	*- FL
18	1		*SET REAR BUMPER SENSOR	Serviceable	280.00 FS	*- FS
19	1		*REAR DOOR STICKER -70KM/H	Necessary	18.00 FS	*10.00 FS
20	1		*REAR DOOR STICKER -6 PAX	Necessary	15.00 FS	*10.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,652.70	4,067.80
- List Item Discount on L Items 10.00/10.00% (\$)	533.97	404.78
Total Parts (\$)	5,118.73	3,663.02

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEWING DAMAGED PARTS KNOCK OUT DENT ON ACCIDENT AFFECTED AREA	New	900.00	500.00
2	SPRAY PAINTING ON ACCIDENT AFFECTED AREA	New	800.00	400.00
3	REMOVE & INSTALL NEW DOORS BODY ATTACHMENT SO AS CARRYOUT NECESSARY REPAIR	New	200.00	120.00
Gross Labour Cost (\$\$)			1,900.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >