

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013715/DVD3Q2

Date: 25/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713MKF
Claimant	Insured Vehicle No :	SLP645M
Vehicle No : SMH7011B	Nature of Claim:	TP
Date of Loss: 08/12/2020	Claim No:	631814

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMH7011B	Engine No:	A25A5084678
Make & Model:	TOYOTA CAMRY, 2.0 (A)	Chassis No:	AXVH701036749
Reg. Date:	30/01/2019 (Man. Year: 2018)	Odometer:	198359 km
Colour:	White		
Engine Capacity:	2487 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/40 R18	Rear Tyre Size:	235/40 R18
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	20,926.64	6,522.94	14,403.70	68.83
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,000.00	2,870.00	3,130.00	52.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	26,926.64	9,392.94	17,533.70	65.12
Approved Total (Overridden) (S\$)		7,500.00		
(S\$)	26,926.64	7,500.00	19,426.64	72.15
+ GST 7.00/7.00% (S\$)	1,884.86	525.00	1,359.86	72.15
Nett Amount (S\$)	28,811.50	8,025.00	20,786.50	72.15

INSPECTION

Date of Assignment:	10/12/2020	
Date Inspected:	11/12/2020 Inspected At:	C. S. Ong Auto Pte Ltd (HQ) BLK 10 ANG MO KIO IND PARK 2A, #02-16 AMK AUTOPOINT Singapore 568047
Estimated Period of Repair:	6.0 days	

Adjuster: BRYAN TANI

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 22 Jan 2021)
Parts: 143	TOYOTA CAMRY 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMH7011B)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent	1,588.20 FL	*1,122.50 FL
2	1		*BOOTLID TOYOTA LOGO	Necessary	98.50 FL	*98.50 FL
3	1		*BOOTLID CENTER GARNISH	Serviceable	395.02 FL	*- FL
4	1		*BOOTLID CAMRY EMBLEM	Necessary	115.20 FL	*115.20 FL
5	1		*BOOTLID HYBRID EMBLEM	Necessary	94.32 FL	*94.32 FL
6	1		*BOOTLID LOCK	Bent / Damaged	329.58 FL	*329.58 FL
7	2		*BOOTLID HINGE LH/RH	Not Necessary	390.00 FL	*- FL
8	1		*BOOTLID SWITCH	Not Necessary	299.82 FL	*- FL
9	1		*BOOTLID WEATHER STRIP	Necessary	310.72 FL	*266.30 FL
10	1		*TAIL LAMP PANEL LH	Dented	312.74 FL	*312.74 FL
11	1		*TAIL LAMP LOWER BRACKET LH	Serviceable	201.50 FL	*- FL
12	1		*REAR BUMPER	Dented	1,490.10 FL	*657.60 FL
13	1		*REAR BUMPER SIDE RETAINER LH/RH	N/S Bent / O/S Not Necessary	190.00 FL	*62.40 FL
14	2		*REAR BUMPER SENSOR	Dislodged (1 PCS ONLY)	590.00 FL	*295.00 FL
15	4		*REAR BUMPER SENSOR HOLDER	Dislodged (1 PCS ONLY)	80.00 FL	*20.00 FL
16	1		*REAR BUMPER WIRE HARNESS	Not Necessary	1,784.00 FL	*- FL
17	1		*REAR BUMPER LOWER LID	Mtg Cracked	988.48 FL	*393.00 FL
18	1		*REAR BUMPER REFLECTOR LH	Cracked	106.92 FL	*106.92 FL
19	1		*REAR REINFORCEMENT BAR	Serviceable	1,004.52 FL	*- FL
20	1		*REAR END PANEL	Dented	1,139.40 FL	*677.50 FL
21	1		*REAR END PANEL TOP GARNISH	Mtg Cracked	329.48 FL	*329.48 FL
22	1		*REAR FENDER LH	Dented	1,980.08 FL	*1,178.10 FL
23	1		*REAR FENDER INNER TRIM LH	Bent / Crumpled	458.26 FL	*458.26 FL
24	1		*REAR FENDER AIR DUCT LH	Deformed	102.39 FL	*102.39 FL
25	1		*REAR FENDER SHIELD LH	Not Necessary	289.30 FL	*- FL
26	1		*SET REAR FENDER SHIELD CLIPS LH	Not Necessary	35.00 FL	*- FL
27	1		*REAR WINDSCREEN MOULDING	Necessary	210.80 FL	*210.80 FL
28	1		*REAR EXHAUST PIPE	Not Necessary	1,730.42 FL	*- FL
29	1		*REAR EXHAUST MOUNTING	Not Necessary	125.00 FL	*- FL
30	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	250.80 FL	*- FL
31	1		*REAR ABSORBER LH	Not Necessary	676.40 FL	*- FL
32	1		*REAR KNUCKLE ARM LH	Not Necessary	859.60 FL	*- FL
33	1		*REAR LOWER ARM	Not Necessary	471.40 FL	*- FL
34	1		*REAR WHEEL BEARING & HUB ASSY LH	Not Necessary	580.90 FL	*- FL
35	1		*BOOTLID LAMP CLIPS	Not Necessary	50.00 FS	*- FS
36	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
37	1		*BOOTLID CENTER GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
39	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
40	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
41	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*REAR END PANEL TOP GARNISH CLIPS	Serviceable	50.00 FS	*- FS
43	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*20.00 FS
44	1		*REAR FENDER INNER TRIM CLIPS	Serviceable	50.00 FS	*- FS
45	1		*REAR NO PLATE & CASING	Not Necessary	100.00 FS	*- FS
46	1		*REAR FENDER TAIL LAMP LH /RH	N/S Cracked / O/S Not Necessary	2,000.00 FS	*700.00 FS
47	1		*BOOTLID LAMP LH/RH	N/S Cracked /O/S Not Necessary	1,600.00 FS	*600.00 FS
48	1		*REAR LH RAYS SPORTS RIM	Not Necessary	1,500.00 FS	*- FS
49	1		*REAR LH TYRE	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$) **25,828.85** **8,230.59**
- List Item Discount on L Items 25.00/25.00% (\$) 4,902.21 1,707.65

Total Parts (\$) **20,926.64** **6,522.94**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	120.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	1,600.00	1,200.00
3	TO REPLACE DAMAGED REAR UNDER-CARRIAGE PARTS	New	400.00	0.00
4	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	1,600.00	1,200.00
5	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
6	TO RNR BOOTLID MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
7	TO RNR REAR BUMPER SENSOR TO FACILITATE REPAIRS	New	150.00	40.00
8	TO RNR REAR WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
9	TO RNR FUEL TANK FILLER PIPE	New	150.00	0.00
10	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIR	New	300.00	60.00
11	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
12	TO CONDUCT COMPUTERIZED 4 WHEEL ALIGNMENT TEST	New	200.00	0.00
13	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$\$)			6,000.00	2,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >