

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013718/GGS3Q2
Date: 09/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800066434
Claimant Vehicle No :	SLX5963U	Insured Vehicle No :	SFW6263B
Date of Loss:	08/12/2020	Nature of Claim:	TP
		Claim No:	1876154209SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLX5963U	Engine No:	1ZR0A50844
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 Elegance (A)	Chassis No:	MR053REH604576409
Reg. Date:	02/04/2018 (Man. Year: 2017)	Odometer:	108974 km
Colour:	White		
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,365.60	1,831.65	2,533.95	58.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,985.00	1,130.00	855.00	43.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,350.60	2,961.65	3,388.95	53.36
Approved Total (Overridden) (S\$)		2,350.00		

(S\$)	6,350.60	2,350.00	4,000.60	63.00
+ GST 7.00/7.00% (S\$)	444.54	164.50	280.04	63.00
Nett Amount (S\$)	6,795.14	2,514.50	4,280.64	63.00
+ Loss of Use (4.0 x S\$50.00/day) (S\$)		200.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,716.50		

INSPECTION

Date of Assignment: 11/12/2020

Date Inspected: 15/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

S & H Motor Pte Ltd (Sin Ming)
 160 Sin Ming Drive #07-02, Sin Ming AutoCity
 Singapore 575722

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Repair	725.00 FL	*- FL
2	1		*REAR TAILGATE EMBLEM	Necessary	61.90 FL	*61.90 FL
3	1		*REAR TAILGATE BADGE COROLLA	Necessary	61.90 FL	*61.90 FL
4	1		*REAR TAILGATE BADGE ALTIS	Necessary	61.70 FL	*61.70 FL
5	1		*RH TAILGATE INNER TAIL LAMP	Scratched	270.10 FL	*270.10 FL
6	1		*LH TAILGATE INNER TAIL LAMP	Not Necessary	270.10 FL	*- FL
7	1		*REAR TAILGATE INNER LOCK	Serviceable	352.00 FL	*- FL
8	1		*RH TAILGATE HINGE	Repair	70.70 FL	*- FL
9	1		*RH OUTER TAILLAMP	Scratched	379.65 FL	*379.65 FL
10	1		*LH OUTER TAILLAMP	Cracked	379.65 FL	*379.65 FL
11	1		*REAR BUMPER	Deformed	480.50 FL	*480.50 FL
12	1		*REAR BUMPER CLIPS	Necessary	32.00 FL	*32.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	386.00 FL	*386.00 FL
14	1		*RH BUMPER RETAINER	Deformed	91.70 FL	*91.70 FL
15	1		*RH BUMPER BRACKET	Not Necessary	91.70 FL	*- FL
16	1		*REAR END PANEL	Repair	645.30 FL	*- FL
17	1		*REAR END PANEL TOP TRIM	Deformed	197.10 FL	*197.10 FL
18	1		*REAR TAILGATE CAMERA	Not Necessary	380.00 FS	*- FS
19	1		*REAR BUMPER PARKING SENSOR	Not Necessary	260.00 FS	*- FS
20	1		*REAR BUMPER STICKER	Cut	80.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,277.00	2,432.20
- List Item Discount on L Items 20.00/25.00% (\$\$)	911.40	600.55
Total Parts (\$\$)	4,365.60	1,831.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO DISCONNECT WIRE HARNESS TO FACILITATE REPAIRS AND CHECK FOR DAMAGE AND RECONNECT WIRING SYSTEM AND CHECK FOR FULL FUNCTIONALITY .TO FOCUS TAILLAMP	New	35.00	30.00
2	TO REMOVE REAR DAMAGED PARTS ,TO JACK OUT REAR END PANEL ,REAR FLOOR PANEL AND CUT OUT DAMAGED PARTS ,TO REWELD ,RESHAPE AND REPAIR REAR END PANEL ,RH REAR FENDER ,LH REAR FENDER ,TAILGATE ,REAR BUMPER TO STRAIGHTEN CHASSIS MEMBER AND ADJUST BODY PANEL ALIGNMENT	New	750.00	400.00
3	TO SPRAY PAINT AFFECTED REAR AND INNER DAMAGED PORTION INCLUSIVE OF PREPARATORY WORKS AND MATERIAL	New	1,100.00	700.00
4	TO APPLY ANTI-CORROSION TUFF KOTE	New	100.00	0.00
Gross Labour Cost (S\$)			1,985.00	1,130.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >