

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013722/KGS3Q2

Date: 16/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900235347

Claimant
Vehicle No : SLE2803T **Insured Vehicle No :** SMP9690K

Date of Loss: 07/12/2020 Nature of Claim: TP Claim No: 3548075403SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLE2803T	Engine No:	G4FGGU158671
Make & Model:	HYUNDAI ELANTRA, 1.6 AD GLS (A)	Chassis No:	KMHD841CMHU144051
Reg. Date:	15/07/2016 (Man. Year: 2016)	Odometer:	72446 km
Colour:	Metallic Red		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Continental 9 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Continental 9 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,059.84	859.60	200.24	18.89
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,170.00	620.00	550.00	47.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,229.84	1,479.60	750.24	33.65
+ GST 7.00/7.00% (S\$)	156.09	103.57	52.52	33.65
Nett Amount (S\$)	2,385.93	1,583.17	802.76	33.65
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		1,735.17		

INSPECTION

Date of Assignment: 11/12/2020

Date Inspected: 14/12/2020 Inspected At:

Ah Lim Motor Company (Sin Ming)
176 Sin Ming Drive #05-12, Sin Ming
AutoCare
Singapore 575721

Estimated Period of Repair: 3.0 days

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	459.40 FL	*459.40 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	480.20 FL	*480.20 FL
3	10		*REAR BUMPER CLIP	Necessary	60.00 FL	*60.00 FL
4	1		*REAR BUMPER LOWER GARNISH	Serviceable	250.30 FL	*- FL
5	1		*REAR REFLECTOR LH	Cracked	45.80 FL	*45.80 FL
6	1		*REAR CENTRE BADGE	Necessary	29.10 FL	*29.10 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	1,324.80	1,074.50
- List Item Discount on L Items 20.00/20.00% (S\$)	264.96	214.90
Total Parts (S\$)	1,059.84	859.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING AND REINSTALL REVERSE SENSOR	New	20.00	20.00
2	TO DISMANTLE AND INSTALL DAMAGE PARTS ,TO KNOCK AND REPAIR REAR BOOT LID AND REFIT LISTED PARTS BACK SAME	New	500.00	200.00
3	TO SPRAY REAR BOOT LID ,REAR BUMPER ,REAR BUMPER REINFORCEMENT	New	650.00	400.00
Gross Labour Cost (\$\$)			1,170.00	620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >