

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG20013724/R1TD3E2

**Date:** 15/09/2021

### REFERENCE

|                   |             |                  |            |           |              |
|-------------------|-------------|------------------|------------|-----------|--------------|
| Insured/Claimant: | LUO WUQIONG | Policy No:       | 2070125657 |           |              |
| Date of Loss:     | 07/12/2020  | Nature of Claim: | OD         | Claim No: | 4831747708SG |

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                      |             |                   |
|-----------------------------|--------------------------------------|-------------|-------------------|
| Reg No:                     | SMU6923H                             |             |                   |
| Make & Model:               | AUDI Q2, 999cc 1.0 TFSI S TRONIC (A) | Engine No:  | CHZC33089         |
| Reg. Date:                  | 25/08/2020 (Man. Year: 2019)         | Chassis No: | WAUZZZGA7KA084229 |
| Colour:                     | Grey                                 | Odometer:   | 1937 km           |
| Engine Capacity:            | 999 cc                               |             |                   |
| Market Value/New Car Price: | S\$110,000.00                        |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price           |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 215/60 R16       | Rear Tyre Size:  | 215/60 R16       |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre tread depth

| COST OF CLAIMS                      | Repairer's        | Adjuster's       | Difference       | Diff %       |
|-------------------------------------|-------------------|------------------|------------------|--------------|
| Parts                               | 77,853.50         | 52,988.56        | 24,864.94        | 31.94        |
| Miscellaneous Items                 | 0.00              | 0.00             | 0.00             |              |
| Labour                              | 37,444.00         | 20,194.00        | 17,250.00        | 46.07        |
| Paintwork Labour                    | 0.00              | 0.00             | 0.00             |              |
| Towing                              | 0.00              | 0.00             | 0.00             |              |
| <b>Calculated Gross Total (S\$)</b> | <b>115,297.50</b> | <b>73,182.56</b> | <b>42,114.94</b> | <b>36.53</b> |
| <b>- Excess (S\$)</b>               | <b>400.00</b>     | <b>400.00</b>    | <b>0.00</b>      | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>114,897.50</b> | <b>72,782.56</b> | <b>42,114.94</b> | <b>36.65</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>8,042.83</b>   | <b>5,094.78</b>  | <b>2,948.05</b>  | <b>36.65</b> |
| <b>Nett Amount (S\$)</b>            | <b>122,940.33</b> | <b>77,877.34</b> | <b>45,062.99</b> | <b>36.65</b> |

### INSPECTION

Date of Assignment: 11/12/2020

Date Inspected: 09/12/2020

Estimated Period of Repair: 28.0 days

Premium Automobiles Pte Ltd  
24 Benoi Sector  
Singapore 629857

**Adjuster:** MOHD RASUL

**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                     | Condition                  | Repairer's  | Amount       |
|-----|-----|----------|---|----------------------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                                   | Torn                       | 1,854.00 FS | *1,482.00 FS |
| 2   | 1   |          | *FRONT BUMPER FIXING PARTS                      | Necessary                  | 343.00 FS   | *154.35 FS   |
| 3   | 1   |          | *FRONT BUMPER GRILLE - CENTRE                   | Cracked                    | 195.00 FS   | *155.60 FS   |
| 4   | 2   |          | *FRONT BUMPER AIR GUIDE GRILLE - LH / RH        | Missing                    | 334.00 FS   | *267.20 FS   |
| 5   | 2   |          | *FRONT BUMPER END CAP - LH / RH                 | Missing                    | 68.00 FS    | *55.44 FS    |
| 6   | 1   |          | *FRONT BUMPER SPOILER                           | Missing                    | 296.00 FS   | *236.40 FS   |
| 7   | 1   |          | *FRONT BUMPER CLOSING ELEMENT                   | Deformed                   | 154.00 FS   | *122.80 FS   |
| 8   | 2   |          | *WHEEL SPOILER - LH / RH                        | Cracked                    | 68.00 FS    | *53.44 FS    |
| 9   | 1   |          | *FRONT BUMPER ADAPTER - LH                      | Broken                     | 35.00 FS    | *28.00 FS    |
| 10  | 1   |          | *FRONT BUMPER ADAPTER - RH                      | Missing                    | 42.00 FS    | *33.20 FS    |
| 11  | 1   |          | *RADIATOR GRILLE                                | Cracked                    | 1,395.00 FS | *1,116.00 FS |
| 12  | 1   |          | *RADIATOR GRILLE STRIKER PLATE                  | Cracked                    | 123.00 FS   | *98.00 FS    |
| 13  | 1   |          | *FRONT BUMPER CARRIER                           | Bent                       | 679.00 FS   | *543.20 FS   |
| 14  | 1   |          | *FRONT BUMPER FOAM FILLER PIECE                 | Cracked                    | 77.00 FS    | *61.20 FS    |
| 15  | 2   |          | *FRONT BUMPER GUIDE SECTION - LH / RH           | Missing                    | 70.00 FS    | *56.00 FS    |
| 16  | 1   |          | *FRONT BUMPER TOP COVER                         | Deformed                   | 99.00 FS    | *79.04 FS    |
| 17  | 1   |          | *CAUTION SIGN STICKER                           | Necessary                  | 14.00 FS    | *10.80 FS    |
| 18  | 1   |          | *AIRCON STICKER                                 | Necessary                  | 8.00 FS     | *5.68 FS     |
| 19  | 1   |          | *HORN - LH LOW TONE                             | Broken                     | 283.00 FS   | *226.00 FS   |
| 20  | 1   |          | *SIGNAL HORN - RH HIGH TONE                     | Serviceable                | 180.00 FS   | *- FS        |
| 21  | 1   |          | *SPRING SHACKLE - LH / RH                       | N/S Bent / O/S Serviceable | 62.00 FS    | *24.48 FS    |
| 22  | 2   |          | *FRONT FENDER - LH / RH                         | Bent                       | 2,268.00 FS | *1,814.40 FS |
| 23  | 1   |          | *FRONT FENDER ATTACHMENT PARTS                  | Not Necessary              | 40.00 FS    | *- FS        |
| 24  | 2   |          | *FRONT FENDER BRACKET - LH / RH INNER           | Necessary                  | 32.00 FS    | *24.32 FS    |
| 25  | 2   |          | *FRONT FENDER BRACKET - LH / RH OUTER           | Necessary                  | 94.00 FS    | *74.56 FS    |
| 26  | 2   |          | *FRONT FENDER MIDDLE BRACKET - LH / RH          | Necessary                  | 32.00 FS    | *24.32 FS    |
| 27  | 2   |          | *FRONT FENDER BRACE - LH / RH                   | Bent                       | 74.00 FS    | *57.76 FS    |
| 28  | 1   |          | *FRONT FENDER BRACKET - LH / RH                 | N/S Bent / O/S Serviceable | 46.00 FS    | *17.92 FS    |
| 29  | 2   |          | *WHEEL HOUSING LINER - LH / RH                  | Broken                     | 388.00 FS   | *309.60 FS   |
| 30  | 1   |          | *WHEEL HOUSING LINER ATTACHMENT PARTS           | Serviceable                | 57.00 FS    | *- FS        |
| 31  | 1   |          | *BONNET   | Bent                       | 2,757.00 FS | *2,205.60 FS |
| 32  | 1   |          | *BONNET ATTACHMENT PARTS                        | Not Necessary              | 163.00 FS   | *- FS        |
| 33  | 2   |          | *BONNET LID HINGE - LH / RH                     | Bent                       | 122.00 FS   | *96.48 FS    |
| 34  | 1   |          | *BONNET GAS FILLED STRUT                        | Serviceable                | 101.00 FS   | *- FS        |
| 35  | 2   |          | *BONNET STRIKER - LH / RH                       | Bent                       | 218.00 FS   | *173.60 FS   |
| 36  | 1   |          | *BONNET SOUND ABSORBER                          | Deformed                   | 217.00 FS   | *173.20 FS   |
| 37  | 1   |          | *BONNET IMPACT PROTECTION - CENTRE              | Necessary                  | 30.00 FS    | *23.36 FS    |
| 38  | 1   |          | *BONNET IMPACT PROTECTION - LH                  | Necessary                  | 30.00 FS    | *23.76 FS    |
| 39  | 1   |          | *BONNET IMPACT PROTECTION - RH                  | Necessary                  | 30.00 FS    | *23.36 FS    |
| 40  | 2   |          | *FRONT FENDER TOP SUPPORT OUTER COVER - LH / RH | N/S Cut / O/S Scratched    | 82.00 FS    | *64.32 FS    |
| 41  | 2   |          | *FRONT FENDER TOP SUPPORT INNER COVER - LH / RH | Not Necessary              | 32.00 FS    | *- FS        |
| 42  | 1   |          | *PLENUM CHAMBER COVER                           | Cut                        | 156.00 FS   | *124.40 FS   |
| 43  | 2   |          | *BONNET LID LOCK                                | Cracked                    | 423.00 FS   | *338.40 FS   |
| 44  | 1   |          | *BONNET BOWDEN CABLE - CENTRE                   | Cut                        | 57.00 FS    | *45.52 FS    |
| 45  | 1   |          | *BONNET LID LOCK CABLE                          | Cut                        | 73.00 FS    | *57.92 FS    |
| 46  | 1   |          | *BONNET RELEASE ELEMENT                         | Missing                    | 57.00 FS    | *45.52 FS    |
| 47  | 2   |          | *BONNET BOWDEN CABLE - LH / RH                  | Cut                        | 114.00 FS   | *91.04 FS    |
| 48  | 1   |          | *BONNET RELEASE LEVER                           | Missing                    | 13.00 FS    | *10.08 FS    |
| 49  | 2   |          | *HEADLIGHT MOUNTING - LH / RH                   | Cracked                    | 234.00 FS   | *187.20 FS   |
| 50  | 2   |          | *LED HEADLIGHT - LH / RH                        | Cracked                    | 9,718.00 FS | *7,774.40 FS |
| 51  | 2   |          | *MAIN LIGHT ELECTRONICS POWER MODULE - LH / RH  | Shorted                    | 1,498.00 FS | *606.40 FS   |
| 52  | 2   |          | *LIGHT CONTROL SYSTEM CONTROL UNIT              | Not Necessary              | 1,102.00 FS | *- FS        |

Report was unsubmitted during this print-out.

| No. | Qty | Part No. | Particulars                          | Condition                    | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------|------------------------------|-------------|--------------|
| 53  | 2   |          | *LED WITH HEAT SINK - LH / RH        | Serviceable                  | 1,450.00 FS | *- FS        |
| 54  | 1   |          | *HEADLIGHT HOSE - LH / RH            | N/S Cut / O/S<br>Serviceable | 58.00 FS    | *23.04 FS    |
| 55  | 2   |          | *LIFT CYLINDER - LH / RH             | Cracked                      | 282.00 FS   | *112.40 FS   |
| 56  | 1   |          | *LIFT CYLINDER HOSE                  | Torn                         | 175.00 FS   | *140.00 FS   |
| 57  | 1   |          | *HEADLIGHT WASHER PUMP               | Serviceable                  | 151.00 FS   | *- FS        |
| 58  | 1   |          | *WINDSCREEN WASHER SYSTEM PUMP       | Serviceable                  | 121.00 FS   | *- FS        |
| 59  | 1   |          | *WASH WATER RESERVOIR                | Deformed                     | 173.00 FS   | *138.40 FS   |
| 60  | 1   |          | *LOCK CARRIER                        | Cracked                      | 983.00 FS   | *786.40 FS   |
| 61  | 1   |          | *AIRCON CONDENSER                    | Bent                         | 545.00 FS   | *436.00 FS   |
| 62  | 1   |          | *REFRIGERANT LINE                    | Bent                         | 619.00 FS   | *495.20 FS   |
| 63  | 1   |          | *REFRIGERANT LINE                    | Bent                         | 476.00 FS   | *380.40 FS   |
| 64  | 1   |          | *REFRIGERANT LINE                    | Bent                         | 476.00 FS   | *380.40 FS   |
| 65  | 1   |          | *AIRCON REFRIGERANT LINE BRACKET     | Cracked                      | 26.00 FS    | *20.24 FS    |
| 66  | 1   |          | *AIRCON REFRIGERANT LINE CLAMP       | Not Necessary                | 29.00 FS    | *- FS        |
| 67  | 1   |          | *EXTERNAL TEMPERATURE SENSOR         | Missing                      | 56.00 FS    | *44.32 FS    |
| 68  | 1   |          | *CHARGE AIR COOLER                   | Bent                         | 695.00 FS   | *555.60 FS   |
| 69  | 1   |          | *ACTIVATED CHARCOAL CONTAINER        | Not Necessary                | 305.00 FS   | *- FS        |
| 70  | 1   |          | *RADIATOR                            | Bent                         | 941.00 FS   | *752.80 FS   |
| 71  | 1   |          | *ADDITIONAL RADIATOR                 | Bent                         | 859.00 FS   | *687.20 FS   |
| 72  | 2   |          | *RADIATOR SEALING STRIP - LH / RH    | Cut                          | 36.00 FS    | *27.68 FS    |
| 73  | 1   |          | *RADIATOR BRACKET - UPPER            | Missing                      | 40.00 FS    | *32.00 FS    |
| 74  | 1   |          | *READY MIX COOLANT                   | Necessary                    | 177.00 FS   | *141.44 FS   |
| 75  | 1   |          | *RADIATOR FAN                        | Broken                       | 1,170.00 FS | *936.00 FS   |
| 76  | 1   |          | *RADIATOR FAN                        | Not Necessary                | 1,191.00 FS | *- FS        |
| 77  | 2   |          | *RADIATOR AIR GUIDE - LH / RH        | Cracked                      | 60.00 FS    | *47.84 FS    |
| 78  | 1   |          | *RADIATOR AIR GUIDE - UPPER CENTRE   | Cracked                      | 22.00 FS    | *17.04 FS    |
| 79  | 1   |          | *RADIATOR HOSE                       | Cracked                      | 241.00 FS   | *192.80 FS   |
| 80  | 1   |          | *AIR INTAKE AIR GUIDE - OUTER LOWER  | Cracked                      | 54.00 FS    | *43.20 FS    |
| 81  | 1   |          | *AIR INTAKE COVER                    | Cracked                      | 40.50 FS    | *32.40 FS    |
| 82  | 1   |          | *AIR INTAKE AIR GUIDE HOSE           | Cut                          | 64.00 FS    | *50.80 FS    |
| 83  | 1   |          | *AIR INTAKE AIR GUIDE - UPPER        | Cracked                      | 19.00 FS    | *14.96 FS    |
| 84  | 1   |          | *AIR INTAKE WATER DRAINAGE HOSE      | Cut                          | 32.00 FS    | *25.12 FS    |
| 85  | 1   |          | *AIR INTAKE MANIFOLD - OUTER         | Serviceable                  | 134.00 FS   | *- FS        |
| 86  | 1   |          | *AIR INTAKE AIR FILTER               | Serviceable                  | 267.00 FS   | *- FS        |
| 87  | 1   |          | *AIR INTAKE MANIFOLD - INNER         | Deformed                     | 606.00 FS   | *484.80 FS   |
| 88  | 1   |          | *THROTTLE VALVE CONTROL ELEMENT      | Serviceable                  | 1,006.00 FS | *- FS        |
| 89  | 2   |          | *FRONT WHEEL COVER - LH / RH         | Necessary                    | 636.00 FS   | *508.80 FS   |
| 90  | 1   |          | *STEERING WHEEL AIRBAG               | Activated                    | 3,490.00 FS | *2,792.00 FS |
| 91  | 1   |          | *AIRBAG UNIT                         | Activated                    | 4,324.00 FS | *3,459.20 FS |
| 92  | 2   |          | *HEAD AIRBAG UNIT - LH / RH          | Activated                    | 2,854.00 FS | *2,283.20 FS |
| 93  | 1   |          | *AIRBAG CONTROL UNIT                 | Activated                    | 1,643.00 FS | *1,314.40 FS |
| 94  | 1   |          | *STEERING WHEEL                      | Deformed                     | 2,000.00 FS | *1,600.00 FS |
| 95  | 1   |          | *DASHBOARD                           | Torn                         | 4,211.00 FS | *3,368.80 FS |
| 96  | 2   |          | *SEAT BELT - LH / RH                 | Activated                    | 2,068.00 FS | *1,654.40 FS |
| 97  | 2   |          | *SEATBELT HEIGHT ADJUSTER            | Serviceable                  | 322.00 FS   | *- FS        |
| 98  | 1   |          | *MOULDED HEADLINER                   | Deformed                     | 1,961.00 FS | *1,568.80 FS |
| 99  | 2   |          | *A-PILLAR TRIM - LH / RH             | Cut                          | 318.00 FS   | *253.60 FS   |
| 100 | 2   |          | *B-PILLAR TRIM - LH / RH UPPER       | Serviceable                  | 370.00 FS   | *- FS        |
| 101 | 2   |          | *C-PILLAR TRIM - LH / RH             | Cracked                      | 180.00 FS   | *143.52 FS   |
| 102 | 2   |          | *FRONT GRAB HANDLE                   | Broken                       | 279.00 FS   | *223.20 FS   |
| 103 | 2   |          | *AIRBAG CRASH SENSOR                 | Activated                    | 778.00 FS   | *622.40 FS   |
| 104 | 1   |          | *CHASSIS FRAME COVER PLATE - LH / RH | N/S Bent                     | 182.00 FS   | *75.60 FS    |
| 105 | 2   |          | *FRONT FENDER TOP SUPPORT - LH / RH  | Serviceable                  | 68.00 FS    | *- FS        |
| 106 | 1   |          | *ENGINE MOUNTING                     | Distorted                    | 246.00 FS   | *196.80 FS   |
| 107 | 1   |          | *GEARBOX MOUNTING                    | Serviceable                  | 249.00 FS   | *- FS        |
| 108 | 1   |          | *MECHATRONIC WITH SOFTWARE           | Dented                       | 4,008.00 FS | *3,206.40 FS |
| 109 | 1   |          | *FRONT WINDSCREEN                    | Cracked                      | 990.00 FS   | *791.60 FS   |
| 110 | 1   |          | *RAIN SENSOR GEL FOIL                | Necessary                    | 132.00 FS   | *105.20 FS   |

| No. | Qty | Part No. | Particulars  | Condition     | Repairer's  | Amount     |
|-----|-----|----------|--|---------------|-------------|------------|
| 111 | 1   |          | <b>*RAIN SENSOR RETAINING SPRING</b>   | Necessary     | 20.00 FS    | *16.00 FS  |
| 112 | 1   |          | <b>*PRIMER</b>   | Necessary     | 19.00 FS    | *14.96 FS  |
| 113 | 1   |          | <b>*AIRCON COMPRESSOR</b>  | Serviceable   | 2,136.00 FS | *- FS      |
| 114 | 1   |          | <b>*SOOLANT COMPRESSON OIL</b>   | Not Necessary | 310.00 FS   | *- FS      |
| 115 | 1   |          | <b>*POLY-V-BELT</b>  | Serviceable   | 47.00 FS    | *- FS      |
| 116 | 1   |          | <b>*NOISE INSULATION</b>   | Broken        | 264.00 FS   | *210.80 FS |
| 117 | 1   |          | <b>*FRONT WINDSCREEN SEALANT</b>   | Necessary     | 200.00 FS   | *200.00 FS |
| 118 | 1   |          | <b>*STONE CHIP</b>   | Not Necessary | 180.00 FS   | *- FS      |
| 119 | 1   |          | <b>*CAVITY WAX</b>   | Not Necessary | 140.00 FS   | *- FS      |
| 120 | 1   |          | <b>*ACRYLIC SEALANT</b>  | Necessary     | 180.00 FS   | *180.00 FS |
| 121 | 1   |          | <b>*FRONT NO PLATE</b>   | Bent          | 60.00 FS    | *60.00 FS  |
| 122 | 1   |          | <b>*SUNDRIES</b>   | Necessary     | 500.00 FS   | *128.29 FS |
| 123 | 1   |          | <b>*OIL SEPARATOR</b><br>(Supplementary)   | Cut           | 107.00 FS   | *85.60 FS  |
| 124 | 1   |          | <b>*OIL FILTER</b><br>(Supplementary)  | Bent          | 25.00 FS    | *19.68 FS  |
| 125 | 1   |          | <b>*OIL SUMP COVER</b><br>(Supplementary)  | Broken        | 14.00 FS    | *10.64 FS  |
| 126 | 1   |          | <b>*OIL SUMP VENT HOSE</b><br>(Supplementary)                                    | Cut           | 34.00 FS    | *26.88 FS  |
| 127 | 1   |          | <b>*COOLANT PUMP</b><br>(Supplementary)  | Broken        | 368.00 FS   | *294.40 FS |
| 128 | 1   |          | <b>*COOLANT HOSE WITH QUICK RELEASE COUPLING LOWER</b><br>(Supplementary)        | Cut           | 130.00 FS   | *103.60 FS |
| 129 | 1   |          | <b>*COOLANT HOSE WITH QUICK RELEASE COUPLING FRONT</b><br>(Supplementary)        | Cut           | 241.00 FS   | *192.80 FS |
| 130 | 1   |          | <b>*RADIATOR BRACKET UPPER</b><br>(Supplementary)                                | Necessary     | 79.00 FS    | *62.88 FS  |
| 131 | 1   |          | <b>*RADIATOR LOWER BUSH</b><br>(Supplementary)                                   | Necessary     | 19.00 FS    | *14.72 FS  |
| 132 | 1   |          | <b>*CHARGED AIR COOLER SEALS</b><br>(Supplementary)                              | Necessary     | 26.00 FS    | *20.64 FS  |
| 133 | 1   |          | <b>*COOLANT PIPE</b><br>(Supplementary)  | Scratched     | 29.00 FS    | *22.80 FS  |
| 134 | 1   |          | <b>*FLAT CONTACT HOUSING 2 PIN</b><br>(Supplementary)                            | Broken        | 17.00 FS    | *13.28 FS  |
| 135 | 1   |          | <b>*VACUUM HOSE WITH NON RETURN VALVE AND PRESSURE SENSOR</b><br>(Supplementary) | Cracked       | 368.00 FS   | *294.40 FS |
| 136 | 1   |          | <b>*SET OF AERODYNAMIC WIPER BLADES</b><br>(Supplementary)                       | Cut           | 87.00 FS    | *69.12 FS  |
| 137 | 1   |          | <b>*WIRING SET FOR THREE PHRASE ALTERNATOR</b><br>(Supplementary)                | Torn          | 215.00 FS   | *172.00 FS |
| 138 | 1   |          | <b>*FLAT CONTACT HOUSING 25 PIN</b><br>(Supplementary)                           | Necessary     | 125.00 FS   | *99.60 FS  |
| 139 | 1   |          | <b>*TRANSMISSION FLUID 1.0L</b><br>(Supplementary)                               | Necessary     | 120.00 FS   | *96.00 FS  |
| 140 | 1   |          | <b>*WIRING SET FOR ELECTRO MECHANICAL POWER STEERING</b><br>(Supplementary)      | Crushed       | 178.00 FS   | *142.40 FS |
| 141 | 1   |          | <b>*HEADLIGHT COMPENSATING PIECE</b><br>(Supplementary)                          | Necessary     | 90.00 FS    | *74.40 FS  |

F=Franchise part. S=SpcNett.

**Total Parts (\$\$) 77,853.50 52,988.56**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars   | Lab.Type | Repairer's | Amount   |
|---------------------|---|----------|------------|----------|
| <b>Labour Items</b> |   |          |            |          |
| 1                   | TO TOW AND RECOVER VEHICLE FROM SCENE OF ACCIDENT   | New      | 280.00     | 0.00     |
| 2                   | TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER  | New      | 800.00     | 800.00   |
| 3                   | TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY   | New      | 360.00     | 360.00   |
| 4                   | TO REMOVE AND RENEW AIRCON CONDENSER, RADIATOR AND ADDITIONAL RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS  | New      | 1,400.00   | 1,400.00 |
| 5                   | TO RENEW FRONT WINDSCREEN   | New      | 480.00     | 480.00   |
| 6                   | TO INSTALL SOLAR FILM FOR FRONT WINDSCREEN  | New      | 400.00     | 400.00   |
| 7                   | TO CARRY OUT WATER SEEPAGE TEST ON FRONT WINDSCREEN   | New      | 200.00     | 150.00   |
| 8                   | TO REMOVE AND RENEW FRONT WINDSCREEN RAIN SENSOR FOIL AND RESET SYSTEM  | New      | 300.00     | 300.00   |
| 9                   | TO REMOVE CENTRE CONSOLE, INSTRUMENT PANELS AND CLUSTERS. RENEW DASHBOARD, BOTH FRONTAL AIRBAGS, SLIP RING. TRANSFER OLD FITTINGS. RENEW SEAT BELTS AND CONTROL UNIT, PILLAR TRIMS, ROOF LINING AND BOTH CURTAIN AIR BAGS   | New      | 3,600.00   | 3,600.00 |
| 10                  | TO REMOVE AND REINSTALL ENGINE ASSY WITH GEARBOX ASSY TO FACILITATE CAR O-LINER REPAIRS   | New      | 2,800.00   | 0.00     |
| 11                  | TO REMOVE AND REINSTALL FRONT SUSPENSION ASSY WITH SUBFRAME TO FACILITATE CAR O-LINER REPAIRS. INSPECT FOR DAMAGES AND RENEW IF NECESSARY   | New      | 2,400.00   | 0.00     |
| 12                  | TO PLACE VEHICLE ON CAR O-LINER   | New      | 2,400.00   | 2,400.00 |
| 13                  | TO RENEW GEARBOX MECHATRONIC AND CARRY OUT ADAPTATION   | New      | 980.00     | 980.00   |
| 14                  | TO DISMANTLE FRONT BUMPER, BONNET, BOTH FRONT FENDERS, BOTH HEADLIGHTS. TO CUT OUT AND WELD BOTH FRONT FENDER TOP SUPPORT. TO REPAIR RHS UPPER A-PILLAR, ALIGN BOTH FRONT CHASSIS FRAMES TO SPECIFICATION OF ORIGIN. RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | New      | 12,800.00  | 5,000.00 |
| 15                  | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, RHS UPPER A-PILLAR AND BOTH FRONT FENDER TOP SUPPORTS. TO CARRY OUT JOINT SEALANT WORK AND STONE CHIP TREATMENT  | New      | 6,900.00   | 3,460.00 |
| 16                  | TO CARRY OUT PRE AND POST REPAIR WHEEL ALIGNMENT CHECK  | New      | 480.00     | 0.00     |
| 17                  | TO CARRY OUT PRE AND POST REPAIR DIAGNOSTIC CHECK   | New      | 384.00     | 384.00   |
| 18                  | TO RENEW ENGINE COMPONENTS AND WIRING<br>(Supplementary)  | New      | 480.00     | 480.00   |

**Gross Labour Cost (\$\$)**

**37,444.00**

**20,194.00**

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**