Adjuster Report Page 1 of 3

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG20013728/UPS3Q2

**Date:** 12/01/2021

**REFERENCE** 

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100076668

Claimant
Vehicle No: SKV386R

Insured Vehicle No: SJE9257Y

Date of Loss: 08/12/2020 Nature of Claim: TP Claim No: 3885694802SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

Reg No: SKV386R

Make & Model: TOYOTA COROLLA, 1.6 (A) Engine No: 1ZRX521558

Reg. Date: 27/08/2015 (Man. Year: 2015) Chassis No: MR053REH104536020

Colour: Silver Odometer: 122340 km

Engine Capacity: 1598 cc Market Value/New Car

Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

**CONDITION OF TYRES** 

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16
Front Left Side: Continental 6 mm Rear Left Side: Continental 6 mm
Front Right Side: Continental 6 mm Rear Right Side: Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/12/2020

Date Inspected: 16/12/2020 Inspected At: Teamwork Garage Pte Ltd (HQ)

53 Ubi Ave 1 #01-24, Paya Ubi

Industrial Park Singapore 408934

Estimated Period of Repair: 3.0 days

Adjuster: MARCUS CHUA Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 3

# **REPAIR DETAILS**

### **Recommended Parts**

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR N/S	Repair	0.00 F	*- F
2	1		*REAR FENDER N/S	Repair	0.00 F	*- F
3	1		*REAR BUMPER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER PROTECTOR N/S	Cut	0.00 F	*- F
5	1		*SET REAR BUMPER CLIPS	Necessary	0.00 F	*- F
6	1		*REAR WHEEL HUB BEARING N/S	Damaged	0.00 F	*- F
7	1		*REAR SPORT RIM N/S	Cut	0.00 F	*- F
F=Fra	anchise	part.		_		
				Total Parts (S\$)	0.00	0.00
				_		

Report was unsubmitted during this print-out.

Adjuster Report Page 3 of 3

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >