

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG20013732/AEA3Q2**Date:** 09/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2000004392
Claimant Vehicle No :	SMP3467D	Insured Vehicle No :	SKZ7662B
Date of Loss:	27/11/2020	Nature of Claim:	TP
		Claim No:	3393650891SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP3467D		
Make & Model:	TOYOTA ESTIMA AERAS, 2.4 (A)	Engine No:	2AZL024200
Reg. Date:	23/09/2019 (Man. Year: 2018)	Chassis No:	ACR507166068
Colour:	White	Odometer:	18382 km
Engine Capacity:	2362 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,459.42	3,345.72	1,113.70	24.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,590.00	1,950.00	640.00	24.71
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,049.42	5,295.72	1,753.70	24.88
Approved Total (Overridden) (S\$)		4,200.00		
(S\$)	7,049.42	4,200.00	2,849.42	40.42
+ GST 7.00/7.00% (S\$)	493.46	294.00	199.46	40.42
Nett Amount (S\$)	7,542.88	4,494.00	3,048.88	40.42
+ Loss of Use (7.0 x S\$100.00/day) (S\$)		700.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		5,196.00		

INSPECTION

Date of Assignment:	10/12/2020	Kang Car Repairers Pte Ltd (HQ)
Date Inspected:	10/12/2020 Inspected At:	No 1 Kaki Bukit Ave 6, #02-06 AutoBay@Kaki Bukit
Estimated Period of Repair:	6.0 days	Singapore 417883

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOT LID	Dented	1,490.10 FL	*1,490.10 FL
2	1		*BOOT LID LOGO	Necessary	66.80 FL	*66.80 FL
3	1		*BOOT LID ESTIMA EMBLEM	Necessary	44.20 FL	*44.20 FL
4	1		*REAR WINDSCREEN RUBBER	Necessary	91.20 FL	*91.20 FL
5	1		*BOOT LID LOCK	Not Necessary	389.80 FL	*- FL
6	1		*BOOT LID RUBBER	Not Necessary	325.70 FL	*- FL
7	1		*BOOT LID TRIM	Not Necessary	476.10 FL	*- FL
8	1		*REAR BUMPER	Deformed	765.00 FL	*765.00 FL
9	2		*REAR BUMPER SIDE RETAINERS	Necessary	104.20 FL	*104.20 FL
10	1		*REAR PANEL	Dented	625.50 FL	*625.50 FL
11	1		*REAR PANEL TRIM	Deformed	253.10 FL	*253.10 FL
12	1		*REAR BUMPER SPONGE	Cracked	126.70 FL	*126.70 FL
13	1		*REAR ANTENNA SENSOR	Damaged	187.50 FL	*187.50 FL
14	1		*BOOT LID RUBBER LINING	Necessary	150.00 FS	*100.00 FS
15	1		*TUBE REAR WINDSCREEN SEALANT	Necessary	60.00 FS	*40.00 FS
16	1		*REAR WINDSCREEN SEAL	Necessary	60.00 FS	*40.00 FS
17	1		*SET BOOT LID TRIM CLIPS	Not Necessary	50.00 FS	*- FS
18	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FS	*30.00 FS
19	1		*SET REAR PANEL TRIM CLIPS	Necessary	40.00 FS	*20.00 FS
20	1		*SET REVERSE SENSOR	Damaged	350.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	5,695.90	4,284.30
- List Item Discount on L Items 25.00/25.00% (\$)	1,236.48	938.58
Total Parts (\$)	4,459.42	3,345.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REPLACE THE DAMAGED PARTS ,KNOCK OUT ACCIDENT DENTED PORTIONS ,AND FOR CUTTING/WELDING WORKS	New	1,000.00	800.00
2	TO SPRAY PAINTING	New	1,000.00	800.00
3	TO SPRAY UNDERSEAL	New	80.00	40.00
4	TO REMOVE AND REFIT REAR WINDSCREEN	New	120.00	120.00
5	TO CHECK WIRING	New	50.00	30.00
6	TO REPLACE REAR INNER TRIM	New	100.00	60.00
7	TO REFIT THIRD BRAKE LIGHT	New	80.00	0.00
8	TO REMOVE AND REPLACE REVERSE SENSOR	New	80.00	50.00
9	TO REMOVE AND REFIT REVERSE CAMERA	New	80.00	50.00
Gross Labour Cost (\$\$)			2,590.00	1,950.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >