



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
Email: acm.chang@outlook.com / FB: www.facebook.com/AcmServiceCentre
Tel / Fax: (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Not Authorized

\$ 2716.72

Running After Rain

4 days

Car Plate No. **GBK 4240R**
Model **Toyota Dyna**

Date of Accident : **09-12-2020**
Time of Accident : **19:45**


Venue : **BKE Twd W'lands**

No.	Qty	Parts Description	Estimated Parts Price
1	1	Rear tailgate assy <i>1265-u</i>	\$ <i>B1</i> 1,697.00 ✓
2	4	Rear tailgate hinges	\$ <i>new part</i> 260.00 ✗
3	1	Rear tailgate left top lock	\$ <i>R part</i> 248.00 ✗
4	1	Rear tailgate right top lock	\$ <i>R</i> 248.00 ✗
5	1	Rear tailgate left lower lock hinge <i>110</i>	\$ <i>B1</i> 176.00 ✓
6	1	Rear tailgate right lower lock hinge	\$ <i>R</i> 176.00 ✗
7	<i>*2/</i>	Rear tailgate left rubber stopper	\$ <i>new part</i> 68.00 ✗
8	2	Rear tailgate right rubber stopper	\$ <i>R</i> 68.00 ✗
9	1	Rear tailgate left rubber stopper bracket	\$ <i>R part</i> 88.00 ✗
10	1	Rear tailgate right rubber stopper bracket	\$ <i>R</i> 88.00 ✗
11	1	Rear tailgate lower panel	\$ <i>R</i> 1,465.00 ✗
12	1	Rear tailgate hook	\$ <i>R</i> 250.00 ✗
13	1	Rear left taillamp <i>291-30</i>	\$ <i>CMY</i> 662.00 ✓
14	1	Rear right taillamp	\$ <i>SPR</i> 662.00 ✗
15	1	Rear left taillamp bracket	\$ <i>R part</i> 116.00 ✗
16	1	Rear right taillamp bracket	\$ <i>R</i> 116.00 ✗
17	1	Rear no plate lamp	\$ <i>R</i> 88.00 ✗
18	1	Rear no plate support bracket	\$ <i>R</i> 120.00 ✗
19	1	Rear spare tyre lock holder	\$ <i>R</i> 363.00 ✗
20	1	Rear spare tyre carriage	\$ <i>R</i> 465.00 ✗
21	1	Rear spare tyre bracket carrier	\$ <i>R</i> 380.00 ✗
22	2	Rear exhaust rubber mounting	\$ <i>SPR</i> 36.00 ✗
23	1	Rear exhaust pipe assy	\$ <i>R</i> 1,650.00 ✗
			\$ 9,490.00
Less 25%			\$ 2,372.50
			\$ 7,117.50

Special Nett Items

1	1	Rear tailgate '70km/h' sticker	\$ <i>new</i> 50.00 <i>125u</i>
2	1	Rear tailgate company sticker	\$ <i>(B11) new</i> 300.00 <i>750u</i>
3	1	Rear no plate	\$ <i>new</i> 80.00 <i>255u</i>
4	2	Rear reverse sensor	\$ <i>short</i> 280.00 <i>200u</i>
			\$ 710.00

Total Parts 7,827.50



AH CHANG MOTOR SERVICE CENTRE

Blk 10 Ang Mo Kio Industrial Park 2A #03-16, AMK Autopoint, Singapore 568047
 Email : acm.chang@outlook.com / FB : www.facebook.com/AcmServiceCentre
 Tel / Fax : (65) 6483 5434 / 6484 2124 Co Reg No. 53188714 / GST Reg No. M90368983C

Car Plate No. **GBK 4240R**
 Model **Toyota Dyna**

Date of Accident : **09-12-2020**

Time of Accident : **19:45**

Venue : **BKE Twd W'lands**

<u>No.</u>	<u>Parts Description</u>	<u>Labour Charges</u>
1	Labour for panel beating, cut, weld, straighten rear affected area and replace rear damaged parts.	\$ 1,000.00 <i>500</i>
2	To putty and spray painting rear portion.	\$ 1,000.00 <i>500</i>
3	To check rear lighting and wiring.	\$ 50.00 <i>20</i>
4	To apply anti rust proofing to rear affected area.	\$ 100.00 <i>30</i>
5	To remove and install rear tailgate lock.	\$ <i>nr</i> 80.00 <i>X</i>
6	To remove and install rear exhaust pipe assy.	\$ <i>nr</i> 120.00 <i>X</i>
7	To remove and install rear reverse sensors.	\$ 80.00 <i>30</i>
8	Towing service.	\$ (<i>B.I.I</i>) 100.00 <i>X</i>

Total Labour \$ 2,530.00

Total Parts \$ 7,827.50

Total Labour \$ 2,530.00

Total Repair Cost \$ 10,357.50

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer .

Signature:

Date: