

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20013743/NGS3Q2
Date: 28/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070117683
Claimant Vehicle No :	SHC3153L	Insured Vehicle No :	SMU3588L
Date of Loss:	11/12/2020	Nature of Claim:	TP
		Claim No:	0041055103SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHC3153L		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU400836
Reg. Date:	30/10/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVLU187625
Colour:	Blue	Odometer:	73751 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,091.88	1,706.76	385.12	18.41
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,610.00	1,070.00	540.00	33.54
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,701.88	2,776.76	925.12	24.99
+ GST 7.00/7.00% (S\$)	259.13	194.37	64.76	24.99

Nett Amount (S\$)	3,961.01	2,971.13	989.88	24.99
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$125.19/day) (S\$)		625.95		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		3,849.08		

INSPECTION

Date of Assignment: 11/12/2020

Date Inspected: 11/12/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
 59 Loyang Drive
 Singapore 508969

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Repair	459.40 FL	*- FL
2	10		*HYUNDAI BUMPER COVER CLIP	Serviceable	22.00 FL	*- FL
3	1		*PANEL ASSY -QUARTE	Deformed	1,768.30 FL	*1,768.30 FL
4	1		*CAP ASSY -WHEEL HU	Scratched	346.40 FL	*346.40 FL
5	1		*FUEL LID (PETROL ONLY)LOGO	Necessary	15.00 FS	*15.00 FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
					Sub Total (\$\$)	2,611.10
					- List Item Discount on L Items 20.00/20.00% (\$\$)	519.22
					Total Parts (\$\$)	2,091.88
						1,706.76

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	960.00	640.00
2	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00
3	REMOVE/REFIX REVERSE SENSOR	New	80.00	30.00
4	ADJUST REAR WHEEL ALIGNMENT	New	120.00	0.00
Gross Labour Cost (S\$)			1,610.00	1,070.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >