

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013751/T1GS3Q2
Date: 05/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100480460
Claimant Vehicle No :	SH7163A	Insured Vehicle No :	SGT4858C
Date of Loss:	10/12/2020	Nature of Claim:	TP
		Claim No:	7108055191SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH7163A		
Make & Model:	HYUNDAI IONIQ HYBRID, 1.6 GLS DCT (A)	Engine No:	G4LEKU210459
Reg. Date:	30/04/2019 (Man. Year: 2019)	Chassis No:	KMHC851CVKU146115
Colour:	Blue	Odometer:	176897 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,003.92	779.28	224.64	22.38
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,130.00	970.00	160.00	14.16
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,133.92	1,749.28	384.64	18.03
+ GST 7.00/7.00% (S\$)	149.37	122.45	26.92	18.02

Nett Amount (\$)	2,283.29	1,871.73	411.56	18.02
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 14/12/2020

Estimated Period of Repair: 3.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969**Adjuster:** MOHD TAUFIKH BIN HAMID**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER -RR BUMPER	Cracked	459.40 FL	*459.40 FL
2	1		*HYUNDAI BUMPER COVER CLIP	Necessary	22.00 FL	*22.00 FL
3	1		*MOULDING ASSY-R	Cut	451.25 FL	*451.25 FL
4	1		*BRACKET ASSY-RR B	Not Necessary	55.80 FL	*- FL
5	1		*HYUNDAI REVERSE SENSOR AS	Not Necessary	180.00 FS	*- FS
6	1		*REFLECTOR /REFLEX	Cut	41.45 FL	*41.45 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,209.90	974.10
- List Item Discount on L Items 20.00/20.00% (\$\$)	205.98	194.82
Total Parts (\$\$)	1,003.92	779.28

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TOWING FEE	New	60.00	60.00
2	PANEL BEATING	New	500.00	480.00
3	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00
4	REMOVE/REFIX REVERSE SENSOR	New	120.00	30.00
Gross Labour Cost (\$\$)			1,130.00	970.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >