

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/MSG20013752/UVF3E2

Date: 23/02/2021

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	29141713MKF		
Claimant Vehicle No :	SLJ8548P	Insured Vehicle No :	SLS8832X		
Date of Loss:	11/12/2020	Nature of Claim:	TP	Claim No:	632027

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ8548P	Engine No:	27492030545583
Make & Model:	MERCEDES-BENZ C200, 1.5 AMG (A)	Chassis No:	WDD2050422R157762
Reg. Date:	28/12/2016 (Man. Year: 2016)	Odometer:	135567 km
Colour:	Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R18	Rear Tyre Size:	245/40 R18
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	46,714.02	20,026.86	26,687.16	57.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,250.00	3,170.00	4,080.00	56.28
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	53,964.02	23,196.86	30,767.16	57.01
Approved Total (Overridden) (S\$)		18,500.00		
(S\$)	53,964.02	18,500.00	35,464.02	65.72
+ GST 7.00/7.00% (S\$)	3,777.48	1,295.00	2,482.48	65.72
Nett Amount (S\$)	57,741.50	19,795.00	37,946.50	65.72

INSPECTION

Date of Assignment:	16/12/2020	
Date Inspected:	12/12/2020	Inspected At: Fastech Auto Pte Ltd (HQ) 1 Kaki Bukit Ave 6, #01-46/48/50 Autobay Singapore 417883
Estimated Period of Repair:	9.0 days	

Adjuster: MARCUS CHUA

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Feb 2021)	
Parts:	N/A	MERCEDES-BENZ C200 1.5 AMG (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLJ8548P)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Bent / Buckled	2,880.00 F	*2,248.39 FL
2	1		*BOOTLID REAR LOGO	Necessary	88.00 F	*59.80 FL
3	1		*BOOTLID C200L EMBLEM	Necessary	85.00 F	*82.00 FL
4	1		*BOOTLID INNER LOCK	Serviceable	355.00 F	*- FL
5	1		*BOOTLID INNER LOCK PUMP	Shorted / Jammed	1,250.00 F	*1,025.00 FL
6	1		*BOOTLID WEATHERSTRIP	Twisted	288.00 F	*281.10 FL
7	1		*BOOTLID OUTER CHROME MOULDING	Not Necessary	199.00 F	*- FL
8	1		*BOOTLID INNER TRIM	Not Necessary	315.00 F	*- FL
9	1		*SET BOOTLID INNER TRIM CLIPS	Not Necessary	50.00 F	*- FL
10	1		*REAR BUMPER AMG	Dented / Deformed	2,211.22 F	*2,047.22 FL
11	1		*REAR BUMPER LOWER	Distorted	492.00 F	*289.00 FL
12	1		*REAR BUMPER PDC SENSORS (4PCS)	N/S Shorted (1Pc Only)	792.00 F	*188.00 FL
13	1		*REAR BUMPER REINFORCEMENT	Bent	822.00 F	*712.00 FL
14	2		*REAR BUMPER SIDE HOLDERS	Not Necessary	180.00 F	*- FL
15	1		*REAR BUMPER INNER RETAINER	Cracked	285.00 F	*182.35 FL
16	1		*REAR BUMPER EXHAUST CHROMES	N/S Cut	960.00 F	*320.00 FL
17	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
18	1		*REAR END PANEL	Dented / Bent	1,545.00 F	*1,100.25 FL
19	1		*REAR END PANEL TOP GARNISH	Not Necessary	359.00 F	*- FL
20	2		*TAILLAMPS	Cracked	1,830.00 F	*1,430.00 FL
21	1		*REAR FENDER	Repair	2,580.00 F	*- FL
22	1		*REAR FENDER INNER TRIM	Not Necessary	311.00 F	*- FL
23	1		*REAR FLOOR PANEL	Not Necessary	566.80 F	*- FL
24	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	615.00 F	*- FL
25	1		*BONNET	Bent / Buckled	2,445.00 F	*2,158.74 FL
26	1		*BONNET LOCK	Serviceable	255.00 F	*- FL
27	1		*BONNET LOCK CATCH	Serviceable	109.00 F	*- FL
28	2		*BONNET HINGES	Not Necessary	370.00 F	*- FL
29	1		*FRONT BUMPER	Distorted	1,615.00 F	*1,599.32 FL
30	1		*FRONT BUMPER REINFORCEMENT	Bent	815.00 F	*495.00 FL
31	1		*FRONT BUMPER PDC SENSORS	N/S Shorted (1Pc Only)	396.00 F	*188.00 FL
32	1		*FRONT BUMPER CENTRE GRILLE	Twisted / Torn	288.00 F	*245.00 FL
33	1		*FRONT BUMPER SIDE GRILLE N/S	Deformed	198.00 F	*102.30 FL
34	1		*FRONT BUMPER SIDE HOLDER N/S	Twisted	165.00 F	*112.30 FL
35	1		*FRONT BUMPER SPONGE	Torn	190.00 F	*178.25 FL
36	1		*FRONT BUMPER TOP RETAINER	Cracked	233.00 F	*168.42 FL
37	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
38	1		*FRONT BUMPER LOWER CENTRE CHROME	Cracked	322.00 F	*285.45 FL
39	1		*FRONT BUMPER LOWER SIDE CHROME N/S	Bent	262.00 F	*196.50 FL
40	1		*FRONT BUMPER LOWER TRAY	Cracked	499.00 F	*422.39 FL
41	1		*SET FRONT BUMPER LOWER TRAY CLIPS	Necessary	50.00 F	*50.00 FL
42	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
43	1		*FRONT BUMPER REINFORCEMENT BRACKET N/S	Cracked	312.00 F	*185.43 FL
44	1		*FRONT TOP SUPPORT BRACKET	Cracked	345.00 F	*288.36 FL
45	1		*FRONT GRILLE	Cracked	815.00 F	*650.00 FL

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
46	1		*FRONT GRILLE LOGO	Not Necessary	150.00 F	*- FL
47	1		*HEADLAMPS	N/S Broken	9,710.00 F	*3,349.33 FL
48	2		*HEADLAMP LOWER BRACKETS	Not Necessary	310.00 F	*- FL
49	1		*FRONT CENTRE SUPPORT PANEL	Repair	525.00 F	*- FL
50	1		*FRONT FENDER N/S	Buckled	1,115.00 F	*915.25 FL
51	1		*FRONT FENDER INNER SHIELD N/S	Torn	324.00 F	*266.42 FL
52	1		*SET FRONT FENDER INNER SHIELD CLIPS N/S	Cracked	50.00 F	*50.00 FL
53	1		*AIR CON CONDENSOR	Not Necessary	1,275.00 F	*- FL
54	1		*AIR CON CONDENSER SIDE GARNISH	Deformed / Torn	88.00 F	*82.00 FL
55	1		*HORN UNIT	Cracked	165.00 F	*148.50 FL
56	1		*RADIATOR	Not Necessary	918.00 F	*- FL
57	1		*RADIATOR FAN ASSY	Not Necessary	1,560.00 F	*- FL
58	1		*INTER COOLER	Not Necessary	1,345.00 F	*- FL
59	1		*POWER STEERING COOLING PIPE	Not Necessary	286.00 F	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	46,714.02	22,252.07
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	2,225.21
Total Parts (\$\$)	46,714.02	20,026.86

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	80.00	30.00
2	TO RESET & REPROGRAMME ELECTRICAL MODULE SYSTEM	New	150.00	50.00
3	TO DISMANTLE & REPLACED PDC SENSOR	New	100.00	50.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	150.00	80.00
5	TO DISMANTLE & REFIX BOOTLID MECHANISM	New	120.00	60.00
6	TO SPRAY RUST PROOFING	New	150.00	100.00
7	TO REFILL AIR CON GAS	New	120.00	0.00
8	TO MOUNT VEHICLE ON CAR O-LINER	New	380.00	0.00
9	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	3,200.00	1,200.00
10	TO PUTTY & SPRAY PAINTING	New	2,800.00	1,600.00
Gross Labour Cost (\$\$)			7,250.00	3,170.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >