

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013753/KES3Q2**Date:** 17/02/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0999993943
Claimant Vehicle No :	SMP3716K	Insured Vehicle No :	SMP3968A
Date of Loss:	07/11/2020	Nature of Claim:	TP
		Claim No:	9425999959SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP3716K		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB6559590
Reg. Date:	24/09/2019 (Man. Year: 2018)	Chassis No:	GP71216111
Colour:	Metallic Dark Blue	Odometer:	50107 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Pirelli 9 mm	Rear Left Side:	Pirelli 8 mm
Front Right Side:	Pirelli 9 mm	Rear Right Side:	Pirelli 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,520.80	3,174.00	1,346.80	29.79
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,300.00	1,035.00	2,265.00	68.64
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	7,820.80	4,209.00	3,611.80	46.18
+ GST 7.00/7.00% (S\$)	547.46	294.63	252.83	46.18
Nett Amount (S\$)	8,368.26	4,503.63	3,864.63	46.18
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	14/12/2020	
Date Inspected:	15/12/2020	Inspected At: NO 5 KIM CHUAN LANE
Estimated Period of Repair:	4.0 days	Repairer: World Auto Pte Ltd - Halcyon 2 (HQ)

Adjuster: KENNETH KONG**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,850.00 FL	*1,850.00 FL
2	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
3	1		*REAR TAILGATE HYBRID EMBLEM	Necessary	65.00 FL	*65.00 FL
4	1		*REAR BUMPER	Buckled / Dented	1,800.00 FL	*1,800.00 FL
5	1		*REAR BUMPER SIDE INNER FOAM LH	*Check	160.00 FL	*- FL
6	1		*REAR BUMPER REFLECTOR LENS -LH	Serviceable	115.00 FL	*- FL
7	1		*REAR BUMPER REFLECTOR LENS GARNISH LH	Serviceable	128.00 FL	*- FL
8	1		*REAR BOOT WEATHERSTRIP	Serviceable	118.00 FL	*- FL
9	1		*REAR END PANEL	Repair	480.00 FL	*- FL
10	1		*REAR END PANEL TOP GARNISH	Serviceable	110.00 FL	*- FL
11	1		*SMART BUZZER SENSOR	Serviceable	110.00 FL	*- FL
12	1		*REAR WINDSCREEN GLASS MOULDING	Necessary	110.00 FL	*110.00 FL
13	1		*SET REAR TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	30.00 FS	*- FS
14	1		*SET REAR BUMPER CLIP	Necessary	30.00 FS	*30.00 FS
15	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	20.00 FS	*- FS
16	1		*WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
17	1		*SET REVERSE SENSOR	*Check	280.00 FS	*- FS
						F=Franchise part. S=SpcNett. L=ListItemDisc.
Sub Total (\$\$)					5,541.00	3,950.00
- List Item Discount on L Items 20.00/20.00% (\$\$)					1,020.20	776.00
Total Parts (\$\$)					4,520.80	3,174.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	180.00	120.00
2	TRANSFER REAR BOOTLID MECHANISM AND ACCESSORIES	New	180.00	60.00
3	WIRING CHECK AND RECTIFY WHERE NECESSARY INCLUDING DRILL HOLES ON NEW REAR BUMPER FOR INSTALLATION OF NEW SET OF REVERSE SENSORS	New	180.00	15.00
4	REMOVE ACCIDENT DAMAGED PARTS IN ORDER TO FACILITATE REPAIRS INCLUDING PANEL BEAT ,CUT/WELD REAR END PANEL ,STRAIGHTEN REAR CHASSIS WHERE NECESSARY AND REPLACE ABOVE PARTS	New	1,200.00	400.00
5	DEACTIVATE HV HYBRID SYSTEM IN ORDER TO FACILITATE REPAIRS AND REACTIVATIVATE BACK SAME	New	280.00	0.00
6	PERFORM VEHICLE DIAGNOSTICS INCLUDING CLEARING FAULT CODES REINITIALISE HV HYBRID SYSTEM	New	280.00	0.00
7	PUTTY AND SPRAY PAINT ACCIDENT AFFECTED AREAS	New	1,000.00	440.00
Gross Labour Cost (\$\$)			3,300.00	1,035.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >