

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte L 51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMM 292B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	FRONT BUMPER	TO REPAIR SEE LABOUR	2,858.77	-
2	FRONT BUMPER BRACKETS LH/RH	TO REPAIR SEE LABOUR	128.40	-
1	FRONT BUMPER TOW HOOK COVER	SERVICEABLE	58.85	-
2	FRONT BUMPER WASHER NOZZLE COVER LH/RH	SERVICEABLE	77.04	-
2	FRONT BUMPER SENSOR	SERVICEABLE	612.90	-
2	FRONT BUMPER AIR DUCT LH/RH	CRACKED	231.12	181.20
1	FRONT BUMPER ENGINE BAY COVER	CRACKED	354.08	291.10
1	FRONT BUMPER LOWER ENGINE COVER	SERVICEABLE	726.10	-
1	FRONT GRILLE	CRACKED	2,921.00	2,170.45
1	FRONT GRILLE AUDI LOGO EMBLEM	NECESSARY	175.26	175.26
1	RHF LOWER GRILLE	MISSING	535.00	535.00
1	RHF HEADLAMP	MTG CRACKED	8,358.84	7,186.65
1	RHF HEADLAMP BRACKET (SET)	CRACKED	139.10	139.10
1	FRONT NUMBER PLATE	CRACKED	50.00	50.00
1	FRONT BRACE PANEL (ADDITIONAL)	CRACKED	364.87	320.57
	LESS 5% DISCOUNT		-879.57	-552.47
			16,711.76	10,496.86
	<u>LABOUR</u>			
	TO CHECK LIGHTINGS & WIRINGS.		380.00	20.00
	PROGRAMMING & CALIBRATION RESET.	NOT NECESSARY	280.00	-
	ANTI-RUST PROOFING AND GALVANISING AFFECTED & REPLACEMENT PARTS.	NOT NECESSARY	380.00	-
	LABOUR TO DISMANTLE,REPAIR,REPLACE AND ALIGN THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF FRONT BUMPER AND FRONT BUMPER BRACKETS LH/RH.		1,000.00	250.00
	TO PUTTY,PRIMER,SPRAY PAINT FRONT BUMPER,FRONT GRILLE,RHF LOWER GRILLE.		1,200.00	280.00
			3,240.00	550.00
	GRAND TOTAL		19,951.76	11,046.86

Report Ref No. CS/SMO20013755/Ktf3q2



Page No.:2 of 2

RECOMMENDED COST OF REPAIRS			11,046.86	
-----------------------------	--	--	-----------	--

Report Ref No. CS/SMO20013755/Ktf3q2

KONG SENG CHEONG

Licensed Appraiser