

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013756/KPA3Q2**Date:** 10/06/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900078904
Claimant Vehicle No :	SKJ5978M	Insured Vehicle No :	SFY8759P
Date of Loss:	04/12/2020	Nature of Claim:	TP
		Claim No:	0475274046SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKJ5978M		
Make & Model:	LEXUS NX200T, 2.0 EXECUTIVE (A)	Engine No:	8ARW367448
Reg. Date:	12/05/2017 (Man. Year: 2016)	Chassis No:	JTJBARBZ202094874
Colour:	Metallic Pearl White	Odometer:	70531 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/55 R19	Rear Tyre Size:	235/55 R19
Front Left Side:	Bridgestone 8 mm	Rear Left Side:	Bridgestone 8 mm
Front Right Side:	Bridgestone 8 mm	Rear Right Side:	Bridgestone 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,529.50	5,038.11	4,491.39	47.13
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,200.00	870.00	1,330.00	60.45
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	11,729.50	5,908.11	5,821.39	49.63
+ GST 7.00/7.00% (S\$)	821.07	413.57	407.50	49.63
Nett Amount (S\$)	12,550.57	6,321.68	6,228.89	49.63
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,729.13		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment:	11/12/2020	
Date Inspected:	14/12/2020	Inspected At: Ricardo Auto Centre Pte Ltd (HQ) 160 Sin Ming Drive, #02-02, Sin Ming AutoCity Singapore 575722
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	1,061.80 F	*1,061.80 FL
2	10		*FRONT BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
3	1		*FRONT GRILLE	Cracked	1,211.70 F	*1,211.70 FL
4	1		*FRONT BUMPER REINFORCEMENT	Repair	738.10 F	*- FL
5	1		*FRONT BUMPER SPONGE	Cracked	99.30 F	*99.30 FL
6	1		*REAR BUMPER	Cracked	690.20 F	*690.20 FL
7	10		*REAR BUMPER CLIPS	Necessary	45.00 F	*45.00 FL
8	2		*FRONT BUMPER SIDE RETAINER LH & RH	Serviceable	183.60 F	*- FL
9	1		*REAR UNDER CARRIAGE COVER	Distorted / Buckled	250.60 F	*250.60 FL
10	1		*REAR EXHAUST CHROME COVER LH & RH	N/S Dented	1,330.40 F	*530.30 FL
11	1		*REAR EXHAUST PIPE	Repair	2,109.00 F	*- FL
12	1		*REAR EXHAUST MOUNTING	Distorted	41.00 F	*41.00 FL
13	2		*GRILLE OUTER COVER LH & RH	Dented	68.40 F	*68.40 FL
14	1		*FRONT GRILLE SENSOR LH	Shorted	490.80 F	*390.00 FL
15	1		*GRILLE HOLE COVER FOR CAMERA	Missing	35.00 F	*35.00 FL
16	1		*GRILLE LOWER PORTION	Cracked	302.00 F	*302.00 FL
17	1		*GRILLE MOULDING	Mtg Cracked	827.60 F	*827.60 FL
					Sub Total (\$\$)	9,529.50 5,597.90
					- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00 559.79
					Total Parts (\$\$)	9,529.50 5,038.11

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO SPRAY PAINT ON RH FRONT FENDER	New	200.00	0.00
2	TO CUT WELD & STRAIGHTEN FRONT & REAR PORTION DUE TO ACCIDENT ,ADJUST & REPLACE DAMAGE PARTS	New	1,000.00	400.00
3	TO TUFF COAT REPAIRED AREA	New	100.00	0.00
4	TO REMOVE & REPLACE EXHAUST PIPE	New	100.00	30.00
5	TO SPRAY PAINT ON REPAIRED AREAS	New	800.00	440.00
Gross Labour Cost (\$\$)			2,200.00	870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >