

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013758/UQD3Q2

Date: 04/01/2021

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No: 29139110AT2

Claimant
Vehicle No : SKG5447U

Insured Vehicle No : SKQ7620U

Date of Loss: 12/12/2020

Nature of Claim: TP

Claim No: 631917

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SKG5447U**

Make & Model: MERCEDES-BENZ C180K, 1.6 BlueEFFICIENCY (W204) (A)

Engine No: 27491030010674

Reg. Date: 18/09/2012 (Man. Year: 2012)

Chassis No: WDD2040312A757608

Colour: Black

Odometer: 160970 km

Engine Capacity: 1595 cc

Market Value/New Car

Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 ZR17

Rear Tyre Size:

225/45 ZR17

Front Left Side: Tourador 6 mm

Rear Left Side:

Continental 6 mm

Front Right Side: Tourador 6 mm

Rear Right Side:

Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	29,301.02	15,296.25	14,004.77	47.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,780.00	2,490.00	2,290.00	47.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	34,081.02	17,786.25	16,294.77	47.81
Approved Total (Overridden) (S\$)		13,000.00		
Nett Amount (S\$)	34,081.02	13,000.00	21,081.02	61.86

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 14/12/2020 Inspected At:

Zoom Autowerks Pte Ltd (HQ)
130 Bedok Reservoir Road, Eunos
Spring, #08-1339
Singapore 470130

Estimated Period of Repair: 7.0 days

Adjuster: MARCUS CHUA

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 04 Jan 2021)
Parts:	143	MERCEDES-BENZ C180K 1.6 BlueEFFICIENCY (W204) (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKG5447U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Distorted	1,286.40 FL	*1,286.40 FL
2	1		*FRONT BUMPER REINFORCEMENT	Bent	420.80 FL	*315.40 FL
3	1		*FRONT BUMPER INNER SPONGE	Not Necessary	210.30 FL	*- FL
4	1		*FRONT BUMPER CENTRE AIR-GRILLE	Not Necessary	195.60 FL	*- FL
5	1		*FRONT BUMPER SIDE GARNISH LH	Not Necessary	286.20 FL	*- FL
6	2		*FRONT BUMPER CHROMES	Necessary	391.60 FL	*230.00 FL
7	1		*FRONT BUMPER DAY LIGHT LH	Not Necessary	296.40 FL	*- FL
8	1		*FRONT BUMPER INNER SUPPORT FRAME BRACKET	Bent	250.40 FL	*148.20 FL
9	1		*FRONT BUMPER BRACKET LH	Not Necessary	175.40 FL	*- FL
10	1		*FRONT BUMPER MOUNT LH	No such part	98.50 FL	*- FL
11	2		*FRONT BUMPER DISTANCE SENSOR	Not Necessary	365.20 FL	*- FL
12	1		*SET FRONT BUMPER DISTANCE SENSOR HOLDER	Not Necessary	125.40 FL	*- FL
13	1		*FRONT BUMPER NUMBER PLATE GARNISH	Not Necessary	145.80 FL	*- FL
14	1		*SET FRONT BUMPER CLIPS	Necessary	60.00 FL	*60.00 FL
15	1		*SET FRONT RADIATOR GRILLE CHROME	Not Necessary	296.80 FL	*- FL
16	1		*FRONT RADIATOR GRILLE BASE	Not Necessary	495.10 FL	*- FL
17	1		*FRONT WASHER TANK	Distorted	175.40 FL	*166.20 FL
18	1		*FRONT HEADLAMP ASSY LH	Cracked	1,128.40 FL	*1,102.35 FL
19	1		*FRONT HEADLAMP BRACKET LH	Not Necessary	118.40 FL	*- FL
20	1		*FRONT HEADLAMP SUPPORT LH	Bent	125.40 FL	*92.30 FL
21	1		*FRONT BONNET ASSY	Bent/Buckled	1,598.60 FL	*1,598.60 FL
22	1		*FRONT FENDER LH	Bent	1,108.20 FL	*918.20 FL
23	1		*FRONT FENDER INNER SHIELD LH	Torn	298.30 FL	*145.80 FL
24	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	60.00 FL	*48.00 FL
25	1		*FRONT FENDER CHROME MOULDING LH	Necessary	121.40 FL	*112.30 FL
26	1		*FRONT KNUCKLE ARM LH	Bent	1,487.20 FL	*845.50 FL
27	1		*FRONT KNUCKLE HUB,WHEEL BEARING LH	Damaged	495.70 FL	*390.00 FL
28	1		*FRONT TOP ARM LH	Not Necessary	255.60 FL	*- FL
29	1		*FRONT TIE ROD LH	Twisted	376.20 FL	*248.20 FL
30	1		*FRONT LOWER ARM LH	Bent	520.30 FL	*391.00 FL
31	1		*FRONT LOWER CONTROL ARM LH	Bent	386.70 FL	*282.00 FL
32	1		*FRONT SHOCK ABSORBER LH	Dented/Bent	395.80 FL	*395.80 FL
33	1		*FRONT WING MIRROR ASSY LH	Not Necessary	1,125.40 FL	*- FL
34	1		*FRONT DOOR LH	Dented/Bent	1,486.50 FL	*1,486.50 FL
35	1		*FRONT DOOR OUTER HANDLE GARNISH LH	Not Necessary	195.80 FL	*- FL
36	1		*FRONT DOOR LOWER CHROME MOULDING LH	Necessary	215.40 FL	*175.20 FL
37	1		*FRONT DOOR TOP HINGE LH	Serviceable	128.60 FL	*- FL
38	1		*FRONT DOOR LOWER HINGE LH	Not Necessary	132.50 FL	*- FL
39	1		*FRONT DOOR INNER LOCK LH	Shorted	496.50 FL	*480.50 FL
40	1		*FRONT DOOR WEATHER STRIP LH	Necessary	386.70 FL	*299.00 FL
41	1		*FRONT DOOR INNER TRIMBOARD LH	Deformed/Torn	786.40 FL	*715.40 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
42	1		*FRONT DOOR POWER WINDOW MOTOR/LINKAGE ASSY LH	Bent/Jammed	755.20 FL	*680.00 FL
43	1		*REAR DOOR LH	Dented/Bent	1,296.80 FL	*1,296.80 FL
44	1		*REAR DOOR LOWER CHROME MOULDING LH	Necessary	198.70 FL	*171.20 FL
45	1		*REAR DOOR TOP HINGE LH	Not Necessary	128.60 FL	*- FL
46	1		*REAR DOOR LOWER HINGE LH	Not Necessary	132.50 FL	*- FL
47	1		*REAR DOOR INNER LOCK LH	Not Necessary	496.50 FL	*- FL
48	1		*REAR DOOR WEATHER STRIP LH	Necessary	386.70 FL	*291.00 FL
49	1		*REAR DOOR INNER TRIMBOARD LH	Not Necessary	755.80 FL	*- FL
50	1		*REAR DOOR POWER WINDOW MOTOR/LINKAGE ASSY LH	Shorted	755.20 FL	*645.00 FL
51	1		*REAR DOOR QUARTER GLASS MOULDING LH	Not Necessary	295.70 FL	*- FL
52	1		*REAR BUMPER	Deformed/Cut	1,586.40 FL	*1,312.32 FL
53	1		*REAR FENDER INNER SHIELD LH	Not Necessary	320.00 FL	*- FL
54	1		*REAR KNUCKLE ARM LH	Not Necessary	1,587.50 FL	*- FL
55	1		*REAR KNUCKLE HUB,WHEEL BEARING LH	Not Necessary	481.50 FL	*- FL
56	1		*REAR TOP ARM LH	Not Necessary	295.40 FL	*- FL
57	1		*REAR TOP CONTROL ARM LH	Not Necessary	386.40 FL	*- FL
58	1		*REAR LOWER ARM LH	Not Necessary	464.70 FL	*- FL
59	1		*REAR LOWER CONTROL ARM LH	Not Necessary	396.50 FL	*- FL
60	1		*REAR SHOCK ABSORBER LH	Not Necessary	371.29 FL	*- FL
61	1		*REAR SPORT RIM LH	Repair	1,380.00 FL	*- FL
62	1		*FRONT SPORT RIM LH	Dented/Bent	1,242.00 FS	*600.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 32,418.69 16,929.17
- List Item Discount on L Items 10.00/10.00% (\$\$) 3,117.67 1,632.92

Total Parts (\$\$) 29,301.02 15,296.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR & RENEW AFFECTED ACCIDENT AREAS	New	1,400.00	600.00
2	TO PUTTY,SPRAY PAINT ON REAR AFFECTED ACCIDENT AREAS	New	1,600.00	1,400.00
3	TO CHECK & RE-CONNECT ALL ELECTRICAL WIRING	New	50.00	30.00
4	TO REMOVE & INSTALL FRONT DOOR COMPONENTS	New	150.00	60.00
5	TO REMOVE & INSTALL REAR DOOR COMPONENTS	New	150.00	60.00
6	TO REMOVE & INSTALL FRONT LEFT UNDERCARRIAGE COMPONENTS	New	250.00	150.00
7	TO REMOVE & INSTALL REAR LEFT UNDERCARRIAGE COMPONENTS	New	250.00	0.00
8	TO CONDUCT ALL WHEEL ALIGNMENT	New	280.00	80.00
9	TO DIAGNOSTIC & RESET TO STAR SPECIFICATION	New	450.00	50.00
10	TO RUST PROOF AFFECTED AREAS	New	200.00	60.00
Gross Labour Cost (S\$)			4,780.00	2,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >