

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013759/UBA3Q2

Date: 08/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993854

Claimant
Vehicle No : SGT3218G **Insured Vehicle No :** GBG1578H

Date of Loss: 11/12/2020 Nature of Claim: TP Claim No: 8364223393SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGT3218G		
Make & Model:	HONDA STREAM, 1.8 X (A)	Engine No:	R18A1733360
Reg. Date:	09/04/2007 (Man. Year: 2007)	Chassis No:	RN61029782
Colour:	Silver	Odometer:	260504 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/45 R17	Rear Tyre Size:	225/45 R17
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	16,689.70	5,320.88	11,368.82	68.12
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,220.00	2,180.00	2,040.00	48.34
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	20,909.70	7,500.88	13,408.82	64.13
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	20,909.70	6,000.00	14,909.70	71.31
+ GST 7.00/7.00% (S\$)	1,463.68	420.00	1,043.68	71.31
Nett Amount (S\$)	22,373.38	6,420.00	15,953.38	71.31
+ Car Rental (4.0 x S\$140.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		6,982.00		
Global Sum Settlement (S\$)		6,800.00		

INSPECTION

Date of Assignment: 12/12/2020

Date Inspected: 12/12/2020 Inspected At:

 Fastech Auto Pte Ltd (HQ)
 1 Kaki Bukit Ave 6, #01-46/48/50
 Autobay
 Singapore 417883

Estimated Period of Repair: 5.0 days

Adjuster: MARCUS CHUA**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR WINDSCREEN	Shattered	1,488.20 F	*1,145.30 FL
2	1		*REAR WINDSCREEN MOULDING	Necessary	188.20 F	*82.30 FL
3	1		*TAILGATE	Badly Dented	1,285.00 F	*903.20 FL
4	1		*TAILGATE OUTER HANDLE	Broken	249.20 F	*249.20 FL
5	1		*TAILGATE H LOGO	Necessary	39.00 F	*39.00 FL
6	1		*TAILGATE REAR WIPER ARM	Bent	241.80 F	*185.20 FL
7	1		*TAILGATE REAR WIPER MOTOR	Jammed	509.00 F	*509.00 FL
8	1		*TAILGATE REAR WIPER BLADE	Bent	105.90 F	*101.20 FL
9	1		*TAILGATE STREAM EMBLEM	Necessary	65.00 F	*32.60 FL
10	1		*TAILGATE WEATHERSTRIP	Twisted	288.50 F	*116.90 FL
11	1		*TAILGATE INNER LOCK	Dented / Shorted	315.90 F	*145.30 FL
12	1		*TAILGATE INNER TRIM BOARD	Deformed / Cracked	455.20 F	*341.50 FL
13	1		*SET TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 F	*50.00 FL
14	2		*TAILGATE DAMPERS	Not Necessary	490.20 F	*- FL
15	1		*REAR BUMPER	Dented	755.20 F	*654.00 FL
16	1		*REAR BUMPER TOW COVER	Not Necessary	28.00 F	*- FL
17	2		*REAR BUMPER SIDE RETAINERS	Not Necessary	70.00 F	*- FL
18	2		*REAR BUMPER LOWER BRACKETS	Not Necessary	110.00 F	*- FL
19	1		*SET REAR BUMPER CLIPS	Necessary	50.00 F	*50.00 FL
20	1		*REAR END PANEL	Dented	398.20 F	*306.10 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted	266.90 F	*182.30 FL
22	2		*TAILLAMPS	Cracked	900.00 F	*733.00 FL
23	2		*TAILLAMP HOUSING PANELS	Repair	598.00 F	*- FL
24	1		*REAR FLOOR PANEL	Repair	918.90 F	*- FL
25	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	466.70 F	*- FL
26	2		*REAR FENDERS	Repair	1,982.00 F	*- FL
27	2		*REAR FENDER INNER TRIM BOARDS	Not Necessary	970.00 F	*- FL
28	1		*REAR AIR VENT N/S	Not Necessary	68.80 F	*- FL
29	2		*REAR LICENCE PLATE LAMPS	Not Necessary	50.00 F	*- FL
30	1		*REAR EXHAUST	Not Necessary	885.80 F	*- FL
31	1		*REAR EXHAUST MOUNTING	Not Necessary	45.00 F	*- FL
32	1		*REAR FENDER LOWER PANEL N/S	Repair	366.20 F	*- FL
33	1		*REAR FLOOR INNER SIDE PANEL N/S	Repair	388.90 F	*- FL
34	1		*SET REAR BUMPER REVERSE SENSOR	Not fitted	300.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	50.00 FS	*40.00 FS
36	1		*REAR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*30.00 FS
37	1		*REAR END PANEL SEALANT	Necessary	50.00 FS	*50.00 FS
38	1		*SET REAR FLOOR PANEL INSULATOR	Not Necessary	280.00 FS	*- FS
39	1		*REAR LICENCE PLATE	Bent	50.00 FS	*40.00 FS
40	1		*SET REAR WINDSCREEN SLOAR FILM	Necessary	380.00 FS	*200.00 FS
41	1		*SET REAR REVERSE CAMERA	Shorted	450.00 FS	*300.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 16,689.70 6,486.10
- List Item Discount on L Items 0.00/20.00% (\$\$) 0.00 1,165.22

Total Parts (\$\$) 16,689.70 5,320.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO CHECK WIRING	New	50.00	30.00
2	TO DISMANTLE & REPLACED REVERSE CAMERA	New	80.00	50.00
3	TO DISMANTLE & REFIX REAR WINDSCREEN	New	150.00	120.00
4	TO DISMANTLE & REFIX CUSHION UPHOLSTERY	New	120.00	80.00
5	TO DISMANTLE & REFIX REAR EXHAUST	New	100.00	0.00
6	TO TRANSFER TAILGATE MECHANISM	New	100.00	60.00
7	TO SPRAY RUST PROOFING	New	120.00	60.00
8	LABOUR FOR PANEL BEATING & REPLACED PARTS	New	2,000.00	680.00
9	TO PUTTY & SPRAY PAINTING	New	1,500.00	1,100.00
Gross Labour Cost (\$)			4,220.00	2,180.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >