

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20013765/APA3Q2

**Date:** 14/04/2021

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100406378  
**Claimant**  
**Vehicle No :** SJC3799A **Insured Vehicle No :** SKQ3329M  
**Date of Loss:** 11/12/2020 **Nature of Claim:** TP **Claim No:** 3186520863SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SJC3799A**  
 Make & Model: TOYOTA WISH, 1.8 (A) Engine No: 1ZZ2955923  
 Reg. Date: 15/02/2008 (Man. Year: 2007) Chassis No: ZNE100378915  
 Colour: Silver Odometer: 289731 km  
 Engine Capacity: 1794 cc  
 Market Value/New Car Price: N/A  
 Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15  
 Front Left Side: Tourador 6 mm Rear Left Side: Tourador 6 mm  
 Front Right Side: Tourador 6 mm Rear Right Side: Tourador 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	10,894.60	3,713.37	7,181.23	65.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,000.00	2,050.00	2,950.00	59.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,894.60</b>	<b>5,763.37</b>	<b>10,131.23</b>	<b>63.74</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,600.00</b>		
<b>Nett Amount (S\$)</b>	<b>15,894.60</b>	<b>4,600.00</b>	<b>11,294.60</b>	<b>71.06</b>
<b>+ Loss of Use (6.0 x S\$80.00/day) (S\$)</b>		480.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>5,087.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>5,080.00</b>		

### INSPECTION

Date of Assignment: 11/12/2020  
 Date Inspected: 11/12/2020 Inspected At: Ishare Auto Pte. Ltd. (HQ)  
 8 KAKI BUKIT AVENUE 4 #08-09  
 PREMIER @ KAKI BUKIT  
 Singapore 415875

Estimated Period of Repair: 6.0 days

**Adjuster:** ADRIAN LING

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

**SPECIAL REMARKS**

Market Value: \$16,000.00(est) less LTA Rebate: \$10,988.00(est) = Nett Value :\$5,012.00(est)

Please note that third party vehicle COE expiry date is 14 Feb 2023.

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,042.40 FL	*585.00 FL
2	2		*REAR BUMPER BRACKET	Dented	171.20 FL	*171.20 FL
3	2		*REAR BUMPER SIDE RETAINER	Necessary	144.20 FL	*144.20 FL
4	1		*TAILLAMP C/W BRACKET	O/S Cracked	792.40 FL	*396.20 FL
5	2		*REAR FENDER INNER TRIM	Not Necessary	1,151.20 FL	*- FL
6	2		*REAR FENDER INNER COWLING	Not Necessary	566.20 FL	*- FL
7	1		*TAILGATE	Dented	1,272.40 FL	*1,272.40 FL
8	1		*TAILGATE OUTER MOULDING	Not Necessary	277.10 FL	*- FL
9	1		*TAILGATE LOGO	Necessary	75.20 FL	*75.20 FL
10	1		*TAILGATE INNER LOCK	Not Necessary	539.80 FL	*- FL
11	1		*TAILGATE LOWER LOCK	Not Necessary	38.60 FL	*- FL
12	2		*TAILGATE DAMPER	Not Necessary	556.20 FL	*- FL
13	2		*TAILGATE STOPPER	Not Necessary	49.40 FL	*- FL
14	1		*TAILGATE INNER HOLDER	Not Necessary	39.60 FL	*- FL
15	1		*TAILGATE WEATHERSTRIP	Cut	369.80 FL	*369.80 FL
16	1		*TAILGATE INNER TRIM (LOWER)	Not Necessary	363.20 FL	*- FL
17	4		*TAILGATE WINDSCREEN MOULDING	Necessary	155.60 FL	*155.60 FL
18	1		*REAR END PANEL	Dented	590.60 FL	*590.60 FL
19	1		*REAR END PANEL TOP GARNISH	Cracked	298.70 FL	*298.70 FL
20	1		*REAR END PANEL BOTTOM (CENTRE)	Dented	145.60 FL	*145.60 FL
21	1		*REAR FLOOR PANEL	Repair	580.97 FL	*- FL
22	1		*SPARE TYRE CHAIN	Not Necessary	328.50 FL	*- FL
23	1		*REAR CHASSIS MEMBER RH	Not Necessary	389.60 FL	*- FL
24	1		*REAR EXHAUST PIPE	Not Necessary	830.70 FL	*- FL
25	5		*REAR EXHAUST MOUNTING	Not Necessary	194.50 FL	*- FL
26	1		*REAR EXHAUST INSULATOR	Not Necessary	135.80 FL	*- FL
27	1		*REAR NUMBER PLATE	Not Necessary	80.00 FS	*- FS
28	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
29	1		*SET REAR BUMPER REFLECTOR (SPECIAL TYPE)	Cracked	250.00 FS	*200.00 FS
30	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
31	1		*SET TAILGATE INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
32	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*60.00 FS
33	1		*TAILGATE WINDSCREEN INNER SHIELD	Not Necessary	60.00 FS	*- FS
34	1		*SET TAILLAMP CLIP	Necessary	50.00 FS	*10.00 FS
35	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	80.00 FS	*- FS
36	1		*SET REAR FENDER INNER COWLING CLIP	Not Necessary	80.00 FS	*- FS
37	1		*REAR END PANEL INSULATION SEAL	Necessary	150.00 FS	*60.00 FS
38	1		*REAR END PANEL BOTTOM (CENTRE) SEALANT	Not Necessary	120.00 FS	*- FS
39	1		*REAR FLOOR PANEL SEALANT	Not Necessary	350.00 FS	*- FS
40	4		*REVERSE SENSOR	Damaged	380.00 FS	*200.00 FS
41	1		*REVERSE CAMERA	Not Necessary	580.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$)** 13,669.47 4,764.50  
**- List Item Discount on L Items 25.00/25.00% (\$\$)** 2,774.87 1,051.13

**Total Parts (\$\$)** 10,894.60 3,713.37

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO PANEL BEAT ,REMOVE AND REPLACE PARTS	New	1,600.00	800.00
2	TO SPRAY PAINT AFFECTED AREA	New	1,600.00	800.00
3	TUFF COAT	New	250.00	60.00
4	WIRING AND BULB CHECK	New	180.00	30.00
5	REMOVE AND REFIX CUSHION SEAT /UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	New	350.00	60.00
6	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	New	150.00	60.00
8	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	New	150.00	60.00
9	TRANSFER TAILGATE MECHANISM	New	120.00	60.00
10	REMOVE AND REFIX TAILGATE WINDSCREEN	New	120.00	120.00
11	REAR CHASSIS ALIGNMENT	New	180.00	0.00
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT /CONTROL UNITS ,RESET MEMORIES TO SPECIFICATION ETC	New	180.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>5,000.00</b>	<b>2,050.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >