

Co. Reg No: 201939376R
8 Kaki Bukit Avenue 4
#08-09 Premier @ Kaki Bukit
Singapore 415875
Tel: 6341 6789 Fax: 6341 6778
Email: ishareauto@gmail.com



TO : **AIG** MOTOR CLAIMS DEPTS
VEHICLE NO : **SJC3799A**
MODEL : **TOYOTA WISH**
DATE OF ACCIDENT : 11.12.20
TIME OF ACCIDENT : 07:40HRS

Xiao Tony

2NF100378915

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR BUMPER <i>dent</i>	1	\$ 1,042.40	\$ 1,042.40
2	REAR BUMPER BRACKET <i>Dented</i>	2	\$ 85.60	\$ 171.20
3	REAR BUMPER SIDE RETAINER <i>New</i>	2	\$ 72.10	\$ 144.20
4	TAILLAMP C/W BRACKET <i>Left RH auto</i>	2	\$ 396.20	\$ 792.40
5	REAR FENDER INNER TRIM <i>Not New</i>	2	\$ 575.60	\$ 1,151.20
6	REAR FENDER INNER COWLING <i>New</i>	2	\$ 283.10	\$ 566.20
7	TAILGATE <i>Dented</i>	1	\$ 1,272.40	\$ 1,272.40
8	TAILGATE OUTER MOULDING <i>Not New</i>	1	\$ 277.10	\$ 277.10
9	TAILGATE LOGO <i>New</i>	1	\$ 75.20	\$ 75.20
10	TAILGATE INNER LOCK <i>Not New</i>	1	\$ 539.80	\$ 539.80
11	TAILGATE LOWER LOCK <i>New</i>	1	\$ 38.60	\$ 38.60
12	TAILGATE DAMPER <i>Not New</i>	2	\$ 278.10	\$ 556.20
13	TAILGATE STOPPER <i>Not New</i>	2	\$ 24.70	\$ 49.40
14	TAILGATE INNER HOLDER <i>Not New</i>	1	\$ 39.60	\$ 39.60
15	TAILGATE WEATHER STRIP <i>At</i>	1	\$ 369.80	\$ 369.80
16	TAILGATE INNER TRIM (LOWER) <i>Not New</i>	1	\$ 363.20	\$ 363.20
17	TAILGATE WINDSCREEN MOULDING <i>New</i>	4	\$ 38.90	\$ 155.60
18	REAR END PANEL <i>Dented</i>	1	\$ 590.60	\$ 590.60
19	REAR END PANEL TOP GARNISH <i>Cracked</i>	1	\$ 298.70	\$ 298.70
20	REAR END PANEL BOTTOM (CENTRE) <i>Dented</i>	1	\$ 145.60	\$ 145.60
21	REAR FLOOR PANEL <i>Repair</i>	1	\$ 580.97	\$ 580.97
22	SPARE TYRE CHAIN	1	\$ 328.50	\$ 328.50
23	REAR CHASSIS MEMBER RH <i>Not New</i>	1	\$ 389.60	\$ 389.60
24	REAR EXHAUST PIPE <i>New</i>	1	\$ 830.70	\$ 830.70
25	REAR EXHAUST MOUNTING	5	\$ 38.90	\$ 194.50

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJC3799A**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 11.12.20
 TIME OF ACCIDENT : 07:40HRS

26	REAR EXHAUST INSULATOR <i>Neu</i>	1	\$ 135.80	\$ 135.80
----	-----------------------------------	---	-----------	-----------

4204.50

3153.37

TOTAL PRICE \$ 11,099.47
 LESS 25% \$ 2,774.87
SUB TOTAL PRICE \$ 8,324.60

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	REAR NUMBER PLATE <i>Neu</i>	1	\$ 80.00	\$ 80.00
2	REAR BUMPER CLIPS (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00
3	REAR BUMPER REFLECTOR (SPECIAL TYPE)(SET) <i>Cracked</i>	1	\$ 250.00	\$ 250.00
4	TAILGATE SEALANT <i>Neu</i>	1	\$ 150.00	\$ 150.00
5	TAILGATE INNER TRIM CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00
6	TAILGATE WINDSCREEN SEALANT <i>Neu</i>	1	\$ 80.00	\$ 80.00
7	TAILGATE WINDSCREEN INNER SHIELD <i>Neu</i>	1	\$ 60.00	\$ 60.00
8	TAILLAMP CLIP (SET) <i>Neu</i>	1	\$ 50.00	\$ 50.00
9	REAR FENDER INNER TRIM CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00
10	REAR FENDER INNER COWLING CLIP (SET) <i>Neu</i>	1	\$ 80.00	\$ 80.00
11	REAR END PANEL INSULATION SEAL <i>Neu</i>	1	\$ 150.00	\$ 150.00
12	REAR END PANEL BOTTOM (CENTRE) SEALANT <i>Neu</i>	1	\$ 120.00	\$ 120.00
13	REAR FLOOR PANEL SEALANT <i>Neu</i>	1	\$ 350.00	\$ 350.00
14	REVERSE SENSOR (4PCS) <i>Damaged</i>	1	\$ 380.00	\$ 380.00
15	REVERSE CAMERA <i>Neu</i>	1	\$ 580.00	\$ 580.00

560

TOTAL \$ 2,570.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	\$ 1,600.00	800
2	TO SPRAY PAINT AFFECTED AREA	\$ 1,600.00	800
3	TUFF COAT	\$ 250.00	60
4	WIRING AND BULB CHECK	\$ 180.00	30
5	REMOVE AND REFIX CUSHION SEAT/UPHOLSTERY & ROOF LINING TO FACILITATE REPAIR	\$ 350.00	60
6	CONDUCT WATER LEAKAGE TEST	\$ 120.00	X

TO : **AIG** MOTOR CLAIMS DEPTS
 VEHICLE NO : **SJC3799A**
 MODEL : **TOYOTA WISH**
 DATE OF ACCIDENT : 11.12.20
 TIME OF ACCIDENT : 07:40HRS

7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	\$ 150.00	60
8	REMOVE AND REFIX VIDEO RECORDER AND DISTANCE SETTING	\$ 150.00	60
9	TRANSFER TAILGATE MECHANISM	\$ 120.00	60
10	REMOVE AND REFIX TAILGATE WINDSCREEN	\$ 120.00	✓
11	REAR CHASSIS ALIGNMENT	\$ 180.00	x
12	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 180.00	x

2050

TOTAL \$ 5,000.00

ESTIMATE REPORT

TOTAL PARTS COST : \$10,894.60
 TOTAL LABOUR COST : \$5,000.00
 TOTAL REPAIR COST : \$15,894.60

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

MICHELLE

SERVICE ADVISOR
 MICHELLE
 HP : 9856 4815

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj
 h/s 11/12/20.
 06 Days.

total: 5763.37.

2/s: 4.61c