

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20013768/EVF3E2
Date: 13/01/2021

REFERENCE

Insured/Claimant: LAM SZE JIA (LAN SIJIA) Policy No: 1900150108
Date of Loss: 10/12/2020 Nature of Claim: OD Claim No: 4352678448SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMN5700C**
Make & Model: MITSUBISHI OUTLANDER, 2.0 (A) Engine No: 4J11BH4181
Reg. Date: 19/08/2019 (Man. Year: 2019) Chassis No: GF7W0601876
Colour: Blue Odometer: 16910 km
Engine Capacity: 1998 cc
Market Value/New Car Price: S\$99,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/55R18 Rear Tyre Size: 225/55R18
Front Left Side: Toyo 5 mm Rear Left Side: Toyo 5 mm
Front Right Side: Toyo 5 mm Rear Right Side: Toyo 5 mm

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|-------------------------------------|------------------|------------------|-----------------|--------------|
| Parts | 7,854.09 | 6,682.18 | 1,171.91 | 14.92 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 4,490.00 | 3,380.00 | 1,110.00 | 24.72 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 12,344.09 | 10,062.18 | 2,281.91 | 18.49 |
| - Excess (S\$) | 300.00 | 300.00 | 0.00 | 0.00 |
| (S\$) | 12,044.09 | 9,762.18 | 2,281.91 | 18.95 |
| + GST 7.00/7.00% (S\$) | 843.09 | 683.35 | 159.74 | 18.95 |
| Nett Amount (S\$) | 12,887.18 | 10,445.53 | 2,441.65 | 18.95 |

INSPECTION

Date of Assignment: 14/12/2020
Date Inspected: 14/12/2020 Inspected At: CYCLE & CARRIAGE AUTOMOTIVE PTE LTD
209 PANDAN GARDENS
SINGAPORE 609339
Estimated Period of Repair: 7.0 days

Adjuster: CHEN TSUE YEE

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|-------------|--------------|
| 1 | 1 | | *HEADLAMP ASSY,RH | Broken | 1,938.00 FL | *1,938.00 FL |
| 2 | 1 | | *LAMP ASSY,FOG,FR RH | Broken | 348.00 FL | *348.00 FL |
| 3 | 1 | | *GARNISH,FR BUMPER,RH | Missing | 48.00 FL | *48.00 FL |
| 4 | 1 | | *BRACKET,FR BUMPER SIDE RH | Broken | 18.00 FL | *18.00 FL |
| 5 | 1 | | *EXTENSION,FR BUMPER | Broken | 515.00 FL | *515.00 FL |
| 6 | 1 | | *GARNISH,FR BUMPER SIDE | Broken | 220.00 FL | *220.00 FL |
| 7 | 1 | | *GARNISH,FR BUMPER SIDE | Broken | 112.00 FL | *112.00 FL |
| 8 | 1 | | *REINFORCEMENT,FR BUMPER | Not Necessary | 490.00 FL | *- FL |
| 9 | 1 | | *BAR,FR BUMPER GUARD | Not Necessary | 130.00 FL | *- FL |
| 10 | 1 | | *COVER,HEADLAMP SUPT PANEL | Not Necessary | 50.00 FL | *- FL |
| 11 | 1 | | *GRILLE ASSY RADIATOR | Not Necessary | 548.00 FL | *- FL |
| 12 | 1 | | *HOOD | Dented | 975.00 FL | *975.00 FL |
| 13 | 1 | | *WEATHERSTRIP HOOD | Not Necessary | 41.00 FL | *- FL |
| 14 | 1 | | *FENDER,FR RH | Dented | 688.00 FL | *688.00 FL |
| 15 | 1 | | *INSULATOR,FR FENDER,RH | Not Necessary | 60.00 FL | *- FL |
| 16 | 1 | | *SHIELD,FR WHEELHOUSE,RH | Not Necessary | 164.00 FL | *- FL |
| 17 | 1 | | *MOULDING,FR BUMPER,RH | Cut | 116.00 FL | *116.00 FL |
| 18 | 1 | | *MOULDING,FRH WHEEL ARCH,RH | Necessary | 160.00 FL | *160.00 FL |
| 19 | 1 | | *SUNDRIES | Necessary | 50.00 FS | *20.00 FS |
| 20 | 1 | | *FACE,FR BUMPER (Supplementary) | Broken | 859.00 FL | *859.00 FL |
| 21 | 1 | | *COVER, FR BUMPER (Supplementary) | Broken | 359.00 FL | *359.00 FL |
| 22 | 1 | | *GARNISH,FR BUMPER SIDE (Supplementary) | Cut | 48.00 FL | *48.00 FL |
| 23 | 6 | | *RIVET, FR BUMPER (Supplementary) | Necesarly | 30.00 FL | *30.00 FL |
| 24 | 1 | | *TANK, WINDSHIELD WAHSER (Supplementary) | Crumpled | 86.00 FL | *86.00 FL |
| 25 | 1 | | *SENSOR,W/SHLD WASHER TANK (Supplementary) | Broken | 114.00 FL | *114.00 FL |
| 26 | 1 | | *BODY KIT,OUTLANDER (Supplementary) | Cut | 1,554.00 FS | *1,554.00 FS |

F=Franchise part. S=SpcNett. L=ListItemDisc.

| | | |
|--|----------|----------|
| Sub Total (S\$) | 9,721.00 | 8,208.00 |
| - List Item Discount on L Items 23.00/23.00% (S\$) | 1,866.91 | 1,525.82 |
| Total Parts (S\$) | 7,854.09 | 6,682.18 |

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|--------------------------------|---|----------|-----------------|-----------------|
| Labour Items | | | | |
| 1 | REPLACE FRT BUMPER,BONNET,FRT RH FENDER & AFFECTED AREA REPAIR ON FRT RH DOOR | New | 2,250.00 | 1,350.00 |
| 2 | PAINT WORK ON FRT BUMPER,BONNET,FRT RH FENDER & FRT RH DOOR | New | 1,600.00 | 1,400.00 |
| 3 | REMOVE & INSTALL FRT PARKING ASSIST | New | 120.00 | 120.00 |
| 4 | PERFORM RUST PREVENTION | New | 50.00 | 40.00 |
| 5 | CHECK WIRING & CHASSIS ELECTRICAL SYSTEM | New | 30.00 | 30.00 |
| 6 | TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST | New | 120.00 | 120.00 |
| 7 | TO APPLY ZERTONA COATING ON AFFECTED AREA | New | 320.00 | 320.00 |
| Gross Labour Cost (S\$) | | | 4,490.00 | 3,380.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >