

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CC4/AIG20013771/R1PS3Q2  
**Date:** 23/07/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100359031
<b>Claimant Vehicle No :</b>	SHD3286G	<b>Insured Vehicle No :</b>	SFY1315H
Date of Loss:	13/12/2020	Nature of Claim:	TP
		Claim No:	3943027771SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHD3286G</b>	Engine No:	D4FDGU655897
Make & Model:	HYUNDAI I40, 1.7 D CRDI F/L ABS AIRBAG 4DR (A)	Chassis No:	KMHLB41UMGU091880
Reg. Date:	08/07/2016 (Man. Year: 2016)	Odometer:	497418 km
Colour:	Blue		
Engine Capacity:	1685 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,949.76	941.76	2,008.00	68.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,180.00	480.00	700.00	59.32
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,129.76</b>	<b>1,421.76</b>	<b>2,708.00</b>	<b>65.57</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,150.00</b>		

(S\$)	4,129.76	1,150.00	2,979.76	72.15
<b>+ GST 7.00/7.00% (S\$)</b>	289.08	80.50	208.58	72.15
<b>Nett Amount (S\$)</b>	<b>4,418.84</b>	<b>1,230.50</b>	<b>3,188.34</b>	<b>72.15</b>
<b>+ Loss of Use (2.5 x S\$50.00/day) (S\$)</b>		125.00		
<b>+ Car Rental (2.5 x S\$114.95/day) (S\$)</b>		287.38		
<b>+ Doc/Search Fee (S\$)</b>		2.00		
<b>Nett Liability (S\$)</b>		<b>1,644.88</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,640.00</b>		

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 14/12/2020

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)

59 Loyang Drive

Singapore 508969

Estimated Period of Repair: 3.0 days

**Adjuster:** MOHD RASUL**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	1,052.20 FL	*1,052.20 FL
2	1		*FRT BUMPER UPR BRKT LH	Serviceable	22.40 FL	*- FL
3	1		*FRT BUMPER SIDE BRKT LH	Serviceable	24.60 FL	*- FL
4	1		*FRT FENDER LH	Repair	663.00 FL	*- FL
5	1		*HEADLAMP LH	Serviceable	1,800.00 FL	*- FL
6	1		*FRT FENDER ADV.STICKER LH	Necessary	100.00 FS	*100.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>3,662.20</b>	<b>1,152.20</b>
<b>- List Item Discount on L Items 20.00/20.00% (\$\$)</b>	712.44	210.44
<b>Total Parts (\$\$)</b>	<b>2,949.76</b>	<b>941.76</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	600.00	280.00
2	SPRAYPAINT CHARGE	New	500.00	200.00
3	CHECK ALL LIGHTING	New	40.00	0.00
4	TUFF COAT ON AFFECTED PARTS	New	40.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,180.00</b>	<b>480.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >