

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CS/AIG20013773/EQD3E2
Date: 30/12/2020

REFERENCE

Insured/Claimant:	LIM FEI LIONG	Policy No:	1900018520	Claim No:	6238620344SG
Date of Loss:	12/12/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ335C	Engine No:	G4FGJH713514
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5024711
Reg. Date:	20/02/2019 (Man. Year: 2018)	Odometer:	26464 km
Colour:	Silver		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$68,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Kumho 4 mm	Rear Left Side:	Kumho 4 mm
Front Right Side:	Kumho 4 mm	Rear Right Side:	Kumho 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,530.00	4,070.40	1,459.60	26.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,510.00	4,120.00	390.00	8.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	10,040.00	8,190.40	1,849.60	18.42
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	9,440.00	7,590.40	1,849.60	19.59
+ GST 7.00/7.00% (S\$)	660.80	531.33	129.47	19.59
Nett Amount (S\$)	10,100.80	8,121.73	1,979.07	19.59

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 14/12/2020
Estimated Period of Repair: 8.0 days

Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT NUMBER PLATE WITH CASING	Not Necessary	50.00 FS	*- FS
2	1		*SUNDRIES	Necessary	20.00 FS	*20.00 FS
3	1		*COVER-FR BUMPER	Broken	633.00 FL	*633.00 FL
4	1		*CAP-FRONT HOOK	Not Necessary	9.00 FL	*- FL
5	1		*GRILLE-FRONT BUMPER	Not Necessary	262.00 FL	*- FL
6	1		*COVER-FR BUMPER FOG LAMP, RH	Not Necessary	15.00 FL	*- FL
7	1		*GRILLE ASSY-RADIATOR	Broken	328.00 FL	*328.00 FL
8	1		*GARNISH-RADIATOR GRILLE	Broken	38.00 FL	*38.00 FL
9	1		*LAMP ASSY-FRONT FOG, RH	Not Necessary	303.00 FL	*- FL
10	1		*MOULDING-FRONT BUMPER, RH	Cut	36.00 FL	*36.00 FL
11	1		*LAMP ASSY-SIDE REPEATER, RH	Not Necessary	143.00 FL	*- FL
12	1		*AIR DUCT-FR BUMPER, RH	Broken	14.00 FL	*14.00 FL
13	1		*ABSORBER-FRONT BUMPER ENERGY	Not Necessary	84.00 FL	*- FL
14	1		*STIFFNER-FR BPR LWR	Not Necessary	114.00 FL	*- FL
15	1		*BRACKET-FR BUMPER UPR SIDE MTG	Broken	22.00 FL	*22.00 FL
16	1		*BEAM COMPLETE-FR BUMPER	Not Necessary	497.00 FL	*- FL
17	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
18	1		*CARRIER ASSY-FRONT END MODULE	Broken	675.00 FL	*675.00 FL
19	1		*PANEL ASSY-HOOD	Dented	1,502.00 FL	*1,502.00 FL
20	1		*HINGE ASSY-HOOD, LH	Not Necessary	43.00 FL	*- FL
21	1		*HINGE ASSY-HOOD, RH	Not Necessary	43.00 FL	*- FL
22	13		*CLIP-HOOD INSULATING PAD MTG	Necessary	13.00 FL	*13.00 FL
23	1		*LATCH ASSY-HOOD	Not Necessary	103.00 FL	*- FL
24	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
25	1		*GUARD ASSY-FRONT WHEEL, RH	Crushed	95.00 FL	*95.00 FL
26	1		*LAMP ASSY-HEAD, RH	Broken	1,219.00 FL	*1,219.00 FL
27	1		*RESERVOIR & PUMP ASSY-WASHER	Not Necessary	146.00 FL	*- FL
28	1		*COOLANT (4L)	Necessary	26.00 FL	*26.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,895.00	5,083.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	1,365.00	1,012.60
Total Parts (\$\$)	5,530.00	4,070.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	RENEW FRT BUMPER, BONNET, RHF FENDER & FRT SUPPORT PNL. REPAIR RHF DOOR, RHF A PILLAR & LHF FENDER	New	2,000.00	2,000.00
2	RESPRAY FRT BUMPER, BONNET, LHF FENDER, RHF FENDER, RHF DOOR & RHF A PILLAR	New	2,100.00	1,750.00
3	REMOVE & REFIT AC COND & RADIATOR	New	100.00	100.00
4	TOP UP AIRCON GAS	New	80.00	80.00
5	CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	APPLY ANTI COROSSION ON AFFECTED AREAS	New	80.00	40.00
Gross Labour Cost (\$\$)			4,510.00	4,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >