



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LIM FEI LIONG Reg No/Reg Date SMJ335C*KC17P/ 20/02/201 Date In/Mileage / 0 Chassis No KNAF3416MK5024711 Engine No G4FGJH713514 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	14/12/2020/ 12:51	QUE	261 / Edwin Caina	25733			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000								2000.00
RENEW FRT BUMPER , BONNET , RHF FENDER & FRT SUPPORT PNL 400 x 5								
REPAIR RHF DOOR , RHF A PILLAR & LHF FENDER								
E PNT98000								2100.00
RESPRAY FRT BUMPER , BONNET , LHF FENDER , RHF FENDER , RHF DOOR & RHF A PILLAR 350 x 5								
E PNT88000								100.00
REMOVE & REFIT AC COND & RADIATOR								
M SUNDRY								80.00
TOP UP AIRCON GAS								
A 54900099								30.00
CHECK WIRING ELECTRICAL SYSTEM & ADJUST HEADLAMP AIM								
A 10028901								120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST								
USING HI-SCAN PRO TEST								
M SUNDRY								80.00
APPLY ANTI CORROSION ON AFFECTED AREAS								
M SUNDRY								50.00
SUPPLY FRT NUMBER PLATE WITH CASING								
M SUNDRY								20.00
Sundries								
M COVER-FR BUMPER					1.00	633.00	20.00	506.40
M CAP-FRONT HOOK					1.00	9.00	20.00	7.20
M GRILLE-FRONT BUMPER					1.00	262.00	20.00	209.60
M COVER-FR BUMPER FOG LAMP,RH					1.00	15.00	20.00	12.00
M GRILLE ASSY-RADIATOR					1.00	328.00	20.00	262.40
M GARNISH-RADIATOR GRILLE					1.00	38.00	20.00	30.40
M LAMP ASSY-FRONT FOG,RH					1.00	303.00	20.00	242.40
M MOULDING-FRONT BUMPER,RH					1.00	36.00	20.00	28.80
M LAMP ASSY-SIDE REPEATER,RH					1.00	143.00	20.00	114.40
M AIR DUCT-FR BUMPER,RH					1.00	14.00	20.00	11.20
M ABSORBER-FRONT BUMPER ENERGY					1.00	84.00	20.00	67.20
M STIFFNER-FR BPR LWR					1.00	114.00	20.00	91.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LIM FEI LIONG Reg No/Reg Date SMJ335C*KC17P/ 20/02/201 Date In/Mileage / 0 Chassis No KNAF3416MK5024711 Engine No G4FGJH713514 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim 4SS SILKY SILVER / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	14/12/2020/ 12:51	QUE	261 / Edwin Caina	25733
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M BRACKET-FR BUMPER UPR SIDE MTG	BR	1.00	22.00	20.00	17.60
M BEAM COMPLETE-FR BUMPER	X NAI	1.00	497.00	20.00	397.60
M ORNAMENT-KIA NO.115	NAI	1.00	32.00	20.00	25.60
M CARRIER ASSY-FRONT END MODULE	BR	1.00	675.00	20.00	540.00
M PANEL ASSY-HOOD	DD	1.00	1502.00	20.00	1201.60
M HINGE ASSY-HOOD,LH	X NAI	1.00	43.00	20.00	34.40
M HINGE ASSY-HOOD,RH	X NAI	1.00	43.00	20.00	34.40
M CLIP-HOOD INSULATING PAD MTG	NAI	13.00	1.00	20.00	10.40
M LATCH ASSY-HOOD	X NAI	1.00	103.00	20.00	82.40
M PANEL-FENDER,RH	DD	1.00	430.00	20.00	344.00
M GUARD ASSY-FRONT WHEEL,RH	GRU	1.00	95.00	20.00	76.00
M LAMP ASSY-HEAD,RH	BR	1.00	1219.00	20.00	975.20
M RESERVOIR & PUMP ASSY-WASHER	X NAI	1.00	146.00	20.00	116.80
M COOLANT (4L)	NAI	1.00	26.00	23.00	20.02

SURVEYOR NAME: Steve CLKK 14/12/20, 2-09pm

SURVEYOR SIGNATURE: DD-NM AN

DATE: EXCISI - ?

REMARKS: 8 days

P/P

By BOL SM

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirm & accepted by

7% GST on **Nett** 10,039.22
702.75
Total Payable 10,741.97

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.