

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013774/ETF3E2
Date: 05/01/2021

REFERENCE

Insured/Claimant: ANG KIM HOCK Policy No: 2070111864
Date of Loss: 13/12/2020 Nature of Claim: OD Claim No: 1298302956SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMU1804B**
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH754831
Reg. Date: 30/07/2020 (Man. Year: 2020) Chassis No: KNAF5416ML5086981
Colour: Grey Odometer: 4459 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$90,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Nexen 5 mm Rear Left Side: Nexen 5 mm
Front Right Side: Nexen 5 mm Rear Right Side: Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,554.80	1,308.80	1,246.00	48.77
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,620.00	1,510.00	1,110.00	42.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	5,174.80	2,818.80	2,356.00	45.53
+ GST 7.00/7.00% (S\$)	362.24	197.32	164.92	45.53
Nett Amount (S\$)	5,537.04	3,016.12	2,520.92	45.53

INSPECTION

Date of Assignment: 14/12/2020
Date Inspected: 14/12/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 4.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*GUARD-REAR WHEEL, LH	Not Necessary	75.00 FL	*- FL
3	6		*NUT-PLUG	Not Necessary	12.00 FL	*- FL
4	1		*LAMP ASSY-REAR COMB OUTSIDE, LH	Broken	675.00 FL	*675.00 FL
5	1		*BRACKET ASSY-RR BPR SIDE UPR, L	Broken	25.00 FL	*25.00 FL
6	1		*BRACKET ASSY-RR BPR SIDE UPR, R	Not Necessary	31.00 FL	*- FL
7	1		*BEAM-RR BUMPER	Not Necessary	318.00 FL	*- FL
8	2		*BRACKET-RR BEAM LWR MTG	Not Necessary	12.00 FL	*- FL
9	1		*BRACKET-RR BEAM LWR, CTR	Not Necessary	6.00 FL	*- FL
10	1		*BRACKET-RR BEAM UPR MTG, LH	Not Necessary	9.00 FL	*- FL
11	1		*BRACKET-RR BEAM UPR MTG, RH	Not Necessary	9.00 FL	*- FL
12	1		*EXTN WIRING ASSY-BWS	Not Necessary	207.00 FL	*- FL
13	1		*LAMP ASSY-SIDE T/SIGNAL, LH	Not Necessary	181.00 FL	*- FL
14	1		*COVER-RR BUMPER FOG LAMP, LH	Cut	19.00 FL	*19.00 FL
15	2		*GROMMET ASSY-SCREW	Not Necessary	4.00 FL	*- FL
16	2		*RETAINER	Not Necessary	4.00 FL	*- FL
17	1		*COVER-RR BUMPER	Broken	651.00 FL	*651.00 FL
18	1		*COVER-RR BUMPER LWR	Crushed	241.00 FL	*241.00 FL
19	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
20	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
21	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL
22	1		*ULTRASONIC SENSOR ASSY-BWS	Not Necessary	163.00 FL	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	3,181.00	1,631.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	626.20	322.20
Total Parts (\$\$)	2,554.80	1,308.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REPAIR LH REAR FENDER, REPAIR REAR END PANEL	New	1,200.00	600.00
2	REMOVE AND INSTALL PARKING ASSIST	New	60.00	60.00
3	PAINT WORK SPRAY REAR END PANEL, REAR BUMPER FACE, LH REAR FENDER AND AFFECTED PORTION	New	1,050.00	700.00
4	PERFORM RUST PREVENTION	New	80.00	0.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
7	RE-APPLY BODY ZERTONA COATING	New	80.00	0.00
Gross Labour Cost (\$\$)			2,620.00	1,510.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >