



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12611/ANG KIM HOCK Reg No/Reg Date SMU1804B / 30/07/202 Date In/Mileage / 0 Chassis No KNAF5416ML5086981 Engine No G4FGKH754831 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX0000	Credit	14/12/2020/ 14:00	QUD	247 / DonBong	25764				
<b>Estimate</b>									
E PNT88000									1200.00
RENEW ACCIDENT DAMAGED PARTS ON REAR BUMPER FACE, REPAIR LH REAR FENDER, REPAIR REAR END PANEL									400
E PNT88000									60.00
REMOVE AND INSTALL PARKING ASSIST									700
E PNT98000									1050.00
PAINT WORK SPRAY REAR END PANEL, REAR BUMPER FACE, LH REAR FENDER AND AFFECTED PORTION									
M SUNDRY									80.00
PERFORM RUST PREVENTION									
A 54900099									30.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									
A 10028901									120.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST									
M SUNDRY									80.00
RE-APPLY BODY ZERTONA COATING (Provide Sales Agmt)									20
M SUNDRY									50.00
SUNDRIES									
M GUARD-REAR WHEEL, LH	X					1.00	75.00	20.00	60.00
M NUT-PLUG	X					6.00	2.00	20.00	9.60
M LAMP ASSY-REAR COMB OUTSIDE, LH						1.00	675.00	20.00	540.00
M BRACKET ASSY-RR BPR SIDE UP, L						1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UP, R	X					1.00	31.00	20.00	24.80
M BEAM-RR BUMPER	X					1.00	318.00	20.00	254.40
M BRACKET-RR BEAM LWR MTG	?					2.00	6.00	20.00	9.60
M BRACKET-RR BEAM LWR, CTR	X					1.00	6.00	20.00	4.80
M BRACKET-RR BEAM UP, MTG, LH	?					1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UP, MTG, RH	X					1.00	9.00	20.00	7.20
M EXTN WIRING ASSY-BWS	X					1.00	207.00	20.00	165.60
M LAMP ASSY-SIDE T/SIGNAL, LH	X					1.00	181.00	20.00	144.80
M COVER-RR BUMPER FOG LAMP, LH	?					1.00	19.00	20.00	15.20
M GROMMET ASSY-SCREW	/ NK					2.00	2.00	20.00	3.20

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE  
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV12611/ANG KIM HOCK Reg No/Reg Date SMU1804B / 30/07/202 Date In/Mileage / 0 Chassis No KNAF5416ML5086981 Engine No G4FGKH754831 Make/Model KIA/CERATO 1.6 A GT LINE H171 Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX00000	Credit	14/12/2020/ 14:00	QUD	247 / DonBong	25764				
Description of Goods / Services									
M	RETAINER					2.00	2.00	20.00	3.20
M	COVER-RR BUMPER	GR				1.00	651.00	20.00	520.80
M	COVER-RR BUMPER LWR	CR4				1.00	241.00	20.00	192.80
M	ULTRASONIC SENSOR ASSY-BWS	X				1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-BWS	X				1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-BWS	X				1.00	163.00	20.00	130.40
M	ULTRASONIC SENSOR ASSY-BWS	X				1.00	163.00	20.00	130.40

# Estimate

SURVEYOR NAME: Steve CLKK 14/12/20, 2:00pm  
 SURVEYOR SIGNATURE: OD - Nm AuthL  
Excess - ?  
 DATE: \_\_\_\_\_  
 REMARKS: 4 dys  
PIF  
Ry Bol spy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

Confirm & accepted by \_\_\_\_\_

- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged By Repairer

Authorized signatory and company stamp

	Nett	5,174.80
7% GST on	5174.80	362.24
<b>Total Payable</b>		<b>5,537.04</b>

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.