

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG20013779/ETF3E2
Date: 06/01/2021

REFERENCE

Insured/Claimant: LIN JINGQUAN Policy No: 2070050499
Date of Loss: 11/12/2020 Nature of Claim: OD Claim No: 1507638297SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SGC9002L
Make & Model: KIA CERATO, 1.6 (A) Engine No: G4FGKH741133
Reg. Date: 17/03/2020 (Man. Year: 2019) Chassis No: KNAF5416ML5063955
Colour: White Odometer: 3513 km
Engine Capacity: 1591 cc
Market Value/New Car Price: S\$88,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Cinturato 5 mm Rear Left Side: Cinturato 5 mm
Front Right Side: Cinturato 5 mm Rear Right Side: Cinturato 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,386.40	3,651.20	735.20	16.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,870.00	3,120.00	750.00	19.38
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,256.40	6,771.20	1,485.20	17.99
- Excess (S\$)	300.00	300.00	0.00	0.00
(S\$)	7,956.40	6,471.20	1,485.20	18.67
+ GST 7.00/7.00% (S\$)	556.95	452.98	103.97	18.67
Nett Amount (S\$)	8,513.35	6,924.18	1,589.17	18.67

INSPECTION

Date of Assignment: 14/12/2020
Date Inspected: 14/12/2020 Inspected At: Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339
Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PANEL,FENDER RH	Dented	430.00 FL	*430.00 FL
2	1		*INSULATOR-FENDER RH	Broken	27.00 FL	*27.00 FL
3	1		*PANEL ASSY-FRONT DOOR,RH	Dented	1,277.00 FL	*1,277.00 FL
4	1		*MOULDING ASSY-FRT DR FRAME,RH	Bent	72.00 FL	*72.00 FL
5	1		*WHEEL ASSY-ALUMINIUM	Cut	926.00 FL	*926.00 FL
6	1		*BLACK TAPE-FR DR RR,RH	Necessary	13.00 FL	*13.00 FL
7	1		*MIRROR ASSY-OUTSIDE RR VIEW RH	Cut	559.00 FL	*559.00 FL
8	1		*GUARD ASSY-FRONT WHEEL,RH	Not Necessary	95.00 FL	*- FL
9	1		*STRUT ASSY-FR,RH	Not Necessary	280.00 FL	*- FL
10	1		*BEARING-STRUT	Not Necessary	86.00 FL	*- FL
11	1		*HUB ASSY-FR WHEEL	Not Necessary	436.00 FL	*- FL
12	1		*ARM COMPLETE-FR LWR,RH	Bent	286.00 FL	*286.00 FL
13	1		*STAY RH	Not Necessary	22.00 FL	*- FL
14	1		*SUNDRY	Necessary	20.00 FS	*20.00 FS
15	1		*W/STRIP ASSY-FR DR BELT O/S RH (Supplementary)	Bent	80.00 FL	*80.00 FL
16	1		*W/STRIP ASSY-RR DR BELT O/S RH (Supplementary)	Bent	75.00 FL	*75.00 FL
17	1		*CLIPS(X12) (Supplementary)	Necessary	24.00 FL	*24.00 FL
18	1		*GEAR ASST-STEERUNG (Supplementary)	Bent	770.00 FL	*770.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,478.00	4,559.00
- List Item Discount on L Items 20.00/20.00% (S\$)	1,091.60	907.80
Total Parts (S\$)	4,386.40	3,651.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW FRT FENDER RH,FRT DOOR RH,REPAIR SIDE SKIRT RH,REAR FENDER RH	New	1,200.00	800.00
2	SPRAY PAINT FOR FRT FENDER RH,FRT DOOR RH,SIDE SILL RH,REAR FENDER RH	New	1,400.00	1,050.00
3	REMOVE & INSTALL FRT DOOR TRIMS AND GLASS	New	180.00	180.00
4	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
5	APPLY SEALANT FOR ACCIDENT PORTION	New	40.00	40.00
6	TRANSFER FRT RIGHT RIM	New	30.00	30.00
7	RENEW FRT UNDER CARRIAGE	New	400.00	400.00
8	CHECK WIRING & ELECTRICAL SYSTEM	New	30.00	30.00
9	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	120.00	120.00
10	RESPRAY ON RH REAR DOOR (Supplementary)	New	350.00	350.00
Gross Labour Cost (S\$)			3,870.00	3,120.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >