

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CS/AIG20013780/EQF3E2
Date: 30/12/2020

REFERENCE

Insured/Claimant:	WEE ZHI CONG	Policy No:	1900160447	Claim No:	0608321067SG
Date of Loss:	13/12/2020	Nature of Claim:	OD		

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMP1326R	Engine No:	G4FGJH720482
Make & Model:	KIA CERATO, 1.6 (A)	Chassis No:	KNAF3416MK5040719
Reg. Date:	12/09/2019 (Man. Year: 2018)	Odometer:	9038 km
Colour:	Black		
Engine Capacity:	1591 cc		
Market Value/New Car Price:	S\$70,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Nexen 5 mm	Rear Left Side:	Nexen 5 mm
Front Right Side:	Nexen 5 mm	Rear Right Side:	Nexen 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,430.00	2,030.40	1,399.60	40.80
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,490.00	2,980.00	2,510.00	45.72
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	8,920.00	5,010.40	3,909.60	43.83
+ GST 7.00/7.00% (S\$)	624.40	350.73	273.67	43.83
Nett Amount (S\$)	9,544.40	5,361.13	4,183.27	43.83

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 14/12/2020 Inspected At:

Cycle & Carriage KIA Pte Ltd (Pandan Gardens)
209 Pandan Gardens
Singapore 609339

Estimated Period of Repair: 6.0 days

Adjuster: CHEN TSUE YEE

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*COVER-FR BUMPER	Repair	633.00 FL	*- FL
3	1		*GRILLE-FRONT BUMPER	Not Necessary	262.00 FL	*- FL
4	1		*RETAINER-BUMPER SIDE MTG	Necessary	1.00 FL	*1.00 FL
5	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
6	1		*BRACKET-FR BUMPER UPR SIDE MTG	Not Necessary	22.00 FL	*- FL
7	1		*ORNAMENT-KIA NO.115	Necessary	32.00 FL	*32.00 FL
8	1		*PANEL-FENDER, RH	Dented	430.00 FL	*430.00 FL
9	1		*INSULATOR-FENDER RH	Not Necessary	27.00 FL	*- FL
10	1		*PANEL ASSY-FRONT DOOR, RH	Dented	1,277.00 FL	*1,277.00 FL
11	1		*BLACK TAPE-FR DR RR, RH	Necessary	13.00 FL	*13.00 FL
12	1		*MIRROR ASSY-OUTSIDE RR VIEW, RH	Cut	559.00 FL	*559.00 FL
13	1		*ARM COMPLETE-FR LWR, RH	Not Necessary	286.00 FL	*- FL
14	1		*HUB ASSY-FR WHEEL	Not Necessary	436.00 FL	*- FL
15	1		*HANDLE ASSY-DOOR OUTSIDE, RH	Cut	164.00 FL	*164.00 FL
16	1		*COVER-FR DR O/S HDL RH	Not Necessary	14.00 FL	*- FL
17	1		*PAD-FR DR O/S HDL COVER, RH	Not Necessary	5.00 FL	*- FL
18	1		*PAD-FR DR O/S HDL HINGE, RH	Not Necessary	5.00 FL	*- FL
19	1		*MOULDING ASSY - FRT DR FRAME, RH	Necessary	37.00 FL	*37.00 FL

(Supplementary)

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	4,275.00	2,533.00
- List Item Discount on L Items 20.00/20.00% (\$)	845.00	502.60
Total Parts (\$)	3,430.00	2,030.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, RH FRONT FENDER, RH FRONT DOOR, RH SIDE MIRROR, REPAIR RH REAR DOOR	New	2,000.00	800.00
2	LABOUR TRANSFER RH FRONT DOOR GLASS, DOOR MECHANISM, DOOR TRIM AND OTHER ATTACHMENT TO NEW DOOR PANEL	New	120.00	120.00
3	PAINT WORK SPRAY FRONT BUMPER FACE, RH FRONT FENDER, RH FRONT DOOR, RH SIDE MIRROR, RH REAR DOOR AND AFFECTED PORTION	New	1,750.00	1,050.00
4	APPLY BODY SEALANT	New	80.00	40.00
5	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM	New	30.00	30.00
6	PERFORM RUST PREVENTION	New	80.00	40.00
7	RENEW FRONT UNDERCARRIAGE DAMAGES	New	400.00	0.00
8	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT	New	120.00	120.00
9	SUPPLY RH FRONT SPORT RIM	New	400.00	400.00
10	RE-APPLY LTA BREAK SEAL AND RESEAL FOR FRONT NUMBER PLATE	New	80.00	0.00
11	SUPPLY FRONT NUMBER PLATE WITH FRAME	New	50.00	0.00
12	LABOUR RENEW RH FRONT RIM INCLUDING BALANCING	New	30.00	30.00
13	RESPRAY ON RH SIDE SILL (Supplementary)	New	350.00	350.00
Gross Labour Cost (\$\$)			5,490.00	2,980.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >