



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address		Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000		Cust No/Name Reg No/Reg Date Date In/Mileage Chassis No Engine No Make/Model Colour/Trim	LCV11102/WEE ZHI CONG (HUANG ZHICONG) SMP1326R / 12/09/201 / 9038 KNAF3416MK5040719 G4FGJH720482 KIA/CERATO 1.6 A EX G333 ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	Qty	Unit Price	Disc%	Amount
LAX00000	Credit	14/12/2020/ 14:36	QUD	247 / DonBong	25767				
Description of Goods / Services									
E PNT88000									800 2000.00
RENEW ACCIDENT DAMAGED PARTS ON FRONT BUMPER FACE, 400 x 2									
RH FRONT FENDER, RH FRONT DOOR, RH SIDE MIRROR,									120.00
REPAIR RH REAR DOOR									
E PNT88000									1050 1750.00
LABOUR TRANSFER RH FRONT DOOR GLASS, DOOR MECHANISM,									
DOOR TRIM AND OTHER ATTACHMENT TO NEW DOOR PANEL									
E PNT98000									350 x 3
PAINT WORK SPRAY FRONT BUMPER FACE, RH FRONT FENDER,									
RH FRONT DOOR, RH SIDE MIRROR, RH REAR DOOR									40 80.00
AND AFFECTED PORTION									
M SUNDRY									30.00
APPLY BODY SEALANT									
A 54900099									40 80.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM									
M SUNDRY									3 X 400.00
PERFORM RUST PREVENTION									
A 20000001									120.00
RENEW FRONT UNDERCARRIAGE DAMAGES									
A WHEELALIGNMENTBP									400.00
To Conduct Computerize Full Wheel Alignment									
M SUNDRY									3 X 80.00
SUPPLY RH FRONT SPORT RIM									
M SUNDRY									3 X 50.00
RE-APPLY LTA BREAK SEAL AND RESEAL FOR FRONT NUMBER PLATE									
M SUNDRY									30.00
SUPPLY FRONT NUMBER PLATE WITH FRAME									
M SUNDRY									20 50.00
LABOUR RENEW RH FRONT RIM INCLUDING BALANCING									
M SUNDRY									
SUNDRIES									1.00 633.00 20.00 506.40
M COVER-FR BUMPER	X					1.00	262.00	20.00	209.60
M GRILLE-FRONT BUMPER	X								

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE
209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV11102/WEE ZHI CONG (HUANG ZHICONG) Reg No/Reg Date SMP1326R / 12/09/201 Date In/Mileage / 9038 Chassis No KNAF3416MK5040719 Engine No G4FGJH720482 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim ABP AURORA BLACK / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	14/12/2020/ 14:36	QUD	247 / DonBong	25767			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	RETAINER-BUMPER SIDE MTG				1.00	1.00	20.00	0.80
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M	BRACKET-FR BUMPER UPR SIDE MTG				1.00	22.00	20.00	17.60
M	ORNAMENT-KIA NO.115				1.00	32.00	20.00	25.60
M	PANEL-FENDER,RH				1.00	430.00	20.00	344.00
M	INSULATOR-FENDER RH				1.00	27.00	20.00	21.60
M	PANEL ASSY-FRONT DOOR,RH				1.00	1277.00	20.00	1021.60
M	BLACK TAPE-FR DR RR,RH				1.00	13.00	20.00	10.40
M	MIRROR ASSY-OUTSIDE RR VIEW,RH				1.00	559.00	20.00	447.20
M	ARM COMPLETE-FR LWR,RH				1.00	286.00	20.00	228.80
M	HUB ASSY-FR WHEEL				1.00	436.00	20.00	348.80
M	HANDLE ASSY-DOOR OUTSIDE,RH				1.00	164.00	20.00	131.20
M	COVER-FR DR O/S HDL RH				1.00	14.00	20.00	11.20
M	PAD-FR DR O/S HDL COVER,RH				1.00	5.00	20.00	4.00
M	PAD-FR DR O/S HDL HINGE,RH				1.00	5.00	20.00	4.00

SURVEYOR NAME: Steve CLKK 14/12/20, 3.00pm

SURVEYOR SIGNATURE: DD - N/A Auth

DATE: Express - ?

REMARKS: P/P

By Bel sy
6 days

LKK Auto Consultants hence notify the Repairer of the following:

- Confirm & accepted by
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Authorized signatory and company stamp

7% GST on **8,540.40** **597.83**

Total Payable 9,138.23

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.