

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CS3/AIG20013782/GVF3E2

**Date:** 04/02/2021

### REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2070014080		
<b>Claimant Vehicle No :</b>	SFG1050R	<b>Insured Vehicle No :</b>	SFE5766T		
Date of Loss:	10/12/2020	Nature of Claim:	TP	Claim No:	6262015703SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SFG1050R</b>	Engine No:	L13B14101104
Make & Model:	HONDA JAZZ, 1.3 CVT (A)	Chassis No:	JHMGK3850KS214220
Reg. Date:	29/04/2019 (Man. Year: 2019)	Odometer:	33257 km
Colour:	Grey		
Engine Capacity:	1318 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	175/65 R15	Rear Tyre Size:	175/65 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Nett Amount (S\$)</b>	<b>0.00</b>	<b>0.00</b>	<b>0.00</b>	

### INSPECTION

Date of Assignment:	14/12/2020	Garage 13 Pte Ltd (HQ)
Date Inspected:	15/12/2020 Inspected At:	8 Kaki Bukit Ave 4, Premier @ Kaki Bukit, #03-46
Estimated Period of Repair:	5.0 days	Singapore 415875

**Adjuster:** XING GUO QIANG

**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	0.00 F	*- F
2	1		*REAR BUMPER CLIPS	Necessary	0.00 F	*- F
3	2		*REAR BUMPER SIDE RETAINER	Deformed	0.00 F	*- F
4	1		*REAR BUMPER GARNISH	Deformed	0.00 F	*- F
5	1		*REAR BUMPER MOULDING	Deformed	0.00 F	*- F
6	1		*REVERSE SENSOR	Damaged	0.00 F	*- F
7	1		*REAR END PANEL	Buckled	0.00 F	*- F
8	1		*REAR END PANEL TOP GARNISH	Deformed	0.00 F	*- F
9	1		*REAR LH TAILLAMP	Cracked	0.00 F	*- F
10	1		*REAR LH TAILLAMP PANEL	Buckled	0.00 F	*- F
11	1		*REAR RH TAILLAMP	Cut	0.00 F	*- F
12	1		*TAILGATE	Buckled	0.00 F	*- F
13	1		*TAILGATE EMBLEM	Necessary	0.00 F	*- F
14	1		*TAILGATE OUTER HANDLE	Broken	0.00 F	*- F
15	2		*TAILGATE LAMP	Cut	0.00 F	*- F
16	1		*TAILGATE GLASS MOULDING	Necessary	0.00 F	*- F
17	1		*TAILGATE GLASS SEALANT	Necessary	0.00 F	*- F
18	1		*TAILGATE LOCK	Bent	0.00 F	*- F
19	1		*TAILGATE RUBBER	Twisted	0.00 F	*- F
20	1		*TAILGATE INNER BOARD	Deformed	0.00 F	*- F
21	1		*SPARE TYRE BOARD	Bent	0.00 F	*- F
22	1		*SPARE TYRE PANEL	Repair	0.00 F	*- F
23	1		*SPARE TYRE SPONGE	Deformed	0.00 F	*- F
24	1		*SPARE TYRE COVER	Deformed	0.00 F	*- F
25	1		*REAR LH FENDER	Repair	0.00 F	*- F
26	1		*REAR LH FENDER INNER TRIM	Deformed	0.00 F	*- F
27	1		*REAR LH DOOR	Repair	0.00 F	*- F
28	1		*REAR LH DOOR LOCK	Damaged	0.00 F	*- F

F=Franchise part.

Total Parts (S\$)					0.00	0.00
-------------------	--	--	--	--	------	------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.
---

< END OF ESTIMATES >