

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PRE-REPAIR INSPECTION REPORT

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	LONPAC INSURA	NCE BHD		Ref:	CS3/LPC20013784/Gqd3e2	
	300 BEACH ROAD #17-04/07 THE CC	NCOURSESINGAPORE 199555		Date:	28/12/2020	
				Code:	LPC2	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	GBD 377T	Veh. Inspected	t	SJV 9577Y	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	20/20/20/VC05/024001	Excess (\$)		0.00	
	Assign From	GERALD POH	Assign Date		14/12/2020	
2.	Vehicle Particulars & Condition					
	Make & Model	KIA CERATO FORTE 1.6	c.c		1591	
	Engine No.	HIDDEN	Year of Reg.		2010	
	Chassis No.	KNAFW611MA5203927	Colour		BLUE	
	Odometer	132132 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	YOKOHAMA		6 mm	
	L/H Front Tyre	215/45 R17	YOKOHAMA		6 mm	
	R/H Rear Tyre	215/45 R17	YOKOHAMA		6 mm	
	L/H Rear Tyre	215/45 R17	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	E VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	11/12/2020	Inspect Date /	Time	15/12/2020 (12:30 PM)	
	Survey held at	EVERDAWN AUTO SERVICE				
		8 KAKI BUKIT AVE 4 #01-02 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.		Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					

Report Ref No. CS3/LPC20013784/Gqd3e2

Inspected By

XING GUO QIANG

K.K.LAU CPT(RET)

M.MATAI, AMSAE-A

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor