

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013786/DPA3Q2

Date: 09/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900259120

Claimant
Vehicle No : SKX5515S **Insured Vehicle No :** SMQ7561H

Date of Loss: 12/12/2020 Nature of Claim: TP Claim No: 5943503368SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKX5515S		
Make & Model:	MAZDA 3, 1.5 L 4-DOOR SEDAN SP.6EAT (A)	Engine No:	P520336863
Reg. Date:	17/12/2015 (Man. Year: 2015)	Chassis No:	JM6BM42A8G0328235
Colour:	Grey	Odometer:	61066 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Toyo 5 mm	Rear Left Side:	Toyo 5 mm
Front Right Side:	Toyo 5 mm	Rear Right Side:	Toyo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,974.48	5,186.24	9,788.24	65.37
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,390.00	1,920.00	4,470.00	69.95
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	21,364.48	7,106.24	14,258.24	66.74
Approved Total (Overridden) (S\$)		5,600.00		
(S\$)	21,364.48	5,600.00	15,764.48	73.79
+ GST 7.00/7.00% (S\$)	1,495.51	392.00	1,103.51	73.79
Nett Amount (S\$)	22,859.99	5,992.00	16,867.99	73.79
+ Car Rental (6.0 x S\$100.00/day) (S\$)		600.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		120.00		
Nett Liability (S\$)		6,748.45		
Global Sum Settlement (S\$)		6,600.00		

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 15/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 6.0 days

Adjuster: BRYAN TANI

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	1,204.00 FL	*- FL
2	1		*BOOTLID MAZDA LOGO	Not Necessary	97.00 FL	*- FL
3	1		*BOOTLID MAZDA 3 EMBLEM	Not Necessary	78.00 FL	*- FL
4	1		*BOOTLID SKYACTIV EMBLEM	Not Necessary	86.00 FL	*- FL
5	1		*BOOTLID LAMP LH	Not Necessary	499.00 FL	*- FL
6	1		*TAIL LAMP LH	Cut / Scratched	1,190.00 FL	*473.00 FL
7	1		*TAIL LAMP PANEL LH	Not Necessary	495.00 FL	*- FL
8	1		*TAIL LAMP LOWER BRACKET LH	Not Necessary	175.00 FL	*- FL
9	1		*REAR BUMPER	Dented / Cut	1,227.00 FL	*998.00 FL
10	1		*REAR BUMPER SIDE RETAINER LH/RH	N/S Bent / O/S Not Necessary	152.00 FL	*76.00 FL
11	1		*REAR FENDER LH	Dented	1,832.00 FL	*1,129.30 FL
12	1		*REAR FENDER INNER SHIELD LH	Not Necessary	236.00 FL	*- FL
13	1		*REAR FENDER AIR DUCT LH	Deformed	91.70 FL	*91.70 FL
14	1		*REAR FENDER INNER TRIM LH	Not Necessary	446.00 FL	*- FL
15	1		*REAR WHEEL HOUSING LH	Not Necessary	1,482.00 FL	*- FL
16	1		*REAR RIM LH	Distorted / Cut	1,248.00 FS	*500.00 FS
17	1		*REAR WHEEL BEARING & HUB ASSY LH	Damaged	573.00 FL	*256.20 FL
18	1		*REAR LOWER ARM LH	Distorted	313.00 FL	*313.00 FL
19	1		*REAR KNUCKLE ARM LH	Distorted	498.00 FL	*498.00 FL
20	1		*REAR ABSORBER LH	Distorted	383.00 FL	*383.00 FL
21	1		*REAR DOOR LH	Not Necessary	1,284.00 FL	*- FL
22	1		*REAR DOOR WINDOW MOULDING LH	Not Necessary	312.00 FL	*- FL
23	1		*REAR DOOR CHROME MOULDING LH	Not Necessary	331.00 FL	*- FL
24	1		*REAR DOOR BLACK PLASTIC MOULDING LH	Not Necessary	191.00 FL	*- FL
25	2		*REAR DOOR HINGE LH	Not Necessary	186.00 FL	*- FL
26	1		*REAR DOOR WEATHERSTRIP LH	Not Necessary	151.00 FL	*- FL
27	1		*REAR DOOR INNER TRIM BOARD LH	Not Necessary	673.00 FL	*- FL
28	1		*REAR WINDSCREEN MOULDING	Necessary	319.00 FL	*185.60 FL
29	1		*REAR END PANEL	Dented	846.00 FL	*559.60 FL
30	1		*REAR ASSIST ARM	Distorted	357.00 FL	*357.00 FL
31	1		*REAR UPPER ARM	Distorted	587.90 FL	*224.90 FL
32	1		*TAIL LAMP CLIPS	Not Necessary	50.00 FS	*- FS
33	1		*REAR FENDER SEALANT	Necessary	80.00 FS	*40.00 FS
34	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
35	1		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
36	1		*REAR WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
37	1		*REAR FENDER INNER SHIELD CLIPS	Not Necessary	50.00 FS	*- FS
38	1		*REAR DOOR INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
39	1		*TYRE (50%)	Punctured / Torn	300.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) 18,233.60 **6,295.30**
- List Item Discount on L Items 20.00/20.00% (\$\$) 3,259.12 1,109.06
Total Parts (\$\$) 14,974.48 **5,186.24**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	300.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	New	2,000.00	700.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	New	2,000.00	700.00
4	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
5	TO RNR REVERSE CAMERA	New	100.00	0.00
6	TO RNR REAR UNDERCARRIAGE TO FACILITATE REPAIRS	New	250.00	150.00
7	TO CONDUCT COMPUTERIZED 4 WHEEL ALIGNMENT	New	120.00	60.00
8	TO RNR REAR WINDSCREEN TO ASSIST WORK LOAD	New	250.00	120.00
9	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	New	200.00	0.00
10	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	New	250.00	0.00
11	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
12	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
13	TO RNR REVERSE SENSOR TO ASSIST WORK LOAD	New	120.00	40.00
Gross Labour Cost (\$\$)			6,390.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >