

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC3/AIG20013792/KBA3Q2

Date:

06/09/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

2100111583

Claimant Vehicle No : SHF748A**Insured Vehicle No :**

SJM1714E

Date of Loss: 09/12/2020

Nature of Claim:

TP

Claim No:

0594482047SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SHF748A**

Make & Model: RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)

Engine No:

M9R8839C002715

Reg. Date: 30/06/2016 (Man. Year: 2015)

Chassis No:

VF1ABL15AUC282205

Colour: Metallic White/Red

Odometer:

538645 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16

Rear Tyre Size:

215/60 R16

Front Left Side: Sailun 9 mm

Rear Left Side:

Sailun 9 mm

Front Right Side: Sailun 9 mm

Rear Right Side:

Sailun 9 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	4,746.55	1,131.87	3,614.68	76.15
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,360.00	880.00	3,480.00	79.82
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,106.55	2,011.87	7,094.68	77.91
Approved Total (Overridden) (S\$)		1,600.00		

(S\$)	9,106.55	1,600.00	7,506.55	82.43
+ GST 7.00/7.00% (S\$)	637.46	112.00	525.46	82.43
Nett Amount (S\$)	9,744.01	1,712.00	8,032.01	82.43
Global Sum Settlement (S\$)	0.00			

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020

Estimated Period of Repair: 2.0 days

Inspected At: Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Adjuster: KENNETH KONG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER FRT	Buckled	747.20 FL	*747.20 FL
2	1		*BUMPER SPOILER FRT	Serviceable	344.70 FL	*- FL
3	1		*BUMPER BEAM FRT	Repair	663.70 FL	*- FL
4	1		*BUMPER ABSORBER FRT	Serviceable	394.68 FL	*- FL
5	1		*BUMPER BRACKET KIT FRT RH	Serviceable	101.40 FL	*- FL
6	1		*BUMPER RETAINER FRT RH	Serviceable	101.40 FL	*- FL
7	1		*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*- FL
8	1		*HEADLAMP RH	Serviceable	743.60 FL	*- FL
9	1		*FENDER PANEL FRT RH	Bent	437.10 FL	*437.10 FL
10	1		*FENDER BRACKET FRT RH	Serviceable	106.40 FL	*- FL
11	1		*WHEELARCH FRT RH	Serviceable	191.40 FL	*- FL
12	1		*WIPER RESERVOIR	Serviceable	179.60 FL	*- FL
13	1		*BUMPER CLIP FRT	Necessary	90.00 FS	*66.00 FS
14	1		*BUMPER RETAINER CLIP FRT	Not Necessary	75.00 FS	*- FS
15	1		*WHEELARCH CLIP FRT	Not Necessary	75.00 FS	*- FS
16	1		*TYRE	Serviceable	300.00 FS	*- FS
17	1		*TYRE RIM	Serviceable	350.00 FS	*- FS
18	1		*FENDER SCREW	Serviceable	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	5,168.39	1,250.30
- List Item Discount on L Items 10.00/10.00% (\$\$)	421.84	118.43
Total Parts (\$\$)	4,746.55	1,131.87

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO RUST-PROOFING AND APPLY UNDERCOAT OF THE AFFECTED AREAS	New	230.00	30.00
2	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
3	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	1,400.00	440.00
4	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	2,000.00	400.00
5	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
6	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	10.00
7	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
Gross Labour Cost (S\$)			4,360.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >