

ESTIMATE

Date : 25/11/2020
Insurance : EQ INSURANCE COMPANY LTD.
Vehicle / Mobile : *Not Notified*
Mail Address : *11 Sep 8525dp*
Running After Point
Company : GOLDBELL ENGINEERING PTE LTD
Contact : KONYINSIEW
Mobile : +65 6861 0007
Fax : KonYinSiew@goldbell.com.sg

Reg No : SGS3631B
Model : MITSUBISHI LANCER 1.6 A
Chassis No : JMYSTCS3A7U005354
Engine No : 4G18HS0321
Quotation No. : 122537
Ref. No. :
D.O.A. : 24/11/2020
Policy No. : DMPCSNAA00022712006
Claim Type : TP CLAIM - EQ
Workshop : 8 TUAS AVE 18

Part No	Description	Qty	U/Price	%	Net Price	Ext Price
	BONNET <i>789</i>	1	986.30	-10	887.67	887.67 ✓
	BONNET LOCK	1	256.30	-10	230.67	230.67 X
	BONNET HINGE LH <i>110</i>	1	155.10	-10	139.59	139.59 ✓
	BONNET HINGE RH	1	155.10	-10	139.59	139.59 X
	FRONT GRILLE	2	223.50	-10	201.15	402.30 X
	FRONT EMBLEM	1	65.80	-10	59.22	59.22 ✓
	FRONT BUMPER <i>729</i>	1	796.30	-10	716.67	716.67 ✓
	FRONT BUMPER RETAINER LH	1	35.00	-10	31.50	31.50 ✓
	FRONT BUMPER RETAINER RH	1	35.00	-10	31.50	31.50 ✓
	FRONT FOG LAMP LH	1	240.00	-10	216.00	216.00 X
	FRONT FOG LAMP RH	1	240.00	-10	216.00	216.00 X
	FRONT FOG LAMP COVER LH	1	75.00	-10	67.50	67.50 ✓
	FRONT FOG LAMP COVER RH	1	75.00	-10	67.50	67.50 ✓
	FRONT BUMPER LOWER SKIRT	1	480.00	-10	432.00	432.00 ✓
	HEADLAMP LH <i>658</i>	1	875.00	-10	787.50	787.50 ✓
	HEADLAMP RH	1	875.00	-10	787.50	787.50 X
	HEADLAMP BRACKET PANEL LH	1	199.60	-10	179.64	179.64 ✓
	HEADLAMP BRACKET PANEL RH	1	199.60	-10	179.64	179.64 ✓
	FRONT REINFORCEMENT <i>313</i>	1	497.60	-10	447.84	447.84 ✓
	FRONT FENDER LH	1	480.00	-10	432.00	432.00 ✓
	FRONT FENDER INNER SHEILD LH <i>107</i>	1	178.40	-10	160.56	160.56 ✓

PARTS TOTAL :

6,612.39

NETT ITEMS

FRONT FENDER INNER SHIELD CLIPS (SET)	1	30.00	✓
FRONT BUMPER CLIPS (SET)	1	30.00	✓
FRONT TYRE LH (195/60 R15)	1	150.00	X
FRONT RIM LH	1	250.00	X
FRONT GRILLE CLIPS (SET)	1	30.00	X

PARTS TOTAL:

490.00

ESTIMATE

25/11/2020
EQ INSURANCE COMPANY LTD.

Reg No : SGS3631B
Model : MITSUBISHI LANCER 1.6 A
Chassis No : JMYSTCS3A7U005354
Engine No : 4G18HS0321
Quotation No. : 122537
Ref. No. :
D.O.A. : 24/11/2020
Policy No. : DMPCSNA00022712006
Claim Type : TP CLAIM - EQ
Workshop : 8 TUAS AVE 18

GOLDBELL ENGINEERING PTE LTD
KONYINSIEW
+65 6861 0007
KonYinSiew@goldbell.com.sg

TO REMOVE, REFIX & REPAIR
AFFECTED DAMAGED PARTS.
INCLUDING KNOCK OUT, WELD AND
STRAIGHTEN ON THE AFFECTED PARTS
TO REPAIR AND ALIGN RH FRONT
FENDER
TO CHECK AND RECONNECT ALL
NECESSARY WIRING
TO PUTTY, CLEAN, SPRAY PAINT AND
POLISH, ETC
TO CONDUCT FOUR WHEEL ALIGNMENT

12001
2400.00

nn 150.00 X

201 150.00

14001 2100.00

nn 100.00 X

LABOUR TOTAL :	4,900.00
SUB-TOTAL :	12,002.39
GST @ 7% for \$ 12,002.39	840.17
GRAND TOTAL (S\$) :	12,842.56

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: