

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/ICS20013796/ATD3E2
Date: 27/01/2021

REFERENCE

Handling Insurer: ECICS Limited Policy No:
Claimant Vehicle No : SMV1241U **Insured Vehicle No :** SJD5029X
Date of Loss: 12/12/2020 Nature of Claim: TP Claim No: DMPC2000240H/CT

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMV1241U**
Make & Model: KIA CERATO, 1.6 SUNROOF (A) Engine No: G4FGKH740268
Reg. Date: 17/09/2020 (Man. Year: 2019) Chassis No: KNAF5416ML5064431
Colour: Silver Odometer: 2834 km
Engine Capacity: 1591 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45 R17 Rear Tyre Size: 225/45 R17
Front Left Side: Pirelli 6 mm Rear Left Side: Pirelli 6 mm
Front Right Side: Pirelli 6 mm Rear Right Side: Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,465.10	5,766.60	2,698.50	31.88
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,450.00	730.00	720.00	49.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	9,915.10	6,496.60	3,418.50	34.48
Approved Total (Overridden) (S\$)		5,200.00		
Nett Amount (S\$)	9,915.10	5,200.00	4,715.10	47.55

INSPECTION

Date of Assignment: 14/12/2020
Date Inspected: 15/12/2020 Inspected At: Advance Auto Garage
10 Kaki Bukit Road 2, #01-21 First East Centre
Singapore 417868
Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jan 2021)
Parts: 143	KIA CERATO 1.6 SUNROOF (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMV1241U)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	633.00 FL	*633.00 FL
2	2		*FRONT BUMPER SIDE HOLDER	Necessary	56.00 FL	*56.00 FL
3	1		*FRONT BUMPER TOW COVER	Deformed	29.00 FL	*29.00 FL
4	1		*FRONT BUMPER LOGO	Necessary	38.00 FL	*38.00 FL
5	1		*FRONT BUMPER LOWER GARNISH	Deformed	241.00 FL	*241.00 FL
6	1		*FRONT BUMPER LAMP RH	Cracked	143.00 FL	*143.00 FL
7	1		*FRONT BUMPER LAMP COVER RH	Cracked	89.00 FL	*89.00 FL
8	1		*FRONT BUMPER AIR GUIDE RH	Deformed	45.00 FL	*45.00 FL
9	1		*FRONT BUMPER FOG LAMP RH	Cracked	303.00 FL	*303.00 FL
10	1		*FRONT BUMPER LOWER GRILLE	Deformed	262.00 FL	*262.00 FL
11	1		*FRONT BUMPER SENSOR	Damaged (1Pc Only)	450.00 FL	*225.00 FL
12	1		*FRONT BUMPER REINFORCEMENT	Bent	497.00 FL	*497.00 FL
13	1		*FRONT BUMPER LOWER ARM	Cracked	114.00 FL	*114.00 FL
14	1		*FRONT BUMPER SPONGE	Cracked	105.00 FL	*105.00 FL
15	1		*FRONT GRILLE	Cracked	328.00 FL	*328.00 FL
16	1		*HEADLAMP	O/S Cracked	4,420.00 FL	*2,210.00 FL
17	1		*FRONT RH FENDER	Repair	430.00 FL	*- FL
18	1		*FRONT RH FENDER INNER SHIELD	Torn	156.00 FL	*156.00 FL
19	1		*FRONT NUMBER PLATE	Bent	30.00 FS	*30.00 FS
20	1		*FRONT NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
21	1		*SET FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
22	1		*FRONT BUMPER LOWER SPOILER	Deformed	800.00 FS	*700.00 FS
23	1		*SET FRONT GRILLE CLIPS	Necessary	20.00 FS	*20.00 FS
24	1		*SET FRONT RH FENDER INNER SHIELD CLIPS	Necessary	30.00 FS	*30.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	9,299.00	6,314.00
- List Item Discount on L Items 10.00/10.00% (\$)	833.90	547.40
Total Parts (\$)	8,465.10	5,766.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING, REMOVE AND REFIT PARTS	New	600.00	400.00
2	SPRAY PAINTING TO AFFECTED AREA	New	600.00	250.00
3	WIRING CHECK	New	50.00	30.00
4	TO APPLY TUFF COAT	New	100.00	0.00
5	TO REMOVE FRONT BUMPER SENSOR	New	100.00	50.00
			Gross Labour Cost (\$\$)	730.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >