

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20013797/TPA3Q2**Date:** 10/08/2022REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800127031
Claimant Vehicle No :	SLJ466U	Insured Vehicle No :	SME9610A
Date of Loss:	06/12/2020	Nature of Claim:	TP
		Claim No:	7850177162SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ466U		
Make & Model:	TOYOTA COROLLA ALTIS, 1.6 CLASSIC CVT (A)	Engine No:	1ZRY345544
Reg. Date:	28/11/2016 (Man. Year: 2016)	Chassis No:	MR053REH104562051
Colour:	Silver	Odometer:	256110 km
Engine Capacity:	1598 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,385.79	986.96	4,398.83	81.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	460.00	2,740.00	85.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,585.79	1,446.96	7,138.83	83.15
Approved Total (Overridden) (S\$)		1,100.00		
(S\$)	8,585.79	1,100.00	7,485.79	87.19
+ GST 7.00/7.00% (S\$)	601.01	77.00	524.01	87.19
Nett Amount (S\$)	9,186.80	1,177.00	8,009.80	87.19
Global Sum Settlement (S\$)		0.00		

INSPECTION

Date of Assignment:	14/12/2020	
Date Inspected:	14/12/2020	Inspected At: Teamwork Garage Pte Ltd (HQ) 53 Ubi Ave 1 #01-24, Paya Ubi Industrial Park Singapore 408934
Estimated Period of Repair:	2.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Not Necessary	822.50 FL	*- FL
2	1		*BOOTLID EMBLEM LOGO	Not Necessary	69.00 FL	*- FL
3	1		*BOOTLID EMBLEM COROLLA	Not Necessary	46.00 FL	*- FL
4	1		*BOOTLID EMBLEM ALTIS	Not Necessary	50.60 FL	*- FL
5	1		*BOOTLID CHROME GARNISH	Not Necessary	265.65 FL	*- FL
6	1		*BOOTLID LICENCE PLATE LAMP	Not Necessary	72.40 FL	*- FL
7	2		*BOOTLID LAMP	Not Necessary	763.36 FL	*- FL
8	2		*BOOTLID LAMP INNER SEAL	Not Necessary	64.40 FL	*- FL
9	1		*BOOTLID LOCK	Not Necessary	437.00 FL	*- FL
10	1		*BOOTLID LOCK CATCH	Not Necessary	23.00 FL	*- FL
11	1		*BOOTLID INNER TRIM	Not Necessary	396.75 FL	*- FL
12	1		*BOOTLID WEATHERSTRIP	Not Necessary	281.30 FL	*- FL
13	1		*END PANEL	Not Necessary	672.75 FL	*- FL
14	1		*END PANEL TOP GARNISH	Not Necessary	241.50 FL	*- FL
15	1		*REAR BUMPER	Deformed	557.75 FL	*557.75 FL
16	1		*REAR BUMPER RETAINER	N/SNecessary /O/SNot Necessary	130.00 FL	*65.00 FL
17	2		*REAR BUMPER REFLECTOR	Not Necessary	181.20 FL	*- FL
18	2		*REAR BUMPER BRACKET	Not Necessary	149.50 FL	*- FL
19	1		*REAR BUMPER REINFORCEMENT	Bent	453.20 FL	*453.20 FL
20	4		*PDC SENSOR	Not Working	722.20 FL	*200.00 FL
21	1		*SENSOR WIRE HARNESS	Not Necessary	381.00 FL	*- FL
22	1		*SET REAR BUMPER CLIP	Necessary	40.00 FS	*30.00 FS
23	1		*SET REAR FENDER INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
24	1		*SET REAR BUMPER PLATE	Not Necessary	70.00 FS	*- FS
25	1		*SET END PANEL GARNISH CLIP	Not Necessary	30.00 FS	*- FS
26	1		*SET BOOTLID INNER TRIM CLIP	Not Necessary	30.00 FS	*- FS
27	1		*JOINT SEALANT	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	7,081.06	1,305.95
- List Item Discount on L Items 25.00/25.00% (\$)	1,695.27	318.99
Total Parts (\$)	5,385.79	986.96

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK REAR WIRING AND LIGHTING SYSTEM	New	60.00	30.00
2	REMOVE,REFIT REAR LINING TRIM AND GARNISH	New	200.00	0.00
3	REMOVE,RENEW REAR REVERSE SENSOR	New	120.00	30.00
4	REMOVE AND RENEW REAR EXHAUST	New	120.00	0.00
5	TRANSFER PARTS ,ATTACHMENT FROM OLD BOOTLID TO NEW	New	200.00	0.00
6	PANEL BEATING ON AFFECTED AREAS	New	1,200.00	200.00
7	SPRAY PAINTING ON AFFECTED AREAS	New	1,200.00	200.00
8	APPLY ANTI RUST ON AFFECTED AREAS	New	100.00	0.00
Gross Labour Cost (\$\$)			3,200.00	460.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >