

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC3/AIG20013801/KGS3Q2
Date: 27/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900149727
Claimant Vehicle No :	SHD923X	Insured Vehicle No :	SMN4993E
Date of Loss:	09/12/2020	Nature of Claim:	TP
		Claim No:	1576745649SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD923X		
Make & Model:	RENAULT LATITUDE, 2.0 DCI AUTO D/AB 4DR (A)	Engine No:	M9R8839C003342
Reg. Date:	29/12/2017 (Man. Year: 2015)	Chassis No:	VF1ABL15AUC283389
Colour:	Metallic White/Red	Odometer:	219385 km
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Sailun 9 mm	Rear Left Side:	Sailun 9 mm
Front Right Side:	Sailun 9 mm	Rear Right Side:	Sailun 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,045.47	1,880.30	6,165.17	76.63
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,370.00	775.00	6,595.00	89.48
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,415.47	2,655.30	12,760.17	82.78
Approved Total (Overridden) (S\$)		2,100.00		

(S\$)	15,415.47	2,100.00	13,315.47	86.38
+ GST 7.00/7.00% (S\$)	1,079.08	147.00	932.08	86.38
Nett Amount (S\$)	16,494.55	2,247.00	14,247.55	86.38
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$81.13/day) (S\$)		243.39		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		2,647.84		

INSPECTION

Date of Assignment: 10/12/2020

Date Inspected: 10/12/2020

Inspected At:

Trans-cab Auto Services Pte Ltd (Ang Mo Kio)
2, Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 FL
2	1		*BUMPER LOWER REAR	Buckled / Dented	411.90 FL	*411.90 FL
3	1		*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*- FL
4	1		*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*- FL
5	1		*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- FL
6	1		*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- FL
7	1		*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- FL
8	1		*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 FL
9	1		*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- FL
10	1		*BUMPER BEAM BRACKET RH REAR	Repair	114.50 FL	*- FL
11	1		*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- FL
12	1		*BUMPER REFLECTOR RH	Cracked	16.60 FL	*16.60 FL
13	1		*OUTER PANEL REAR (END PANEL)	Repair	745.80 FL	*- FL
14	1		*OUTER PANEL REAR (END PANEL)TRIM	Cracked	404.56 FL	*404.56 FL
15	1		*BOOT REAR	Repair	1,677.20 FL	*- FL
16	1		*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- FL
17	1		*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- FL
18	1		*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- FL
19	1		*BOOT HINGE LH	Repair	254.20 FL	*- FL
20	1		*BOOT HINGE RH	Repair	254.20 FL	*- FL
21	1		*BOOT LOCK	Repair	246.60 FL	*- FL
22	1		*BOOT LOCK CATCH	Repair	41.70 FL	*- FL
23	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
24	1		*BOOT BADGE RENAULT	Not Necessary	82.40 FL	*- FL
25	1		*BOOT BADGE	Not Necessary	95.80 FL	*- FL
26	1		*BOOT FINISHER	Serviceable	344.70 FL	*- FL
27	1		*SET PARKING AID	Serviceable	700.00 FS	*- FS
28	1		*BOOT FINISHER NUT L70Y	Not Necessary	60.00 FS	*- FS
29	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
30	1		*SET BUMPER BRACKET CTR CLIP	Not Necessary	33.00 FS	*- FS
31	1		*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
32	1		*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
33	1		*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary	10.00 FS	*- FS
34	1		*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*- FS
35	1		*SET BUMPER LOWER REAR RIVET	Not Necessary	22.00 FS	*- FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
37	1		*SET WHEELARCH CLIP	Not Necessary	60.00 FS	*- FS
38	1		*SET FENDER CLIP	Not Necessary	35.00 FS	*- FS
39	1		*EXHAUST MOUNTING REAR	Not Necessary	17.82 FS	*- FS
40	1		*REAR NUMBER PLATE WITH HOLDER	Serviceable	120.00 FS	*- FS
41	1		*REAR BOOT STICKER TRANS-CAB	Not Necessary	80.00 FS	*- FS
42	1		*REAR BOOT STICKER 6555-3333	Not Necessary	80.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	8,783.88	2,074.56
- List Item Discount on L Items 10.00/10.00% (S\$)	738.41	194.26
Total Parts (S\$)	8,045.47	1,880.30

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	3,000.00	400.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	3,000.00	300.00
3	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	300.00	0.00
4	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	0.00
5	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
6	TO TRANSFER OF BOOTLID FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	15.00
Gross Labour Cost (\$\$)			7,370.00	775.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >