



ESTABLISHED 1984

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

**DAMAGE ASSESSMENT REPORT**

NTUC INCOME INSURANCE CO-OPERATIVE LTD  
73 BRAS BASAH ROAD  
#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556  
ATTN : CHESTER CHONG

Ref: CS/INC20013807/Atf3e2  
Date: 15/03/2021  
Code: INC

**1. Policy Particulars :- THIRD PARTY CLAIM**

|                     |                |                       |            |
|---------------------|----------------|-----------------------|------------|
| <b>Insured Veh.</b> | SMG 5332T      | <b>Veh. Inspected</b> | SLG 6422Y  |
| <b>Policy No.</b>   |                | <b>Coverage (\$)</b>  | 0.00       |
| <b>Claim No.</b>    | MT/1113636-001 | <b>Excess (\$)</b>    | 0.00       |
| <b>Assign From</b>  | ANNIE KOH      | <b>Assign Date</b>    | 15/12/2020 |

**2. Vehicle Particulars & Condition**

|                         |                   |                     |            |
|-------------------------|-------------------|---------------------|------------|
| <b>Make &amp; Model</b> | HYUNDAI ELANTRA   | <b>c.c</b>          | 1591       |
| <b>Engine No.</b>       | HIDDEN            | <b>Year of Reg.</b> | 2016       |
| <b>Chassis No.</b>      | KMHD841CMHU219694 | <b>Colour</b>       | GOLD       |
| <b>Odometer</b>         | 156889 KM         | <b>Steering</b>     | IN ORDER   |
| <b>Brakes</b>           | IN ORDER          | <b>Modification</b> | SPORTS RIM |
| <b>General</b>          | GOOD              |                     |            |

**3. Conditions of Tyres**

|                       | Size       | Make        | Balance |
|-----------------------|------------|-------------|---------|
| <b>R/H Front Tyre</b> | 205/55 R16 | BRIDGESTONE | 6 mm    |
| <b>L/H Front Tyre</b> | 205/55 R16 | BRIDGESTONE | 6 mm    |
| <b>R/H Rear Tyre</b>  | 205/55 R16 | BRIDGESTONE | 6 mm    |
| <b>L/H Rear Tyre</b>  | 205/55 R16 | BRIDGESTONE | 6 mm    |

**4. Description of Damages**

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.  
DAMAGES SEE DETAILS.

**5. General Information**

|                       |                                                                                                |                            |                         |
|-----------------------|------------------------------------------------------------------------------------------------|----------------------------|-------------------------|
| <b>Accident Date</b>  | 12/12/2020                                                                                     | <b>Inspect Date / Time</b> | 15/12/2020 ( 12:19 PM ) |
| <b>Survey held at</b> | SMARTONE AUTO PTE LTD<br>8 KAKI BUKIT AVENUE 4, #08-09, PREMIER @ KAKI BUKIT, SINGAPORE 415875 |                            |                         |

**5a. Remarks**

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.  
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

**5b. Estimate Days of Repair**

|                                     |                       |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | <b>6 Working Days</b> |
|-------------------------------------|-----------------------|