

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG20013809/ABA3Q2
Date: 31/08/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100492164	
Claimant Vehicle No :	SMM1961Y	Insured Vehicle No :	SLJ1778M	
Date of Loss:	08/12/2020	Nature of Claim:	TP	Claim No: 9751254085SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMM1961Y		
Make & Model:	RENAULT GRAND SCENIC IV, 1.5 DCI EU6 (A)	Engine No:	K9KF649D059843
Reg. Date:	20/06/2019 (Man. Year: 2019)	Chassis No:	VF1RFA00262894770
Colour:	Red	Odometer:	112699 km
Engine Capacity:	1461 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/55 R20	Rear Tyre Size:	195/55 R20
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	49,620.80	33,953.10	15,667.70	31.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,580.00	4,430.00	6,150.00	58.13
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	60,200.80	38,383.10	21,817.70	36.24
Approved Total (Overridden) (S\$)		30,200.00		

Nett Amount (S\$)	60,200.80	30,200.00	30,000.80	49.83
+ Car Rental (23.0 x S\$100.00/day + 7.00% GST) (S\$)		2,461.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		32,668.45		
Global Sum Settlement (S\$)		32,600.00		

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 14/12/2020

Estimated Period of Repair: 14.0 days

Inspected At: Xin Hua Workshop Pte Ltd (HQ)
23 Kaki Bukit Ave 4 #04-01
Singapore 415933

Adjuster: ADRIAN LING**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BONNET	Dented	1,400.00 FL	*1,400.00 FL
2	1		*FRT BONNET LOCK	Not Necessary	257.00 FL	*- FL
3	1		*FRT BONNET LOCK RELEASE LEVER	Not Necessary	155.00 FL	*- FL
4	1		*FRT BONNET LOCK CABLE	Not Necessary	222.00 FL	*- FL
5	1		*FRT BONNET INSULATOR	Torn	367.00 FL	*367.00 FL
6	1		*FRT BONNET RUBBER SEAL RH	Not Necessary	85.00 FL	*- FL
7	1		*FRT BONNET RUBBER SEAL LH	Cut	85.00 FL	*85.00 FL
8	1		*FRT BONNET HINGE LH	Not Necessary	236.00 FL	*- FL
9	1		*FRT BONNET HINGE RH	Not Necessary	236.00 FL	*- FL
10	4		*FRT BONNET STOPED	Not Necessary	84.00 FL	*- FL
11	2		*FRT BONNET STOPED (ADJUSTABLE)	Not Necessary	36.00 FL	*- FL
12	1		*FRT BUMPER UPP	Deformed	1,631.00 FL	*1,631.00 FL
13	1		*FRT BUMPER LOW	Deformed	498.00 FL	*498.00 FL
14	1		*FRT BUMPER BRACKET LH	Cracked	146.00 FL	*146.00 FL
15	1		*FRT BUMPER BRACKET RH	Cracked	146.00 FL	*146.00 FL
16	1		*FRT BUMPER ABSORBER SPONGE	Cracked	280.00 FL	*280.00 FL
17	1		*FRT BUMPER SUPPORT PANEL TOP GARNISH	Cracked	785.00 FL	*785.00 FL
18	1		*LH FOG LAMP COVER	Not Necessary	268.00 FL	*- FL
19	1		*LH FOG LAMP COVER CHROME MLDG	Cut	268.00 FL	*268.00 FL
20	1		*LH FOG LAMP BRACKET	Cracked	224.00 FL	*224.00 FL
21	1		*LH FOG LAMP	Not Necessary	260.00 FL	*- FL
22	1		*FRT BRAKE COOLING AIR GUIDE LH	Cracked	160.00 FL	*160.00 FL
23	1		*A/C GAS LABEL	Necessary	38.00 FL	*38.00 FL
24	1		*DIESEL ENGINE LABEL	Necessary	38.00 FL	*38.00 FL
25	1		*FRT BUMPER AIR GUIDE TOP	Cracked	785.00 FL	*785.00 FL
26	1		*FRT BUMPER AIR GUIDE LOW	Cracked	498.00 FL	*498.00 FL
27	1		*FRT BUMPER AIR GUIDE FLAP LOW	Cracked	148.00 FL	*148.00 FL
28	1		*FRT GRILLE BASE	Cut	379.00 FL	*379.00 FL
29	1		*FRT GRILLE TOP MLDG	Cracked	294.00 FL	*294.00 FL
30	1		*FRT GRILLE LOW CHROME MLDG	Cut	304.00 FL	*304.00 FL
31	1		*FRT GRILLE RENAULT LOGO	Missing	252.00 FL	*252.00 FL
32	2		*FRT BUMPER PARKING SENSOR	Damaged	954.00 FL	*954.00 FL
33	1		*FRT BUMPER BLIND SPOT SENSOR	Missing	477.00 FL	*477.00 FL
34	6		*FRT BUMPER PARKING SENSOR SEAL	Necessary	60.00 FL	*60.00 FL
35	1		*FRT BUMPER PARKING SENSOR WIRE HARNESS	Cracked	266.00 FL	*266.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
36	1		*FRT BUMPER REINFORCEMENT UPP	Bent	714.00 FL	*714.00 FL
37	1		*FRT RADIATOR SUPPORT PANEL	Cracked	1,148.00 FL	*1,148.00 FL
38	1		*RH HEADLAMP	Cracked	1,057.00 FL	*1,057.00 FL
39	1		*LH HEADLAMP	Cracked	1,057.00 FL	*1,057.00 FL
40	1		*LH HEADLAMP BRACKET (RR)	Not Necessary	171.00 FL	*- FL
41	1		*LH HEADLAMP BRACKET (FRT)	Not Necessary	171.00 FL	*- FL
42	1		*FRT FENDER LH	Cracked	717.00 FL	*717.00 FL
43	1		*FRT FENDER INNERSHIELD LH (FRONT)	Torn	286.00 FL	*286.00 FL
44	1		*FRT FENDER INNERSHIELD LH (REAR)	Not Necessary	286.00 FL	*- FL
45	1		*RADIATOR	Not Necessary	1,047.00 FL	*- FL
46	1		*RADIATOR TOP BRACKET LH	Not Necessary	91.00 FL	*- FL
47	1		*RADIATOR TOP BRACKET RH	Not Necessary	91.00 FL	*- FL
48	1		*RADIATOR TOP MOUNTING	Not Necessary	18.00 FL	*- FL
49	1		*RADIATOR LOW MOUNTING	Not Necessary	18.00 FL	*- FL
50	1		*RADIATOR HOSE UPP	Not Necessary	158.00 FL	*- FL
51	1		*RADIATOR HOSE LOW	Not Necessary	511.00 FL	*- FL
52	1		*A/C CONDENSER	Not Necessary	1,225.00 FL	*- FL
53	1		*A/C CONDENSER AIR GUIDE LH	Deformed	227.00 FL	*227.00 FL
54	1		*TURBO INTAKE COOLER AIR GUIDE RH	Deformed	157.00 FL	*157.00 FL
55	1		*RADIATOR FAN ASSY	Not Necessary	1,109.00 FL	*- FL
56	1		*INTERCOOLER ,TURBOCHARGER	Not Necessary	965.00 FL	*- FL
57	1		*FRT HORN LH	Cracked	215.00 FL	*215.00 FL
58	1		*ENGINE DIESEL GLOW PLUG RELAY	Not Necessary	277.00 FL	*- FL
59	1		*RR BUMPER	Distorted	1,345.00 FL	*1,345.00 FL
60	1		*RR BUMPER LOW	Distorted	606.00 FL	*606.00 FL
61	1		*RR BUMPER LOW MLDG	Deformed	812.00 FL	*812.00 FL
62	1		*RR BUMPER TOW COVER	Missing	104.00 FL	*104.00 FL
63	1		*RR BUMPER CENTRE RETAINER	Cracked	417.00 FL	*417.00 FL
64	1		*RR BUMPER SIDE RETAINER RH (INNER)	Cracked	171.00 FL	*171.00 FL
65	1		*RR BUMPER SIDE RETAINER RH (OUTER)	Cracked	335.00 FL	*335.00 FL
66	1		*RR BUMPER SIDE RETAINER LH (INNER)	Cracked	171.00 FL	*171.00 FL
67	1		*RR BUMPER SIDE RETAINER LH (OUTER)	Cracked	335.00 FL	*335.00 FL
68	1		*RR BUMPER LOW BRACKET RH	Cracked	132.00 FL	*132.00 FL
69	1		*RR BUMPER LOW BRACKET LH	Cracked	132.00 FL	*132.00 FL
70	2		*RR BUMPER LOW BRACKET CENTRE	Cracked	202.00 FL	*202.00 FL
71	1		*RR FENDER INNERSHIELD END RH	Not Necessary	274.00 FL	*- FL
72	1		*RR FENDER INNERSHIELD END LH	Cracked	274.00 FL	*274.00 FL
73	1		*RR BUMPER REINFORCEMENT	Bent	799.00 FL	*799.00 FL
74	1		*RR KEY RECEIVER SENSOR	Cracked	452.00 FL	*452.00 FL
75	4		*RR BUMPER REVERSE SENSOR	Damaged	1,188.00 FL	*1,188.00 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
76	1		*RR REVERSE CAMERA	Not Necessary	825.00 FL	*- FL
77	1		*RR REVERSE CAMERA BRACKET	Not Necessary	184.00 FL	*- FL
78	1		*RR BUMPER BLIND SPOT SENSOR	N/S Damaged	968.00 FL	*484.00 FL
79	6		*RR BUMPER REVERSE SENSOR RUBBER SEAL	Necessary	60.00 FL	*60.00 FL
80	1		*RR BUMPER REVERSE SENSOR WIRE HARNESS	Not Necessary	261.00 FL	*- FL
81	1		*RR BUMPER REFLECTOR RH	Cracked	298.00 FL	*298.00 FL
82	1		*RR BUMPER REFLECTOR LH	Missing	516.00 FL	*516.00 FL
83	1		*RR TAILGATE MLDG	Deformed	552.00 FL	*552.00 FL
84	1		*RR TAILGATE	Deformed	3,720.00 FL	*1,929.00 FL
85	1		*RR TAILGATE RENAULT LOGO	Necessary	193.00 FL	*193.00 FL
86	1		*RR TAILGATE SCENIC EMBLEM	Necessary	176.00 FL	*176.00 FL
87	1		*RR TAILGATE RENAULT EMBLEM	Necessary	152.00 FL	*152.00 FL
88	2		*RR TAILGATE NUMBER PLATE LAMP	Not Necessary	80.00 FL	*- FL
89	1		*RR TAILGATE LOCK	Damaged	353.00 FL	*353.00 FL
90	1		*RR TAILGATE LOCK STRIKER	Not Necessary	114.00 FL	*- FL
91	1		*RR TAILGATE DAMPER	Not Necessary	265.00 FL	*- FL
92	1		*RR TAILGATE LOCK OPEN SWTICH	Not Necessary	231.00 FL	*- FL
93	1		*RR TAILGATE STOPED	Not Necessary	628.00 FL	*- FL
94	1		*RR TAILGATE INNER TRIM BOARD	Cracked	950.00 FL	*786.00 FL
95	1		*RR TAILGATE REFLECTOR RH	Cut	640.00 FL	*640.00 FL
96	1		*RR TAILGATE REFLECTOR LH	Cut	640.00 FL	*640.00 FL
97	1		*RR TAILGATE WIRE HARNESS (NPA)	Not Necessary	0.00 FL	*- FL
98	1		*RR TAILGATE WEATHERSTRIP	Cut	230.00 FL	*230.00 FL
99	1		*RR TAILLAMP RH	Cut	640.00 FL	*548.00 FL
100	1		*RR TAILLAMP LH	Cut	640.00 FL	*548.00 FL
101	1		*RR END PANEL OUTER	Dented	1,088.00 FL	*1,088.00 FL
102	1		*RR END PANEL INNER	Repair	492.00 FL	*- FL
103	1		*RR END PANEL SUPORT RH	Not Necessary	359.00 FL	*- FL
104	1		*RR END PANEL SUPORT LH	Not Necessary	359.00 FL	*- FL
105	1		*RR END PANEL TOP GARNISH	Cracked	332.00 FL	*332.00 FL
106	1		*RR SPARE TYRE PANEL	Cracked	1,496.00 FL	*987.00 FL
107	1		*RR TRUNK COVER	Deformed	737.00 FL	*737.00 FL
108	1		*RR TAILLAMP PANEL RH (NPA)	Not Necessary	0.00 FL	*- FL
109	1		*RR TAILLAMP PANEL LH (NPA)	Not Necessary	0.00 FL	*- FL
110	1		*RR FENDER INNERSHIELD RH	Not Necessary	391.00 FL	*- FL
111	1		*RR FENDER INNERSHIELD LH	Torn	391.00 FL	*391.00 FL
112	1		*RR FENDER AIR DUCT RH	Not Necessary	195.00 FL	*- FL
113	1		*RR FENDER AIR DUCT LH	Not Necessary	195.00 FL	*- FL
114	1		*RR FENDER MUDGUARD RH (RR)	Not Necessary	135.00 FL	*- FL
115	1		*RR FENDER MUDGUARD LH (RR)	Not Necessary	135.00 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
116	1		*RR FENDER INNER TRIM RH (NPA)	Not Necessary	0.00 FL	*- FL
117	1		*RR FENDER INNER TRIM LH (NPA)	Not Necessary	0.00 FL	*- FL
118	1		*RR EXHAUST SILENCER BOX	Bent	1,302.00 FL	*781.00 FL
119	1		*RR EXHAUST SILENCER BOX MOUNTING (NPA)	Not Necessary	0.00 FL	*- FL
120	1		*RR EXHAUST PIPE CLAMP	Necessary	80.00 FL	*80.00 FL
121	1		*RR EXHAUST SILENCER BOX INSULATOR	Crumpled	206.00 FL	*206.00 FL
122	1		*RR EXHAUST SILENCER BOX HEAT BAFFLE	Torn	303.00 FL	*303.00 FL
123	1		*FRT BUMPER UNDER DUST COVER	Cracked	471.00 FL	*471.00 FL
124	1		*FRT BUMPER SIDE RETAINER LH	Cracked	146.00 FL	*146.00 FL
125	1		*FRT BUMPER BRACKET CENTRE	Cracked	146.00 FL	*146.00 FL
126	1		*FRT NUMBER PLATE	Not Necessary	65.00 FS	*- FS
127	1		*RADIATOR COOLANT	Necessary	80.00 FS	*50.00 FS
128	10		*FRT BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
129	10		*FRT GRILLE CLIP	Necessary	50.00 FS	*20.00 FS
130	10		*FRT FENDER INNERSIHELD CLIP	Necessary	50.00 FS	*30.00 FS
131	10		*FRT BONNET INSULATOR CLIP	Not Necessary	50.00 FS	*- FS
132	10		*RR BUMPER CLIP	Necessary	50.00 FS	*30.00 FS
133	10		*RR TAILGATE GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
134	10		*RR TAILGATE INNER TRIM BOARD CLIP	Necessary	50.00 FS	*30.00 FS
135	10		*RR TAILGATE TOP SPOILER CLIP	Not Necessary	50.00 FS	*- FS
136	10		*RR END PANEL TOP GARNISH CLIP	Necessary	50.00 FS	*20.00 FS
137	1		*RR WINDSCREEN SEALANT	Necessary	65.00 FS	*40.00 FS
138	1		*RR WINDSCREEN INNER SEAL	Necessary	40.00 FS	*40.00 FS
139	1		*RR WINDSCREEN SOLAR FILM	Not Necessary	200.00 FS	*- FS
140	1		*RR NUMBER PLATE	Bent	65.00 FS	*65.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	55,027.00	37,684.00
- List Item Discount on L Items 10.00/10.00% (\$)	5,406.20	3,730.90
Total Parts (\$)	49,620.80	33,953.10

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	1,400.00	800.00
2	CARRY OUT SPRAY PAINTING ON ACCIDENT AFFECTED AREA ,FRT BUMPER ,FRT BONNET ,FRT SUPPORT PANEL ,FRT FENDER LH ,FRT FENDER RH ,FRT DOOR LH	New	1,400.00	600.00
3	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	120.00	40.00
4	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	160.00	30.00
5	TO REMOVE AND REFIT AIRCON CONDENSOR ,VACUUM REFILL AND CHECK AIR CON GAS SYSTEM	New	600.00	60.00
6	TO REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST	New	120.00	60.00
7	TO CONDUCT RESET OF ENGINE LIGHT ON	New	400.00	0.00
8	TO REFOCUS HEADLAMP	New	100.00	0.00
9	TO REMOVE AND REFIT FRONT SENSOR	New	100.00	50.00
10	TO DISMANTLE /RENEW THE ACCIDENT DAMAGED PORTION ,TO PANEL BEATING ,RESHAPE ,STRAIGHTEN ,ORIENTATE AND ALIGN REPAIR /REPLACEMENT PARTS	New	2,000.00	1,200.00
11	CARRY OUT SPRAY PAINTING ON AFFECTED AREA ,RR TAILGATE ,RR BUMPER ,RR END PANEL ,RR SPARE TYRE PANEL ,RR FENDER RH ,RR FENDER LH	New	2,000.00	1,000.00
12	TO CONDUCT ANTI RUST OF UNDER CARRIAGE TUFF COAT	New	120.00	60.00
13	TO DISCONNECT WIRE HARNESS OF ELECTRICAL COMPONENT TO FACILITATE REPAIRS ,RECONNECT AND CHECK ELECTRICAL FUNCTION AFTER REPAIR	New	160.00	30.00
14	REMOVE AND REFIX SEAT CUSHION UPHOLSTERY & ROOF LINING TO FACILITATE REPAIRS	New	400.00	100.00
15	TO REMOVE AND REFIX REVERSE SENSOR AND CONDUCT TEST	New	120.00	60.00
16	TO REMOVE AND REFIX REVERSE CAMERA AND CONDUCT TEST	New	120.00	60.00
17	TO CONDUCT TRANSFER OF PARTS FROM OLD TAILGATE TO NEW TAILGATE	New	200.00	80.00
18	TO CONDUCT WATER LEAKAGE TEST AFTER REPAIRS OF VEHICLE	New	80.00	0.00
19	TO REMOVE AND REPLACE EXHAUST PIPE	New	400.00	80.00
20	TO REMOVE AND REFIX REAR TAIL GATE WINDSCREEN	New	180.00	120.00
21	TO REMOVE AND REFIX REAR UNDERCARRIAGE	New	400.00	0.00
Gross Labour Cost (\$\$)			10,580.00	4,430.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >

