

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD INV No. AC2102563

3 ANSON ROAD #16-00 INV Date 14/04/2021

SPRINGLEAF TOWER
SINGAPORE 079909
Reference CC3/CTI20013814/R1ra3q2

Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SHC 8138Z

Insured Veh. YM 8698U

Claim No. SNM20D204880/LKKDS

Policy No. DMCVSNW00047342005

Accident Date 14/12/2020

Inspection Date 14/12/2020

| Description | Total |
|--------------------------------|--------|
| Third Party Express Settlement | 400.00 |
| Subtotal | 400.00 |
| GST (7%) | 28.00 |
| Grand Total | 428.00 |

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

LKM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| | Affiliated to Federation Internationale Des Experts En Automobile | | | | | | | |
|-----|---|---|----------------|--------|-------------------------|--|--|--|
| | CHINA TAIPING IN | SURANCE (S) PTE LTD | | Ref: | CC3/CTI20013814/R1ra3q2 | | | |
| | 3 ANSON ROAD # SPRINGLEAF TOV | :16-00 VERSINGAPORE 079909 | | Date: | 14/04/2021 | | | |
| | | | | Code: | CTI | | | |
| 1. | | Policy Particulars :- THIRD PARTY CLAIM | | | | | | |
| | Insured Veh. | YM 8698U | Veh. Inspected | | SHC 8138Z | | | |
| | Policy No. | DMCVSNW00047342005 | Coverage (\$) | | 0.00 | | | |
| | Claim No. | SNM20D204880/LKKDS | Excess (\$) | | 0.00 | | | |
| | Assign From | | Assign Date | | 14/12/2020 | | | |
| 2. | 2. Vehicle Particulars & Condition | | | | | | | |
| | Make & Model | HYUNDAI 140 1.7 CRDI | c.c | | 1685 | | | |
| | Engine No. | HIDDEN | Year of Reg. | | 2016 | | | |
| | Chassis No. | KMHLB41UMGU087801 | Colour | | BLUE | | | |
| | Odometer | 844311 KM | Steering | | IN ORDER | | | |
| | Brakes | IN ORDER | Modification | | NIL | | | |
| | General | FAIR | | | | | | |
| 3. | | Condition | ons of Tyres | | | | | |
| | | Size | Make | | Balance | | | |
| | R/H Front Tyre | 205/60 R16 | WEST LAKE | | 6 mm | | | |
| | L/H Front Tyre | 205/60 R16 | WEST LAKE | | 6 mm | | | |
| | R/H Rear Tyre | 205/60 R16 | WEST LAKE | | 6 mm | | | |
| | L/H Rear Tyre | 205/60 R16 | WEST LAKE | | 6 mm | | | |
| 4. | | Description | on of Damages | | | | | |
| | THE VEHICLE SU | STAINED DAMAGES AT THE O/S | BODY. | | | | | |
| | DAMAGES SEE DETAILS. | | | | | | | |
| 5. | | General | Information | | | | | |
| | Accident Date | 14/12/2020 | Inspection Dat | е | 14/12/2020 | | | |
| | Survey held at | urvey held at COMFORTDELGRO ENGINEERING PTE LTD | | | | | | |
| | | 59 LOYANG DRIVE SINGAPORE 508969 | | | | | | |
| 5a. | | Re | emarks | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | | | |
| 5b. | Estimate Days of Repair | | | | | | | |
| | ESTIMATED NOR | MAL PERIOD FOR REPAIR: | | 3 Work | ing Days | | | |
| | | | | | | | | |



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 8138Z

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|---|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | PANEL ASSY -RR DR RH | BENT | 2,201.10 | 2,201.10 |
| 1 | PANEL ASSY-FR DR RH | TO REPAIR SEE LABOUR | 2,256.40 | - |
| 1 | MOULDING ASSY-SIDE | SERVICEABLE | 732.80 | - |
| | LESS 20% DISCOUNT | | -1,038.06 | -440.22 |
| | | | 4,152.24 | 1,760.88 |
| | SPECIAL NETT ITEMS | | | |
| 1 | (I40) FRT DOOR LOGO SONATA (SN) | NECESSARY | 75.00 | 75.00 |
| 1 | APP LOGO REAR DOOR L/R CT (SN) | NECESSARY | 80.00 | 80.00 |
| | | | 155.00 | 155.00 |
| | <u>LABOUR</u> | | | |
| | PANEL BEATING .INCLUSIVE OF THE REPAIR OF PANEL ASSY-FR DR RH . | | 600.00 | 280.00 |
| | SPRAYPAINT CHARGE. | | 700.00 | 400.00 |
| | TRANSFER DOOR FRT . | | 240.00 | 60.00 |
| | | | 1,540.00 | 740.00 |
| | GRAND TOTAL | | 5,847.24 | 2,655.88 |

| RECOMMENDED COST OF LUMP SUM REPAIRS | | 2,100.00 |
|--------------------------------------|--|----------|
| (TO ITS PRE-ACCIDENT CONDITION) | | |

Report Ref No. CC3/CTI20013814/R1ra3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

Amonto

HO LEONG CHUAN

Automotive Assessor




51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8138Z

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R
















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SHC 8138Z

RE-INSPECTION







