LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG20013818/KVF3E2

06/07/2021 Date:

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. Policy No: MSD/VMS/20-414123

Claimant Vehicle SLB4590J Insured Vehicle No: FBN600X

No:

Date of Loss: 09/12/2020 Nature of Claim: ΤP Claim No: MSC/V/20-000872

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLB4590J**

Make & Model: FORD FOCUS, 1.6 HB TITANIUM (A) FL48755 Engine No:

Reg. Date: 08/04/2016 (Man. Year: 2015) Chassis No: WF04XXGCC4FL48755

White Colour: Odometer: 60341 km

Engine Capacity: 1596 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition: No

CONDITION OF TYRES

225/45 R17 Front Tyre Size: Rear Tyre Size: 225/45 R17 Front Left Side: Pirelli 5 mm Rear Left Side: Pirelli 3 mm Front Right Side: Pirelli 5 mm Rear Right Side: Pirelli 3 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		3,202.40	3,119.00	83.40	2.60
Miscellaneous Items		0.00	0.00	0.00	
Labour		1,290.00	1,010.00	280.00	21.71
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calcul	ated Gross Total (S\$)	4,492.40	4,129.00	363.40	8.09
Approved To	otal (Overridden) (S\$)		3,250.00		
	(S\$)	4,492.40	3,250.00	1,242.40	27.66
+	GST 7.00/7.00% (S\$)	314.47	227.50	86.97	27.66
	Nett Amount (S\$)	4,806.87	3,477.50	1,329.37	27.66

INSPECTION

Date of Assignment: 15/12/2020

Cheng Hoe Motor Pte Ltd (AMK)

10 ANG MO KIO IND PARK 2A, #01-04 ANG MO Date Inspected: 05/02/2021 Inspected At:

KIO AUTOPOINT

Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG Manager: **VERON CHEN**

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 06 Jul 2021)

Parts: 143 FORD FOCUS 1.6 HB TITANIUM (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLB4590J)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH SIDE MIRROR ASSY	Cracked	1,260.00 FL	*1,260.00 FL
2	1		*REAR LH DOOR	Bent	2,465.00 FL	*2,465.00 FL
3	1		*REAR LH DOOR INNER RUBBER (\$278.00) (50%)	Necessary	222.40 FS	*139.00 FS
F=Fra	nchise	part. S=SpcN	Nett. L=ListItemDisc.	-		
				Sub Total (S\$)	3,947.40	3,864.00
			- List Item Discount on L Items 2	20.00/20.00% (S\$)	745.00	745.00
				Total Parts (S\$)	3,202.40	3,119.00
				_		

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Lab</u>	our Items			
1	REMOVE & REFIX FRT LH SIDE MIRROR, REAR LH DOOR & ATTACHMENTS; KNOCKING & REPAIR REAR LH FENDER & REALIGN THE SAME	New	400.00	320.00
2	PUTTY & RESPRAY BOTH LH DOORS & LH SIDE MIRROR, REAR LH FENDER, REAR BUMPER & ALL AFFECTED AREAS	l New	800.00	600.00
3	REMOVE & REFIX REAR LH DOOR WINDOW GLASS & RESET CENTRAL LOCKING	New	60.00	60.00
4	RUSTPROOFING	New	30.00	30.00
	Gross Labour Cost (S\$)		1,290.00	1,010.00
	Report was unsubmitted during this	s print-out.		

< END OF ESTIMATES >