



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT

NTUC INCOME INSURANCE CO-OPERATIVE LTD
73 BRAS BASAH ROAD
#05-01 NTUC TRADE UNION HOUSESINGAPORE
189556
ATTN: LAM KAI WEN

Ref: CS/INC20013824/Aqd3q2

Date: 23/03/2021

Code: INC

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SCM 5573B	Veh. Inspected	SLR 8037E
Policy No.		Coverage (\$)	0.00
Claim No.	MT/1113304-002	Excess (\$)	0.00
Assign From	ANNIE KOH	Assign Date	14/12/2020

2. Vehicle Particulars & Condition

Make & Model	HONDA SHUTTLE	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	GK81104127	Colour	GREY
Odometer	79406 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/55 R15	MICHELIN	6 mm
L/H Front Tyre	195/55 R15	MICHELIN	6 mm
R/H Rear Tyre	195/55 R15	MICHELIN	6 mm
L/H Rear Tyre	195/55 R15	MICHELIN	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	11/12/2020	Inspect Date / Time	15/12/2020 (01:40 PM)
Survey held at	10 KAKI BUKIT ROAD 2, #01-21 FIRST EAST CENTRE		
Repairer	ADVANCE AUTO GARAGE		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
-------------------------------------	-----------------