

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG20013828/GGS3Q2
Date: 14/06/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	0100469255
Claimant Vehicle No :	SHD6234L	Insured Vehicle No :	GX9676G
Date of Loss:	11/12/2020	Nature of Claim:	TP
		Claim No:	7868677293SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD6234L	Engine No:	2ZR1677450
Make & Model:	TOYOTA PRIUS, 1.8 HYBRID CVT (A)	Chassis No:	JTDKN36U305767978
Reg. Date:	13/05/2016 (Man. Year: 2015)	Odometer:	378422 km
Colour:	Maroon		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Sailun 6 mm	Rear Left Side:	Sailun 6 mm
Front Right Side:	Sailun 6 mm	Rear Right Side:	Sailun 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,282.14	1,501.54	9,780.60	86.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,130.00	1,020.00	2,110.00	67.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	14,412.14	2,521.54	11,890.60	82.50
Approved Total (Overridden) (S\$)		2,200.00		

Nett Amount (S\$)	14,412.14	2,200.00	12,212.14	84.74
+ Loss of Use (5.0 x S\$50.00/day) (S\$)		250.00		
+ Car Rental (5.0 x S\$109.14/day) (S\$)		545.70		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		3,002.70		

INSPECTION

Date of Assignment: 14/12/2020

Date Inspected: 14/12/2020

Estimated Period of Repair: 4.0 days

Inspected At:

SMRT Automotive Services Pte Ltd (Woodlands)

60 Woodlands Industrial Park E4

Singapore 757705

Adjuster: XING GUO QIANG**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	16.10 F	*12.08 F
2	1		*BUMPER SUPPORT F/RH (DISC 25%)	Deformed	76.40 F	*57.30 F
3	1		*FENDER FRT /RH (DISC 25%)	Buckled	723.40 F	*542.55 F
4	1		*NAME PLATE (HYBRID) (DISC 25%)	Necessary	51.90 F	*38.93 F
5	1		*HEAD LAMP RH (DISC 10%)	Cracked	945.20 F	*850.68 F
6	1		*BUMPER SUPPORT F/LH	Not Necessary	76.40 F	*- F
7	1		*BUMPER ENERGY ABSORBER FRT	Not Necessary	78.80 F	*- F
8	1		*BUMPER REINFORCEMENT FRT	Not Necessary	498.40 F	*- F
9	1		*ARM SUB-ASSY ,FR BUMPER LH	Not Necessary	250.40 F	*- F
10	1		*ARM SUB-ASSY ,FR BUMPER RH	Not Necessary	250.40 F	*- F
11	1		*NUMBER PLATE FRAME	Not Necessary	12.00 F	*- F
12	1		*COVER ,FR BUMPER HOLE RH	Not Necessary	18.50 F	*- F
13	1		*BUMPER GRILLE SUB-ASSY ,LOWER	Not Necessary	311.10 F	*- F
14	1		*FOG LAMP RH	Not Necessary	295.20 F	*- F
15	1		*GRILLE ,RADIATOR	Not Necessary	310.60 F	*- F
16	1		*GRILLE ,RADIATOR LOWER NO.2	Not Necessary	94.60 F	*- F
17	1		*BUMPER LIP FRT	Not Necessary	139.60 F	*- F
18	1		*BUMPER FRT ABSORBER LOWER	Not Necessary	127.70 F	*- F
19	1		*UNDER COVER CENTER	Not Necessary	448.30 F	*- F
20	1		*HOOD HINGE LH	Not Necessary	55.90 F	*- F
21	1		*HOOD HINGE RH	Not Necessary	55.90 F	*- F
22	1		*FENDER PROTECTOR FRT/RH SIDE	Not Necessary	113.90 F	*- F
23	1		*FENDER LINER PAD ,FR WHEEL ,RH	Not Necessary	49.30 F	*- F
24	1		*WHEEL DISC ,FRONT	Not Necessary	1,484.20 F	*- F
25	1		*TYRE	Not Necessary	126.74 F	*- F
26	1		*MOULDING BODY ,RH	Not Necessary	673.60 F	*- F
27	1		*WHEEL HUB FRT	Not Necessary	549.70 F	*- F
28	1		*MIRROR ASSY ,RH	Not Necessary	1,307.10 F	*- F
29	1		*MIRROR LAMP RH	Not Necessary	65.30 F	*- F
30	1		*COVER ,OUTER MIRROR ,RH	Not Necessary	107.40 F	*- F
31	1		*LENS & BODY FR TURN RH	Serviceable	511.80 F	*- F
32	1		*FENDER LINER FRT/RH	Not Necessary	171.70 F	*- F
33	1		*BUMPER FRT	Repair	482.00 F	*- F
34	1		*HOOD PANEL	Repair	748.10 F	*- F
35	1		*SUPPORT RADIATOR RH	Repair	54.50 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
F=Franchise part.						
Total Parts (S\$)					11,282.14	1,501.54

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODY WORK	New	676.00	400.00
2	SPRAY PAINT	New	1,854.00	600.00
3	TO REMOVE AND REFIX WING MIRROR	New	120.00	0.00
4	TO REMOVE AND REFIT TYRE RIM (SPRAYING PURPOSE)	New	120.00	0.00
5	TO DO WHEEL ALIGNMENT /TYRE BALANCING	New	120.00	0.00
6	TO REPLACE SUNDRY PARTS	New	100.00	0.00
7	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	20.00
8	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (S\$)			3,130.00	1,020.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >