

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG20013836/GBS3Q2

**Date:** 13/04/2021

#### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800137124
<b>Claimant</b>		
<b>Vehicle No :</b> SKB4710S	<b>Insured Vehicle No :</b>	SMG5151Z
Date of Loss: 12/12/2020	Nature of Claim: TP	Claim No: 1054539311SG

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SKB4710S</b>	Engine No:	1NZY130965
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR053HY9305177457
Reg. Date:	31/05/2011 (Man. Year: 2010)	Odometer:	191167 km
Colour:	Blue		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

#### CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Davanti 6 mm	Rear Left Side:	Davanti 6 mm
Front Right Side:	Davanti 6 mm	Rear Right Side:	Davanti 6 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,315.82	503.40	812.42	61.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,250.00	800.00	450.00	36.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>2,565.82</b>	<b>1,303.40</b>	<b>1,262.42</b>	<b>49.20</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>1,000.00</b>		
(S\$)	2,565.82	1,000.00	1,565.82	61.03
<b>+ GST 7.00/7.00% (S\$)</b>	179.61	70.00	109.61	61.03
<b>Nett Amount (S\$)</b>	<b>2,745.43</b>	<b>1,070.00</b>	<b>1,675.43</b>	<b>61.03</b>
<b>+ Loss of Use (4.0 x S\$60.00/day) (S\$)</b>		240.00		
<b>+ Doc/Search Fee (S\$)</b>		7.45		
<b>Nett Liability (S\$)</b>		<b>1,317.45</b>		
<b>Global Sum Settlement (S\$)</b>		<b>1,280.00</b>		

#### INSPECTION

Date of Assignment:	15/12/2020	
Date Inspected:	15/12/2020 Inspected At:	Wei Lee Motor Works (HQ) BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32 Singapore 575644
Estimated Period of Repair:	4.0 days	

---

**Adjuster:** XING GUO QIANG**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	431.90 FL	*363.10 FL
2	2		*REAR BUMPER RETAINER	Not Necessary	96.20 FL	*- FL
3	1		*REAR BUMPER CLIP	Necessary	38.00 FL	*38.00 FL
4	1		*REAR BUMPER FOGLAMP, RH	Not Necessary	87.70 FL	*- FL
5	1		*END PANEL	Repair	608.10 FL	*- FL
6	1		*LID LOCK	Not Necessary	102.00 FL	*- FL
7	1		*LID-EMBLEM	Necessary	47.00 FL	*33.50 FL
8	1		*TOYOTA LOGO	Necessary	50.20 FL	*36.60 FL
9	1		*REVERSE SENSOR	Damaged	220.00 FS	*150.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>1,681.10</b>	<b>621.20</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	365.28	117.80
<b>Total Parts (\$\$)</b>	<b>1,315.82</b>	<b>503.40</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS N ATTACHMENTS REPAIR /RESHAPE TAILGATE N ALL DENTED AREAS REPLACE /ALIGN ALL PARTS INTO POSITION	New	650.00	300.00
2	TO SPRAY PAINT	New	600.00	500.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,250.00</b>	<b>800.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >