

# 威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,  
SINGAPORE 575644.  
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com  
Business Regn No: 269436/00J

15, DEC 2020

AIG Asia Pacific Insurance Pl  
78 Shenton Way  
AIG Building  
S 079120

*4 days.  
Insurance repair  
After repair photos.*

Attn: Motor claim dept-3<sup>rd</sup> party claim  
Claiming against your insured vehicle no: SMG5151Z  
Accident involving vehicle no: SKB4710S/SMG5151Z  
DOA: 12122020 AT Traffic junction twds Bishan st 13

*Guo Qiang  
8288 0282  
15/12/2020*

Dear officer incharge  
Re: Estimate cost of repair for vehicle no: SKB4710S  
To supply--

Description	Qty	Amount
Rear bumper / <i>de</i>	1	431.90
Rear bumper retainer X <i>NN</i> @48.10	2	96.20
Rear bumper clip / <i>NEC</i>		38.00
Rear bumper foglamp, Rh X <i>de NN</i>	1	87.70
End panel <i>repair</i> X	1	608.10
Lid lock X <i>NN</i>	1	102.00
Lid-emblem / <i>de</i>	1	47.00
Toyota logo / <i>de</i>	1	50.20
Parts		1,461.10
Parts less 25%		365.27
		1,095.83

*263.1  
X  
/  
X  
X  
X  
32.5  
36.6  
471.2  
353.4*

Reverse sensor / *pm*  
To remove damaged parts n attachments  
Repair/reshape tailgate n all dented areas  
Replace/align all parts into position  
To spray paint

*220.00 150.  
300  
500  
2,565.83 1303.4  
20% = 1000*

**LKK Auto Consultants hence notify the Repairer of the following:**

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: