

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

15, DEC 2020

AIG Asia Pacific Insurance Pl
78 Shenton Way
AIG Building
S 079120

4 Days.
Insurance repair
After repair photos.
Guo Qian
8288 0282
15/12/2020

Attn: Motor claim dept-3rd party claim
Claiming against your insured vehicle no: SMG5151Z
Accident involving vehicle no: SKB4710S/SMG5151Z
DOA: 12122020 AT Traffic junction twds Bishan st 13

Dear officer incharge
Re: Estimate cost of repair for vehicle no: SKB4710S
To supply--

| Description | Qty | Amount | |
|---|-----|----------|-------|
| Rear bumper / <i>de</i> | 1 | 431.90 | 263.1 |
| Rear bumper retainer X <i>NN</i> @48.10 | 2 | 96.20 | X |
| Rear bumper clip / <i>NEC</i> | | 38.00 | - |
| Rear bumper foglamp, Rh X <i>de NN</i> | 1 | 87.70 | X |
| End panel <i>repair</i> X | 1 | 608.10 | X |
| Lid lock X <i>NN</i> | 1 | 102.00 | X |
| Lid-emblem / <i>acc</i> | 1 | 47.00 | 22.5 |
| Toyota logo / <i>acc</i> | 1 | 50.20 | 36.6 |
| Parts | | 1,461.10 | 471.2 |
| Parts less 25% | | 365.27 | |
| | | 1,095.83 | 353.4 |

Reverse sensor / *pm* 220.00 150.
 To remove damaged parts n attachments
 Repair/reshape tailgate n all dented areas
 Replace/align all parts into position 650.00 300
 To spray paint 600.00 500

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed **and** is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2,565.83 1303.4
20% = 1000
L/S.