



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FL 5440X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	CLUTCH LEVER (CONSISTENT)	BROKEN	90.00	90.00
1	SET BALANCER N/S (CONSISTENT)	BENT	250.00	125.00
1	TAIL TIDY (CONSISTENT)	DISTORTED / DEFORMED	220.00	220.00
1	BRAKE LEVER (CONSISTENT)	NOT NECESSARY	120.00	-
1	LEFT SIDE LOWER FAIRING (CONSISTENT)	CUT	290.00	290.00
1	TAIL PANEL (CONSISTENT)	CUT	280.00	280.00
1	HANDLE BAR LH (CONSISTENT)	NOT NECESSARY	160.00	-
1	FRONT SIDE CENTRE PANEL (FAIRING) (CONSISTENT)	CUT	320.00	320.00
1	SET FORK TUBE (CONSISTENT)	NOT NECESSARY	1,800.00	-
1	CLUTCH SWITCH (CONSISTENT)	BROKEN	265.00	265.00
	LESS 10% DISCOUNT		-379.50	-159.00
			3,415.50	1,431.00
<u>SPECIAL NETT ITEMS</u>				
1	SET STICKER DECAL (SN)(CONSISTENT)	NECESSARY	90.00	50.00
1	NUMBER PLATE (SN)(CONSISTENT)	NOT NECESSARY	15.00	-
			105.00	50.00
<u>LABOUR</u>				
	RE-SPRAY PAINT.		800.00	150.00
	LABOUR TO REPLACE ABOVE PARTS,ALIGN & ETC & REPLACE FORK TUBE,TOP UP FORK OIL.		280.00	80.00
			1,080.00	230.00
GRAND TOTAL			4,600.50	1,711.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,350.00

Report Ref No. CC4/ASM20013837/Dgs3q2

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.