

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road, #16-00 Springleaf Tower  
Singapore 079909

**Our File No:** CS/CTI20013838/KQD3E2

**Date:** 28/05/2021

### REFERENCE

Insured/Claimant: HAMSTER CAR RENTAL PTE LTD Policy No: DMHCSNA00004132000  
Date of Loss: 12/11/2020 Nature of Claim: OD Claim No: SNM20D204697/C01/CHNGPW

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SME8937P**  
Make & Model: VOLKSWAGEN GOLF, 1.4 TSI HL (A) Engine No: CHZC16639  
Reg. Date: 22/10/2018 (Man. Year: 2018) Chassis No: WVVZZZAUZJW303627  
Colour: Metallic Grey Odometer: 40537 km  
Engine Capacity: 999 cc  
Market Value/New Car Price: S\$74,000.00  
Sum Insured (S\$): **Market Value/New Car Price**

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes  
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16  
Front Left Side: Bridgestone 8 mm Rear Left Side: Bridgestone 7 mm  
Front Right Side: Bridgestone 8 mm Rear Right Side: Bridgestone 7 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	50,262.00	27,107.00	23,155.00	46.07
Miscellaneous Items	312.00	230.00	82.00	26.28
Labour	2,669.04	1,813.34	855.70	32.06
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>53,243.04</b>	<b>29,150.34</b>	<b>24,092.70</b>	<b>45.25</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>23,300.00</b>		
<b>- Excess (S\$)</b>	0.00	2,000.00	-2,000.00	
<b>(S\$)</b>	53,243.04	21,300.00	31,943.04	59.99
<b>+ GST 7.00/7.00% (S\$)</b>	3,727.01	1,491.00	2,236.01	59.99
<b>Nett Amount (S\$)</b>	<b>56,970.05</b>	<b>22,791.00</b>	<b>34,179.05</b>	<b>59.99</b>

### INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 16/12/2020 Inspected At:

Blk 5035 Ang Mo Kio Ind Park 2 #01-345  
Repairer: Goldbell Engineering Pte Ltd

Estimated Period of Repair: 20.0 days

**Adjuster:** KENNETH KONG

**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 28 May 2021)

**Parts:**            144            VOLKSWAGEN GOLF 1.4 TSI HL (A) (Catalogue:Merimen Singapore 1.0)

**Labour:**          Repairer's      (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SME8937P)

**Validity:**        These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*Total Parts</b>		50,262.00 F	*27,107.00 F
					<b>Total Parts (S\$)</b>	<b>50,262.00</b>
						<b>27,107.00</b>

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	Total Of Extras	312.00	230.00
			<b>Sub Total (\$)</b>	<b>312.00</b>

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	Total of Labour	New	1,986.60	1,184.40
2	Total Paint Including Material	New	682.44	628.94
			<b>Gross Labour Cost (\$)</b>	<b>2,669.04</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >