



National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHA 2405C

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	PANEL -FENDER RH	BENT	588.80	588.80
1	LAMP ASSY -HEAD	SERVICEABLE	1,993.65	-
1	EMBLEM -BLUE DRIVE	NECESSARY	26.60	26.60
1	BRACKET -FR BUMPER	SERVICEABLE	28.00	-
1	COVER -FR BUMPER	DEFORMED	430.90	430.90
	LESS 20% DISCOUNT		-613.59	-209.26
			2,454.36	837.04
	<u>LABOUR</u>			
	PANEL BEATING .		700.00	640.00
	SPRAY PAINT CHARGE.		500.00	400.00
	CHECK ALL LIGHTING.	NOT NECESSARY	50.00	-
	TUFF COAT ON AFFECTED PARTS.		50.00	40.00
			1,300.00	1,080.00
	GRAND TOTAL		3,754.36	1,917.04
	RECOMMENDED COST OF REPAIRS (CONFIRMED)			1,917.04

Report Ref No. NS/INC20013846/R1qd3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.