

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20013850/DGS3Q2

Date: 08/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999993924

Claimant
Vehicle No : SJZ1120A **Insured Vehicle No :** SML7588H

Date of Loss: 11/12/2020 Nature of Claim: TP Claim No: 9224710245SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SJZ1120A		
Make & Model:	TOYOTA WISH, 1.8 (A)	Engine No:	1ZZ3131948
Reg. Date:	11/09/2008 (Man. Year: 2008)	Chassis No:	JTDER12W303000656
Colour:	Silver	Odometer:	320778 km
Engine Capacity:	1794 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Yokohama 5 mm	Rear Left Side:	Yartu 5 mm
Front Right Side:	Yokohama 5 mm	Rear Right Side:	Yartu 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	28,529.43	9,149.23	19,380.20	67.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,950.00	3,210.00	7,740.00	70.68
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	39,479.43	12,359.23	27,120.20	68.69
Approved Total (Overridden) (\$\$)		9,700.00		
(\$\$)	39,479.43	9,700.00	29,779.43	75.43
+ GST 7.00/7.00% (\$\$)	2,763.56	679.00	2,084.56	75.43
Nett Amount (\$\$)	42,242.99	10,379.00	31,863.99	75.43
+ Car Rental (12.0 x S\$120.00/day) (\$\$)		1,440.00		
+ Doc/Search Fee (\$\$)		36.45		
Nett Liability (\$\$)		11,855.45		

INSPECTION

Date of Assignment: 15/12/2020

Date Inspected: 15/12/2020 Inspected At:

JWG International Pte Ltd (HQ)
Blk 10, Ang Mo Kio Ind Park 2A,, #03-08 AMK AutoPoint
Singapore 568047

Estimated Period of Repair: 8.0 days

Adjuster: BRYAN TANI**Manager:** Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Bent	1,365.00 FL	*798.00 FL
2	1		*BONNET INSULATOR	Not Necessary	312.75 FL	*- FL
3	2		*BONNET HINGE LH/RH	Repair	135.48 FL	*- FL
4	1		*BONNET LOCK	Bent	276.65 FL	*145.50 FL
5	1		*BONNET SEAL	Not Necessary	136.54 FL	*- FL
6	1		*BONNET CHROME MOULDING	Bent / Mtg Broken	293.06 FL	*155.30 FL
7	2		*HEAD LAMP LH/RH (50%)	Mtg Broken	1,730.40 FS	*689.10 FS
8	1		*FRONT BUMPER	Distorted / Cracked	972.80 FL	*645.10 FL
9	2		*FRONT BUMPER SIDE RETAINER LH/RH	Not Necessary	167.20 FL	*- FL
10	2		*FRONT BUMPER FOG LAMP GARNISH LH/RH	Not Necessary	279.54 FL	*- FL
11	1		*FRONT BUMPER LOWER GRILLE	Broken	211.09 FL	*211.09 FL
12	1		*FRONT BUMPER SPONGE	Torn	195.97 FL	*195.97 FL
13	1		*FRONT REINFORCEMENT BAR	Bent	875.48 FL	*435.20 FL
14	1		*FRONT SUPPORT PANEL	Bent	1,148.92 FL	*822.10 FL
15	1		*FRONT SUPPORT PANEL TOP GARNISH	Not Necessary	215.78 FL	*- FL
16	1		*FRONT BRACE PANEL	Bent	84.63 FL	*84.63 FL
17	1		*A/C CONDENSOR ASSY	Punctured	1,557.84 FL	*1,328.49 FL
18	1		*A/C CONDENSOR DISCHARGE HOSE	Not Necessary	346.10 FL	*- FL
19	1		*A/C CONDENSOR SUCTION HOSE	Not Necessary	720.85 FL	*- FL
20	1		*RADIATOR ASSY	Not Necessary	1,843.10 FL	*- FL
21	1		*RADIATOR TOP HOSE	Not Necessary	39.50 FL	*- FL
22	1		*RADIATOR BOTTOM HOSE	Not Necessary	42.10 FL	*- FL
23	1		*RADIATOR FAN MOTOR	Not Necessary	426.50 FL	*- FL
24	1		*RADIATOR FAN BLADE	Not Necessary	285.20 FL	*- FL
25	1		*RADIATOR FAN COWLING	Not Necessary	385.16 FL	*- FL
26	2		*FRONT FENDER LH/RH	Not Necessary	1,650.80 FL	*- FL
27	2		*FRONT FENDER INNER SHIELD LH /RH	Not Necessary	380.20 FL	*- FL
28	1		*TAILGATE	Dented	1,510.10 FL	*1,280.00 FL
29	1		*TAILGATE WINDSCREEN MOULDING	Necessary	192.70 FL	*192.70 FL
30	1		*TAILGATE LOGO	Necessary	80.20 FL	*80.20 FL
31	1		*TAILGATE CENTER CHROME MOULDING	Serviceable	439.10 FL	*- FL
32	2		*TAILGATE NO.PLATE LAMP LH/RH	Not Necessary	184.20 FL	*- FL
33	1		*TAILGATE LOCK	Damaged	543.50 FL	*388.80 FL
34	1		*TAILGATE SWITCH	Not Necessary	188.55 FL	*- FL
35	1		*TAILGATE WEATHERSTRIP	Deformed	404.00 FL	*329.10 FL
36	1		*SET TAILGATE STOPPERS	Not Necessary	36.40 FL	*- FL
37	1		*TAILGATE INNER TRIM BOARD	Mtg Broken	528.20 FL	*485.50 FL
38	1		*TAIL LAMP LH/RH	O/S Cracked / N/SNot Necessary	1,345.20 FL	*441.90 FL
39	2		*TAIL LAMP PANEL LH/RH	Not Necessary	713.46 FL	*- FL
40	1		*REAR BUMPER	Dented	830.50 FL	*545.00 FL
41	2		*REAR BUMPER SIDE RETAINER LH/RH	Not Necessary	179.00 FL	*- FL
42	2		*REAR BUMPER REFLECTOR LH /RH	Not Necessary	193.80 FL	*- FL
43	1		*REAR END PANEL	Dented	890.60 FL	*645.20 FL
44	1		*REAR END PANEL TOP GARNISH	Mtg Deformed	332.96 FL	*265.30 FL
45	1		*REAR FLOOR PANEL	Dented	1,143.10 FL	*880.00 FL
46	1		*REAR FLOOR PANEL TOP BOARD	Not Necessary	562.90 FL	*- FL
47	1		*REAR FLOOR PANEL TOOL BOX	Not Necessary	350.27 FL	*- FL
48	2		*REAR FLOOR QUARTER PANEL LH/RH	Not Necessary	647.80 FL	*- FL
49	2		*REAR FENDER LH/RH	Not Necessary	2,677.18 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*REAR FENDER QUARTER GLASS MOULDING LH/RH	Not Necessary	858.40 FL	*- FL
51	1		*REAR FENDER INNER TRIM BOARD LH/RH	O/S Cracked	1,757.74 FL	*605.10 FL
52	1		*REAR EXHAUST PIPE	Not Necessary	1,198.87 FL	*- FL
53	1		*REAR EXHAUST MOUNTING	Not Necessary	81.50 FL	*- FL
54	1		*REAR EXHAUST HEAT SHIELD	Not Necessary	125.63 FL	*- FL
55	1		*SPARE TYRE BOLT	Not Necessary	297.28 FL	*- FL
56	1		*SPARE TYRE HOLDER	Not Necessary	315.00 FL	*- FL
57	1		*SPARE TYRE BRACKET	Not Necessary	229.00 FL	*- FL
58	1		*BONNET INNER TRIM CLIPS	Not Necessary	50.00 FS	*- FS
59	1		*HEAD LAMP CLIPS	Not Necessary	50.00 FS	*- FS
60	1		*LOWER FRONT GRILLE CLIPS	Necessary	50.00 FS	*15.00 FS
61	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
62	1		*FRONT BUMPER GRILLE CLIPS	Repeated	50.00 FS	*- FS
63	1		*FRONT BUMPER UNDER COVER CLIPS	Not Necessary	50.00 FS	*- FS
64	1		*COOLANT	Not Necessary	100.00 FS	*- FS
65	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
66	1		*TAILGATE WINDSCREEN DAMPING SEAL	Not Necessary	30.00 FS	*- FS
67	1		*TAILGATE CHROME GARNISH CLIPS	Not Necessary	50.00 FS	*- FS
68	1		*TAILGATE INNER TRIM BOARD CLIPS	Necessary	50.00 FS	*15.00 FS
69	1		*REAR BUMPER CLIPS	Necessary	50.00 FS	*20.00 FS
70	1		*REAR END PANEL SEALANT	Necessary	80.00 FS	*20.00 FS
71	1		*REAR END PANEL TOP GARNISH CLIPS	Necessary	50.00 FS	*15.00 FS
72	1		*REAR FLOOR PANEL SEALANT	Not Necessary	80.00 FS	*- FS
73	1		*REAR FENDER SEALANT	Not Necessary	80.00 FS	*- FS
74	1		*REAR FENDER INNER TRIM CLIPS	Necessary	50.00 FS	*15.00 FS
75	1		*REAR FENDER QUARTER GLASS SEALANT	Not Necessary	80.00 FS	*- FS
76	1		*REAR FENDER QUARTER GLASS DAMPING SEAL	Not Necessary	30.00 FS	*- FS
77	1		*FRONT & REAR NO.PLATE & CASING	Bent / Cracked	200.00 FS	*80.00 FS
78	1		*REVERSE CAMERA	Not Necessary	600.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	36,825.78	11,889.28
- List Item Discount on L Items 25.00/25.00% (S\$)	8,296.35	2,740.05
Total Parts (S\$)	28,529.43	9,149.23

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE ALL INTERIOR UPHOLSTERY ITEMS TO FACILITATE REPAIRS	New	500.00	80.00
2	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (FRONT)	New	2,000.00	600.00
3	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (FRONT)	New	2,000.00	600.00
4	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS (REAR)	New	2,000.00	700.00
5	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS (REAR)	New	2,000.00	800.00
6	TO TUFF COAT DAMAGED AREAS	New	300.00	40.00
7	TO RNR A/C CONDENSOR & REFILL GAS TO FACILITATE REPAIRS	New	200.00	120.00
8	TO RNR RADIATOR ASSY & REFILL COOLANT TO FACILITATE REPAIRS	New	200.00	0.00
9	TO RNR TAILGATE MECHANISM TO FACILITATE REPAIRS	New	200.00	60.00
10	TO RNR REVERSE CAMERA TO FACILITATE REPAIRS	New	150.00	0.00
11	TO RNR TAILGATE WINDSCREEN TO FACILITATE REPAIRS	New	300.00	120.00
12	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	New	200.00	0.00
13	TO RNR FUEL TANK FILLER PIPE TO FACILITATE REPAIRS	New	100.00	0.00
14	TO CHECK & REFIX ALL ELECTRICAL WIRINGS	New	200.00	30.00
15	TO RNR REAR EXHAUST & ATTACHMENT PARTS TO FACILITATE REPAIRS	New	300.00	60.00
16	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS ,RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	New	300.00	0.00
Gross Labour Cost (\$)			10,950.00	3,210.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >